WTCI-344-P

ORIGINAL

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower 1

Building No: 1 Floor: _____ Sample Size 4 oz, Vials

Description of Sampling Area: Elevator shafts' Zone I Local Cars.

Sample Numbers:

LL-752-WTC A-C, V	LL-758-A-C X V	LL-	LL-
LL-753-WTC-A-C V	LL-759-WTC-A-C X V	LL-	LL-
LL-754 WTC A-C, V	LL-	LL-	LL-
LL-755-WTC A-C, V	LL-	LL-	LL-
LL-756-WTC-A-C V	LL-	LL-	LL-
LL-757-WTC-A-C V	LL-	LL-	LL-

Form of Asbestos Material

- ___ Sprayed-On
- ___ Troweled-On/Cementitious
- ___ Plaster
- ___ Acoustical Plaster
- ___ Air Cell
- ___ Molded Sections/Pads
- ___ VAT
- ___ Ceiling Tile
- X Other: Hard coat

Location of Asbestos Material

- X Support Beams/Columns
- ___ Concrete Slab/Metal Decking
- ___ Cable
- ___ Duct/Breeching
- ___ Floors
- ___ Heating/Cooling Equiptment
- ___ Ceilings
- ___ Piping/Fittings
- ___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

1. Hard Encapsulating Spray over Fireproofing

Sample taken by: Neil George, Frank Perzola Date: 12-16-92

Persons Present Neil George, Frank Perzola of ALTF
Mario Rosa of National Elevator Service

Photographs Taken By: Neil George, Frank Perzola

Neil Monroe

Signature Neil George 12-16-92
DATE

SURVEYOR _____ JOB NUMBER Tsp 150

ORIGINAL

FACILITY One World Trade Cent
Local Elevator: Zone I

SAMPLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-752-WTC	Spray-on fireproofing and hard coat encapsulant collected From column #1 at the 15th floor. (Elevator Shaft - Pc-24,25,
LL-753-WTC	Spray-on Fireproofing and hard coat encapsulant collected fro Column #2 at the 2nd floor (Elevator Shaft Pc-24,25,26
LL-754-WTC	Spray-on ~~Fire~~proofing and hard coat encapsulant collected from column #1 at the 15th floor. (Elevator Shaft Pc-27,28,
LL-755-WTC	Spray-on fireproofing and hard coat encapsulant collected from column #2 at the 2nd floor (Elevator Shaft Pc 27,28,29
LL-756-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the ~~23~~ 23rd floor. (Elevator Shaft Pc-30,31,
LL-757-WTC	Spray-on fireproofing and hard coat encapsulant collected fr Column #2 at the 2nd floor. (Elevator Shaft Pc-30,31,32
LL-758-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 23rd floor (Elevator Shaft Pc-33,34
759-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 2nd floor. (Elevator Shaft Pc 33,34,35

ORIGINAL

12-16-11

1-WTC Elevator Shafts

Local Zone I



Figure 2.12 Plan View—Bank & Shuttle Elevator Locations Towers A & B, Concourse Level

ORIGINAL

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower 1

Building No: 1 Floor: _____ Sample Size 402 + VIALS

Description of Sampling Area: ELEVATOR SHAFTS ZONE I LOCAL & SHUTTLE CAR 22

X

Sample Numbers:

LL-760-WTC	LL-766-WTC A-C ✓	LL-	LL-
LL-761-WTC	LL-767-WTC A-C ✓	LL-	LL-
LL-762-WTC	LL-768-WTC A-C ✓	LL-	LL-
LL-763-WTC	LL-769-WTC A-C ✓	LL-	LL-
LL-764-WTC	LL-770-WTC A-C ✓	LL-	LL-
LL-765-WTC	LL-	LL-	LL-

Form of Asbestos Material	Location of Asbestos Material
X Sprayed-On	X Support Beams/Columns
___ Troweled-On/Cementitious	___ Concrete Slab/Metal Decking
___ Plaster	___ Cable
___ Acoustical Plaster	___ Duct/Breeching
___ Air Cell	___ Floors
___ Molded Sections/Pads	___ Heating/Cooling Equiptment
___ VAT	___ Ceilings
___ Ceiling Tile	___ Piping/Fittings
X Other: Hard Coat	___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

A. Hard Encapsulating Spray over Fireproofing

Sample taken by: Neil George, Frank Renzola Date: ~~12-17-91~~ 12.17.91

Persons Present Neil George, Frank Renzola of ALTF
MARIO ROCA of National Elevator Service

Photographs Taken By: Neil George, Frank Renzola

Name: Neil George Signature [signature] 12.18.91
DATE

SURVEYOR ______________________ JOB NUMBER Top 150

ORIGINAL

FACILITY One World Trade Cent.

.MPLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-760-WTC	Spray-on fireproofing and hard coat encapsulant collected fr Column #1 at the 30th floor. (Elevator Shaft Pc. 36,37
LL-761-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 2nd Floor. (Elevator Shaft Pc. 36,37,38
LL-762-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 31st Floor. (Elevator Shaft Pc. 39,40,4
LL-763-WTC	Spray-on fireproofing and hard coat encapsulant collected from column #1 at the 2nd floor. (Elevator Shaft Pc. 39,40,
LL-764-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 38th Floor (Elevator Shaft Pc. 42,43,4
LL-765-WTC	Spray-on fireproofing and hard coat encapsulant collected fr Column #1 at the 22nd floor. (Elevator Shaft Pc. 42,43,44
LL-766-WTC	Spray-on fireproofing and hard coat encapsulant collected fr Column #2 at the 2nd floor. (Elevator Shaft Pc. 42,43,44
-767-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 38th Floor. (Elevator Shaft Pc. 45,46,47
LL-768-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 22nd floor (Elevator Shaft Pc 45,46,47
LL-769-WTC	Spray-on fireproofing and hard coat encapsulant collected fr Column #2 at the 2nd Floor (Elevator Shaft Pc. 45,46,4

SURVEYOR _____ JOB NUMBER _____

ORIGINAL

FACILITY WTC-1
Shuttle Elevator
R-22-23

LE NUMBER	DESCRIPTION OF SAMPLING LOCATION
L-770-WTC	Spray-on fireproofing and hard coat encapsulant Sampled at the 76th floor off of car #22 from the column next to the entrance.



Figure 2.12 Plan View—Bank & Shuttle Elevator Locations Towers A & B, Concourse Level

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower

Building No: 1 Floor: _____ Sample Size 402, VIIA15

Description of Sampling Area: Elevator Shafts

Sample Numbers:

LL-782-WTC A-C XV	LL-788 WTC-A-C ✓	LL-	LL-
LL-783-WTC A-C ✓	LL-789 WTC-AC ✓	LL-	LL-
LL-784-WTC A-C ✓	LL-790 WTC-A-C ✓	LL-	LL-
LL-785-WTC A-C ✓	LL-791 WTC-A-C	LL-	LL-
LL-786-WTC A-C ✓	LL-	LL-	LL-
LL-787-WTC A-C ✓	LL-	LL-	LL-

Form of Asbestos Material

- X Sprayed-On
- ___ Troweled-On/Cementitious
- ___ Plaster
- ___ Acoustical Plaster
- ___ Air Cell
- ___ Molded Sections/Pads
- ___ VAT
- ___ Ceiling Tile
- X Other: HARD Coat

Location of Asbestos Material

- X Support Beams/Columns
- ___ Concrete Slab/Metal Decking
- ___ Cable
- ___ Duct/Breeching
- ___ Floors
- ___ Heating/Cooling Equiptment
- ___ Ceilings
- ___ Piping/Fittings
- ___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

A. HARD Coat Encapsulant over fluffy spray-on.

Sample taken by: Nel George, Frank Perzola Date: 12/19/91

Persons Present Nel George Frank Perzola & ALT

Mario Pacio & National Elevator Service

Photographs Taken By: Nel George - Frank Perzola

Signature _____ 12/23/91 DATE

SURVEYOR _____

JOB NUMBER Top-150

ORIGINAL

FACILITY One World Trade Ctr
Zone II Local Elevator Shafts

SAMPLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-782-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 53rd floor (Elevator Shaft Pe 51,52,5
LL-783-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 45th floor (Elevator Shaft Pe 51,54,5
LL-784-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 53rd floor. (Elevator Shaft Pe-54,55,56
LL-785-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 46th floor (Elevator Shaft Pe 54,55,5
LL-786-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 60th floor. (Elevator Shaft Pe-60,61,62,
LL-787-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 45th floor. (Elevator Shaft Pe-60,61,62)
LL-788-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 65th floor. (Elevator Shaft Pe-6 6t,6
-789-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 45th floor. (Elevator Shaft Pe-63,64,65
LL-790-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #1 at the 66th floor. (Elevator Shaft Pe-66,67,68.)
LL-791-WTC	Spray-on fireproofing and hard coat encapsulant collected from Column #2 at the 46th floor (Elevator Shaft Pe-66,67,68)

12 - 19 - 92
One World Trade Center
Zone II Local Elevators

ORIGINAL

SKYLOBBY 44th FLOOR—
CARS NOS. 51-74
FOR FLOORS 44-74





LEGEND

6 —— FIRE DEPARTMENT KEY OPERATED SWITCH

←→ —— PASSENGER MOVEMENT

Figure 2.13 Plan View—Bank & Shuttle Elevator Locations Towers A & B, Skylobby 44th Floor

Port Authority of N.Y and N.J.
Litigation Sampling Program

ORIGINAL

JOB NUMBER _____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower I

Building No: _____ ~~Floor~~: Shuttle CARS Sample Size 4OZ, VIAL

Description of Sampling Area: 44 CAR Elevator Shaft

PE-1&2

Sample Numbers:

LL-824 WTC A-C,V	LL-	LL-	LL-
LL-825 WTC A-C,V	LL-	LL-	LL-
LL-826 WTC A-C	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-

Form of Asbestos Material	Location of Asbestos Material
X Sprayed-On	X Support Beams/Columns
___ Troweled-On/Cementitious	___ Concrete Slab/Metal Decking
___ Plaster	___ Cable
___ Acoustical Plaster	___ Duct/Breeching
___ Air Cell	___ Floors
___ Molded Sections/Pads	___ Heating/Cooling Equiptment
___ VAT	___ Ceilings
___ Ceiling Tile	___ Piping/Fittings
___ Other:	___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

Hard Encapsulant applied over spray-on.

Sample taken by: Neil George, Mike Anton Date: 3/30/92

rsons Present Mario Roca National Elevator Service

Photographs Taken By: Neil George

Name: Neil George Signature Neil George 4-7-92

SURVEYOR _____ JOB NUMBER _____

ORIGINAL FACILITY _____

PLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
304-WTC	Spray on fireproofing & Hard Encapsulant Sampled from (36"x12") Column. Sample collected from 44th Floor, Column No. 1, Core pe-1
L-825-WTC	Spray on fireproofing & Hard Encapsulant Sampled from (36"x12") Column Sample Collected from 21st floor, Column No 2, Core pe-2
LL-826-WTC	Spray on fireproofing & Hard Encapsulant Sample from (36"x12") Column. Sample collected from 3rd floor, Column No 2, Core pe-2.


N
(TOWER A)
N
(TOWER B)
FREIGHT ELEVATORS
SHUTTLE ELEVATORS
TO 44th FLOOR
SKYLOBBY
SHUTTLE ELEVATORS
TO 78th FLOOR
SKYLOBBY
LL-323-WTC (21ST Floor)
LL-326-WTC (3rd Floor)
LL 324-WTC (44 Floor)
Northeast column (1)
Northwest column (2)


World Trade Center
Tower-1
Elevator Shaft
LL-756-WTC
12-16-91




LL-764-VTC
12-17-91




WORLD TRADE CENTER
TOWER-1
ELEVATOR SHAFT
LL-770-WTC
12-17-91


WORLD TRADE CENTER
TOWER-1
ELEVATOR SHAFT
LL-770-WTC
12-17-91


World Trade Center
Elevator Shafts
LL-783 WTC
12-1991


World Trade Center
Elevator Shafts
LL-783 WTC
12-1991


World Trade Center
LL-790 WTC
12-1991


World Trade Center
Elevator Shafts
LL-790 WTC
12-1991


World Trade Center
Tower I
Elevator Shaft.
L- 826 - WTC
3-30-92


Trade Center
I
Shaft.
826 - WTC
3-30-92

ORIGINAL



SCHEMATIC SECTION
TOWER A RISER DIAGRAM
ZONE I-LOCAL ELEVATORS

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ZONE I RISER
BANKS A, B, C, D
MACHINE ROOM PLANS

ORIGINAL



KEY TO SYMBOLS

SCHEMATIC SECTION
TOWER 'A' RISER DIAGRAM
ZONE II LOCAL ELEVATOR

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ORIGINAL



SCHEMATIC SECTION
SHUTTLE ELEVATORS
NOT TO SCALE

THE WORLD TRADE CENTE
THE PORT OF NEW YORK AUTHORITY

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER_____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower II

Building No: II Floor: Zone II Sample Size 4 OZ, VIAL

Description of Sampling Area: Elevator Shafts

CAR 68, CAR 57, CAR 56

Sample Numbers:

LL-827-WTC A-C, ✓ LL-_____	LL-_____	LL-_____
LL-828 WTC A-C, ✓ LL-_____	LL-_____	LL-_____
LL-829 WTC A-C, ✓ LL-_____	LL-_____	LL-_____
LL-830 WTC A-C, ✓ LL-_____	LL-_____	LL-_____
LL-831 WTC A-C, ✓ LL-_____	LL-_____	LL-_____
LL-832 WTC A-C ✓ LL-_____	LL-_____	LL-_____

Form of Asbestos Material	Location of Asbestos Material
X Sprayed-On	X Support Beams/Columns
___ Troweled-On/Cementitious	___ Concrete Slab/Metal Decking
___ Plaster	___ Cable
___ Acoustical Plaster	___ Duct/Breeching
___ Air Cell	___ Floors
___ Molded Sections/Pads	___ Heating/Cooling Equiptment
___ VAT	___ Ceilings
___ Ceiling Tile	___ Piping/Fittings
___ Other:	___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

Hard Encapsulant applied over spray on.

Sample taken by: Neil George, Mike Antol Date: 3/30/92

Persons Present Mario Roca - National Elevator Service

Photographs Taken By: Neil George

Name: Neil George Signature Neil George 4-7-92

SURVEYOR _____ JOB NUMBER _____

FACILITY _____ ORIGINAL

CE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-827-WTC	Spray on fireproofing & Encapsulant mat'l Sampled from a (52") I-Column. Samples Collected from the 60th Floor, Column No. #1 CAR pe-68
LL-828-WTC	Spray on fireproofing & Encapsulant mat'l Sampled from a (52") I-Column. Samples Collected from the 45th Floor, Column No #2, CAR pe-68
LL-829-WTC	Spray-on fireproofing & Encapsulant mat'l Sampled from a (52") I-Column. Samples Collected from the 60th floor, Column No #1, CAR pe-57
LL-830-WTC	Spray-on fireproofing & Encapsulant mat'l Sampled from a (52") I-Column. Samples Collected from the 45th floor, Column No #2, CAR pe-57

SURVEYOR _____ JOB NUMBER _____

FACILITY _____

ORIGINAL

LE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-831-WTC	Spray-on fire proofing & Encapsulant mat'l Sampled from a (52") I-column Samples collected from the 54th floor, column 10*2, CAR pe-56
LL-832-WTC	Spray-on fireproofing & Encapsulant mat'l Sampled from a (52") I-column Samples collected from the 45th floor, column 10*1, CAR pe-56



Figure 2.13 Plan View—Bank & Shuttle Elevator Locations Towers A & B, Skylobby 44th Floor

ORIGINAL

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: The World Trade Center Building: Tower Two

Building No: 2 Floor: B-2 Thru 44 Sample Size 4oz., Vial

Description of Sampling Area: 2-WTC Shuttle elevator Shaft (1-44) fo
Cars PE-10B, PE-11B.

Sample Numbers:

LL-851-WTC-A-G,V	LL-	LL-	LL-
LL-852-WTC-A-G,V	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-

Form of Asbestos Material

- ✓ Sprayed-On
- ___ Troweled-On/Cementitious
- ___ Plaster
- ___ Acoustical Plaster
- ___ Air Cell
- ___ Molded Sections/Pads
- ___ VAT
- ___ Ceiling Tile
- ___ Other:

Location of Asbestos Material

- ✓ Support Beams/Columns
- ___ Concrete Slab/Metal Decking
- ___ Cable
- ___ Duct/Breeching
- ___ Floors
- ___ Heating/Cooling Equiptment
- ___ Ceilings
- ___ Piping/Fittings
- ___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)
The material was encapsulated with a distinct, hard outer coat that is fairly thin yet detectable. This material was included in our samples.

Sample taken by: Frank Pergola Date: 4-2-92

Persons Present Frank Pergola, P.A. Asbestos Litigation Task Force, Chris Frizzell Asbestos Management Division (PA.), Mario Roca National Elevator

Photographs Taken By: Frank Pergola

4-7-92

SURVEYOR Frank Pergola

JOB NUMBER

ORIGINAL

FACILITY The World Trade Center

MPLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-851-WTC	Fluffy - Sprayed on Fireproofing material collected from the North West column at the 21st floor.
LL-852-WTC	Fluffy sprayed - on Fireproofing material collected from + NorthWest column at the 2nd floor. X




LL-85 : WTC
4-2-12


World Trade Center
Tower II
ELEVATOR SHAFT
LL - 857 - WTC
4-2-92




World Trade Center
Tower II
Elevator Shaft
LL - 827 - WTC


World Trade Center
Tower I


World Trade Center
Tower I
Elevator Shaft
LL- 831 -WTC
3-30-92


World Trade Center
Tower II
Elevator Shaft
LL- 831 -WTC
3-30-92


World Trade Center
Tower 2 Elevator Shaft
LL-849-WTC
4-1-92


World Trade Center
Tower 2 Elevator Shaft
LL-849-WTC
4-1-92



SCHEMATIC SECTION
TOWER 'B' RISER DIAGRAM
ZONE I-LOCAL ELEVATORS

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ZONE I - RISER
BANKS 'A' AT

E-2-3



SCHEMATIC SECTION
TOWER II - RISER DIAGRAM
ZONE II LOCAL ELEVATOR
NO SCALE

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ZONE II - RISER
BANK A & B SECONDARY
MACHINE ROOM PLANS



SCHEMATIC SECTION
TOWER 'A' RISER DIAGRAM
ZONE I - LOCAL ELEVATORS

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ZONE I - RISER
BANKS 'A' & 'B'

E-8-3



SCHEMATIC SECTION
TOWER A RISER DIAGRAM
ZONE II LOCAL ELEVATOR

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY

ZONE II - RISER
BANK A ED SECONDARY

SCHEMATIC SECTION
SHUTTLE ELEVATORS
NOT TO SCALE

THE WORLD TRADE CENTER
THE PORT OF NEW YORK AUTHORITY



Figure 2.12 Plan View—Bank & Shuttle Elevator Locations Towers A & B, Concourse Level

ORIGINAL

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: World Trade Center Building: Tower II

Building No: 2 Floor: Zone I Sample Size 4 OZ, VIAL

Description of Sampling Area: Elevator Shaft

PE-CAR 42 X

Sample Numbers:

LL- 857-WTC-AC,V	LL-	LL-	LL-
LL- 858 WTC AC,V	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-
LL-	LL-	LL-	LL-

Form of Asbestos Material		Location of Asbestos Material	
X	Sprayed-On	X	Support Beams/Columns
____	Troweled-On/Cementitious	____	Concrete Slab/Metal Decking
____	Plaster	____	Cable
____	Acoustical Plaster	____	Duct/Breeching
____	Air Cell	____	Floors
____	Molded Sections/Pads	____	Heating/Cooling Equiptment
____	VAT	____	Ceilings
____	Ceiling Tile	____	Piping/Fittings
____	Other:	____	Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

HARD ENCAPSULANT applied over spray-on

Sample taken by: Neal George, Mike Anton Date: 4-3-92

Persons Present MARIO ROCA & National Elevator Service

Photographs Taken By: Neal George

Name: Neal George Signature Neal George 4-7-92

SURVEYOR _____ JOB NUMBER _____

FACILITY _____

ORIGINAL

PLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-857-WTC	Spray on fireproofing & Encapsulant mat'l sampled from a (52") I-Colum. Samples collected from the 39th floor, Colmn No. 2 CAR-PE-42.
LL-858-WTC	Spray on fireproofing & Encapsulant mat sampled from a 36"x12" Colmn. Samples collected from the 3rd floor, Colmn No 1 CAR PE-42.

ORIGINAL

South East Column I
South West Column II

North EAST Column (1)
North WEST Column (2)



ORIGINAL

Port Authority of N.Y and N.J.
Litigation Sampling Program

JOB NUMBER _____

Sample Area Data Sheet

Facility: The World Trade Center Building: Tower Two

Building No: 2 Floor: _____ Sample Size 4oz., Vial

Description of Sampling Area: elevator shafts in 2-WTC Locals Zone 1 North shaft Bank "B" (PE-30), South Shaft Bank "B" (PE-35), North Shaft Bank "A" (PE-24)

Sample Numbers:

LL-845-WTC-A-C,V	LL-_____	LL-_____	LL-_____
LL-846-WTC-A-C,V	LL-_____	LL-_____	LL-_____
LL-847-WTC-A-C,V	LL-_____	LL-_____	LL-_____
LL-848-WTC-A-C,V	LL-_____	LL-_____	LL-_____
LL-~~849-WTC-A-C,V~~	LL-_____	LL-_____	LL-_____
-850-WTC-A-C,V	LL-_____	LL-_____	LL-_____

Form of Asbestos Material

- ✓ Sprayed-On
- ___ Troweled-On/Cementitious
- ___ Plaster
- ___ Acoustical Plaster
- ___ Air Cell
- ___ Molded Sections/Pads
- ___ VAT
- ___ Ceiling Tile
- ___ Other:

Location of Asbestos Material

- ✓ Support Beams/Columns
- ___ Concrete Slab/Metal Decking
- ___ Cable
- ___ Duct/Breeching
- ___ Floors
- ___ Heating/Cooling Equiptment
- ___ Ceilings
- ___ Piping/Fittings
- ___ Other:

Comments: (Indicate any unique characteristics of the material which may help identify the manufacturer.)

The material was encapsulated with a distinct, detectable hard outer coat that is included in our samples.

Sample taken by: Frank Pergola Date: 4-1-92

Persons Present Frank Pergola PA Asbestos Litigation Task Force, Mario Roca National Elevator

Photographs Taken By: Frank Pergola

4-7-92

SURVEYOR Frank Pirgola

OR...NAL

JOB NUMBER

FACILITY The World Trade C. 2-WTC

SAMPLE NUMBER	DESCRIPTION OF SAMPLING LOCATION
LL-845-WTC.	Fluffy spray-on fireproofing material collected from th NorthEast column in the North Shaft of Bank "B" Local elevators Zone I at the 23rd floor
LL-846-WTC	fluffy spray-on fireproofing material collected from NorthWest column in the same shaft as LL-845- at the 2nd floor.
LL-847-WTC	Fluffy spray-on fireproofing material collected from the SothEast column in the South shaft of Bank "B" local elevators Zone I taken at the 23rd floor.
LL-848-WTC	fluffy Spray-on fireproofing material collected from the Sou West column in the same shaft as LL-847-WTC a the 3rd floor
LL-849-WTC	Fluffy Spray-on fireproofing material collected from th NorthEast column of the North Shaft of Bank". local elevator Zone I taken at the 16th floor
LL-850-WTC	Fluffy spray-on Fireproofing material collected from NorthWest column in the same shaft as LL-849- at the 2nd

ORIGIN.

COMMENTS **Job Number**_____

1. The fluffy material was encapsulated with a distinct har outer coat that is somewhat thin yet detectable. Th material was included in : ours (7) samples.

2. The samples were taken in 2-WTC, local Zone I elevators by riding the tops of ca of PE-24, PE-30, PE-35 respectively.

ORIGINAL


(TOWER A)
N
CONCOURSE-
CARS NOS. 24-47
FOR FLOORS 9-40
SHUTTLE ELEVATORS
TO SKYLOBBY
78th FLOOR
TO
SKYLOBBY
78th FLOOR
TO
SKYLOBBY
44th FLOOR
TO
SKYLOBBY
44th FLOOR
23
22
21
20
19
18
17
16
15
14
13
12
1
2
3
4
5
48
6
7
8
9
10
11
BANK A
FLOORS 9-16
CARS NOS. 24-29
BANK B
FLOORS 17-24
CARS NOS. 30-36
BANK D
FLOORS 33-40
CARS NOS. 42-47
BANK C
FLOORS 25-32
CARS NOS. 36-41
North West Column
North East Column
North Shaft Bank "A"
LEGEND
REVOLVING DOOR
SWING DOOR
FIRE DEPARTMENT KEY OPERATED SWITCH
PASSENGER MOVEMENT


ORIGINAL
(TOWER A)
N
CONCOURSE-
CARS NOS. 24-47
FOR FLOORS 9-40
SHUTTLE ELEVATORS
TO SKYLOBBY
78th FLOOR
44th FLOOR
BANK A
FLOORS 9-16
CARS NOS. 24-29
BANK B
FLOORS 17-24
CARS NOS. 30-35
BANK C
FLOORS 25-32
CARS NOS. 36-41
BANK D
FLOORS 33-40
CARS NOS. 42-47
N.W. Column
N.E. Column
North Shaft of Bank "B"
LEGEND
REVOLVING DOOR
SWING DOOR
FIRE DEPARTMENT KEY OPERATED SWITCH
PASSENGER MOVEMENT


ORIGINAL
(TOWER A)
N
CONCOURSE–
CARS NOS. 24-47
FOR FLOORS 9-40
SHUTTLE
ELEVATORS
TO
SKYLOBBY
78th FLOOR
TO
SKYLOBBY
78th FLOOR
23
22
21
20
19
18
17
16
15
14
13
12
BANK
A
FLOORS
9-16
CARS NOS.
24-29
BANK
B
FLOORS
17-24
CARS NOS.
30-35
BANK
D
FLOORS
33-40
CARS NOS.
42-47
BANK
C
FLOORS
25-32
CARS NOS.
36-41
South
Shaft
Bank "B"
Local
Zone I
South
West
Column
South East
Column
SHUTTLE
ELEVATORS
TO
SKYLOBBY
44th FLOOR
TO
SKYLOBBY
44th FLOOR
1
2
3
4
5
48
6
7
8
9
10
11
LEGEND
REVOLVING DOOR
SWING DOOR
FIRE DEPARTMENT KEY OPERATED SWITCH
PASSENGER MOVEMENT

World Trade Center
Tower 2
Lt. 85
WTC
4-2-92





MATERIALS
ANALYTICAL
SERVICES

November 30, 1992

Mr. Kevin Bleach
The Port Authority of New York & New Jersey
One World Trade Center, 37E
New York, NY 10048

RE: World Trade Center Facility/Buildings 1 & 2

Dear Mr. Bleach:

The following is a list of surface treatment samples from the above referenced project in which we have identified the manufacturer of the asbestos containing material.

	Sample #	Manufacturer/Product
1.	LL-826 (Layer A)	Consistent with U.S. Mineral's Mark II
2.	LL-770 (Layer A)	
3.	LL-756 (Layer A)	
4.	LL-764 (Layer A)	
5.	LL-783 (Layer A)	
6.	LL-790 (Layer A)	
7.	LL-851 (Layer A)	
8.	LL-852 (Layer A)	
9.	LL-849 (Layer A)	
10.	LL-857 (Layer A)	
11.	LL-827 (Layer A)	
12.	LL-831 (Layer A)	

If you have any questions about our report, please do not hesitate to give me a call.

Sincerely,

William E. Longo, Ph.D.
President

WEL:lcj

Raleigh Office:
2418 Blue Ridge Road • Suite 105
Raleigh, North Carolina 27607
(919) 881-7708 • FAX (919) 881-8227

Atlanta Office:
3597 Parkway Lane • Suite 25
Norcross, Georgia 3009?
(404) 448-3300 • FAX (404) 3

MATERIALS ANALYTICAL SERVICES

MAS CHAIN-OF-CUSTODY

Client: PORT AUTHORITY OF NY & NJ

Contact: KEVIN BLEACH

Phone #: (212) 435-6145

Mas Job #: M8443

Date Recd: 5/13/92

Client PO: WORLD TRADE FAC/BLDG 1

BULK SAMPLE ANALYSIS

SAMPLE NUMBER(S)

1) LL-794-WTC-B
2) " 9 "
3) " 871 "
4) " 68 "
5) " 76 " A
6) " 26 "
7) " 770 "
8) " 756 "
9) " 64 " C
10) " 83 " B
11) LL-790-WTC-C
12)
13)
14)
15)
16)
17)
18)
19)
20)

Samples Relinquished By: KEVIN BLEACH

Samples Recd. By: [signature] Time: 2:00 PM

Condition of Samples: O.K.

Client Docs: 5 COVER LETTER (ORIG. IN M8424), 11 COC, UPS

Init File Rev:

Sample Prep by: Pam: J. Martin Date: 7/6/92

Sample Analysis: Pam: J. Martin Date: 7/6/92

Report(s) Sent: Date:

Sample(s) Ret. By: Date:

aleigh Office:
118 Blue Ridge Road • Suite 105
aleigh, North Carolina 27607
19) 881-7708 • FAX (919) 881-8227

Atlanta Office:
3597 Parkway Lane • Suite 250
Norcross, Georgia 30092
(404) 448-3200 • FAX (404) 368-87

MATERIALS ANALYTICAL SERVICES

MAS CHAIN-OF-CUSTODY

Client: PORT AUTHORITY OF NY & NJ

Contact: KEVIN BLEACH

Phone #: (212) 435-6145

Mas Job #: M8444

Date Recd: 5/13/92

Client PO: WORLD TRADE CENTER FAC/BLDG 2

BULK SAMPLE ANALYSIS

SAMPLE NUMBER(S)

1) LL-851-WTC-C	11)
2) " 2 " A	12)
3) " 49 "	13)
4) " 57 "	14)
5) " 27 "	15)
6) " 31 " B	16)
7)	17)
8)	18)
9)	19)
10)	20)

Samples Relinquished By: KEVIN BLEACH

Samples Recd. By: [signature] Time: 2:00 PM

Condition of Samples: O.K.

Client Docs: 5 COVER LETTER (ORIG. IN M8424), 6 COC, UPS

Init File Rev: _____

Sample Prep by: _____ Date: _____

Sample Analysis: _____ Date: _____

Report(s) Sent: _____ Date: _____

Sample(s) Ret. By: _____ Date: _____

Raleigh Office:
2418 Blue Ridge Road • Suite 105
Raleigh, North Carolina 27607
(919) 881-7708 • FAX (919) 881-8227

Atlanta Office:
3597 Parkway Lane • Suite 25
Norcross, Georgia 30092
(404) 448-3200 • FAX (404) 368

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8443 - 6A Date: 7/6/92

Project Name: Port Authority of NY&NJ Analyst: J. McC

Sample Identification: World Trade FAC/Bldg 7

LL - 826 - WTC - A

Gross Visual Description: Off-white, compressed wavy fibers bound in a fine grained matrix

Optical Data for Asbestos Identification				
Morphology	wavy			
Pleochroism	no			
Refractive Index	1.55x/1.54x			
Sign of Elongation	+			
Extinction	0			
Birefringence	low			
Melt	no			
Fiber Name	Chrysotile			

ASBESTOS MINERALS: Est. Vol. %

Chrysotile	40
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	60

fine grained aggregate

EFFERVESCENCE: Strong

COMMENTS: Layer A attached to Layer B very thin layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8443 - 7A Date: 7/6/92

Project Name: Port Authority of NY & NJ Analyst: J. McK

Sample Identification: World Trade FAC/Bldg 7
LL -770- WTC-A

Gross Visual Description: off-white, compressed wavy fibers bound in a fine grained matrix

Optical Data for Asbestos Identification			
Morphology	wavy		
Pleochroism	no		
Refractive Index	1.55/1.55+		
Sign of Elongation	+		
Extinction	0		
Birefringence	low		
Melt	no		
Fiber Name	Chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	40
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:	
Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:	
Perlite	
Vermiculite	
Other	
Binders	60
	fine grained aggregate

EFFERVESCENCE: Strong

COMMENTS: Layer A attached to Layer B Very thin Layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

roject # - Spl #: M8443 - 8A Date: 7/1/93

Project Name: Port Authority of NY & NJ Analyst: J McK

Sample Identification: World Trade Ctr / Bldg I

LL - 756 - WTC-A

Gross Visual Description: off-white, compressed wavy fibers bound in a fine grained matrix - off-white paint on one side

Optical Data for Asbestos Identification

Morphology	wavy		
Pleochroism	no		
Refractive Index	[illegible]		
Sign of Elongation	+		
Extinction	0		
Birefringence	low		
Melt	no		
Fiber Name	chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	40
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	60

fine grained aggregate

EFFERVESCENCE: ____ Long

COMMENTS: Layer A attached to Layer B Very thin layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

oject # - Spl #: M8443-9A Date: 7/1/93

roject Name: Port Authority of NY & NJ Analyst: J. McKi

ample Identification: World Trade FAc / Bldg 7

LL-764-WTC-A

ross Visual Description: off-white, compressed wavy fibers bound in a fine grained matrix

Optical Data for Asbestos Identification

Morphology	wavy		
Pleochroism	no		
Refractive Index	1.555/1.545		
Sign of Elongation	+		
Extinction	0		
Birefringence	low		
Melt	no		
Fiber Name	Chrysotile		

SBESTOS MINERALS: Est. Vol. %

rysotile 40
site
cidolite
remolite/Actinolite
nthophyllite

THER FIBROUS COMPONENTS:

lineral/Rock wool
ibrous glass
ellulose
ynthetic
ther

ION-FIBROUS COMPONENTS:

erlite
ermiculite
ther

inders 60

fine grained aggregate

FFERVESCENCE: Strong

MENTS:

Layer attached to Layer B Very thin Layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

roject # - Spl #: M8443 - 10 A Date: 7/6/92

Project Name: Port Authority of NY+NJ Analyst: J. McK

Sample Identification: World Trade FAC / Bldg I

LL-783 - WTC - B

Gross Visual Description: off-white, compressed wavy fibers bound in a fine grained matrix

Optical Data for Asbestos Identification				
Morphology	wavy			
Pleochroism	ND			
Refractive Index	1.555/1.545			
Sign of Elongation	+			
Extinction	0			
Birefringence	low			
Melt	ND			
Fiber Name	Chrysotile			

ASBESTOS MINERALS: Est. Vol. %

Chrysotile	40
mosite	
rocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	60

fine grained aggregate

EFFERVESCENCE: Strong

COMMENTS: Layer A attached to Layer B Very thin Layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

roject # - Spl #: M8443 - 11A Date: 7/6/92

Project Name: Port Authority of NY+NJ Analyst: J. McL

Sample Identification: World Trade FAC / Bldg 1

LL - 790 - WTC - C

Gross Visual Description: off-white, compressed wavy fibers bound in a fine grained matrix

Optical Data for Asbestos Identification

Morphology	wavy		
Pleochroism	ND		
Refractive Index	1.55-1.56		
Sign of Elongation	+		
Extinction	0		
Birefringence	low		
Melt	ND		
Fiber Name	Chrysotile		

ASBESTOS MINERALS: Est. Vol. %

Chrysotile 40
Amosite
Crocidolite
Tremolite/Actinolite
Anthophyllite

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool
Fibrous glass
Cellulose
Synthetic
Other

NON-FIBROUS COMPONENTS:

Perlite
Vermiculite
Other

Binders 60

fine grained aggregate

EFFERVESCENCE: Strong

COMMENTS: Layer A attached to Lay very thin Layer

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-1A Date: 10 July 92

Project Name: Port Authority of NY & NJ Analyst: S [illegible]

Sample Identification: World Trade Center Facility, Building 2

LL-851-WTC-C

Gross Visual Description: Thin lt. grey layer over fluffy off-white layer (B). Contains wispy white fibers / bundles in a fine grain matrix.

Optical Data for Asbestos Identification

Morphology	Wavy		
Pleochroism	Non Str		
Refractive Index	1.545 || 1.555		
Sign of Elongation	+		
Extinction	||		
Birefringence	low		
Melt	—		
Fiber Name	Chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	36
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	64

Carbonate, fine grain aggregate

EFFERVESCENCE: Strong

COMMENTS: No Starch Ob.

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-2A Date: 11 July 92

Project Name: Port Authority of NY & NJ Analyst: SJ

Sample Identification: World Trade Center Facility, Building 2
LL-852-WTC-A

Gross Visual Description: Thin lt. grey layer over fluffy off-white layer (B)
Contains wavy white fibers/bundles in a fine grain matrix. X

Optical Data for Asbestos Identification

Morphology	Wavy		
Pleochroism	None		
Refractive Index	1.545-1.555		
Sign of Elongation	+		
Extinction	||		
Birefringence	Low		
Melt			
Fiber Name	Chrysotile		

ASBESTOS MINERALS: **Est. Vol. %**

Chrysotile	38
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	62

Carbonate, fine grain aggregate 50

EFFERVESCENCE: Strong

COMMENTS: No Stards Ob.

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-3A Date: 11 July 92

Project Name: PORT AUTHORITY of NY & NJ Analyst: S [illegible]

Sample Identification: World Trade Center Facility, Building 2

LL-849-WTC-A

Gross Visual Description: ~~thin lt. gray/off white layer over fluffy off white layer~~ Contains wavy white fibers/bundles in a fine grain matrix.

Optical Data for Asbestos Identification			
Morphology	Wavy		
Pleochroism	None Ob		
Refractive Index	1.545 1.555		
Sign of Elongation	+		
Extinction	//		
Birefringence	low		
Melt			
Fiber Name	Chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	34
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:

Mineral/Rock Wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:

Perlite	
Vermiculite	
Other	
Binders	66

Carbonate, fine grain aggregate

EFFERVESCENCE: Strong

COMMENTS: No Starch Ob

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-4A Date: 11 July 92

Project Name: PORT AUTHORITY of NY & NJ Analyst: SFB

Sample Identification: World Trade Center Facility, Building 2

LL-857 - WTC - A

Gross Visual Description: Slight off white (lt. grey), thin, with wavy white fibers/ bundles in a fine grain matrix. Overlays fluffy off white layer (B).

Optical Data for Asbestos Identification			
Morphology	Wavy		
Pleochroism	None Obs.		
Refractive Index	1.545±1.555		
Sign of Elongation	+		
Extinction	//		
Birefringence	Low		
Melt			
Fiber Name	Chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	40
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:	
Mineral/Rock Wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:	
Perlite	
Vermiculite	
Other	
Binders	60

Carbonate, fine grain aggregate

EFFERVESCENCE: Strong

COMMENTS: No Starch Obs.

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-5A Date: 11July92

Project Name: Port Authority of NY & NJ Analyst: S F B

Sample Identification: World Trade Center Facility, Building 2

LL-827 - WTC - A

Gross Visual Description: White to very lt. grey, thin layer over fluffy off-white layer(B). Contains wavy white fibers/bundles in a fine grain matrix.

Optical Data for Asbestos Identification			
Morphology	Wavy		
Pleochroism	None		
Refractive Index	1.545-1.555		
Sign of Elongation	+		
Extinction	//		
Birefringence	low		
Melt	—		
Fiber Name	Chrysotile		

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	38
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:	
Mineral/Rock Wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:	
Perlite	
Vermiculite	
Other	
Binders	62

Carbonate, fine grain aggregate

EFFERVESCENCE: Strong

COMMENTS: No Starch Ob

MATERIALS ANALYTICAL SERVICES, INC.

BULK ASBESTOS SHEET

Project # - Spl #: M8444-6A Date: 11 July 92

Project Name: Port Authority of NY & NJ Analyst: SF

Sample Identification: World Trade Center Facility, Building 2
LL-831-WTC-B

Gross Visual Description: Thin grey layer over fluffy layer (D). Contains wavy white fibers/bundles in a fine grain matrix.

Optical Data for Asbestos Identification				
Morphology	Wavy			
Pleochroism	None			
Refractive Index	1.545/1.554			
Sign of Elongation	+			
Extinction	//			
Birefringence	Low			
Melt	—			
Fiber Name	Chrysotile			

ASBESTOS MINERALS:	Est. Vol. %
Chrysotile	37
Amosite	
Crocidolite	
Tremolite/Actinolite	
Anthophyllite	

OTHER FIBROUS COMPONENTS:	
Mineral/Rock Wool	
Fibrous glass	
Cellulose	
Synthetic	
Other	

NON-FIBROUS COMPONENTS:	
Perlite	
Vermiculite	
Other	
Binders	63

Carbonate, fine grain aggregate.

EFFERVESCENCE: Strong

COMMENTS: No Starch Ob

Box # W- 157

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler N George Sample Number LL-826-WTC-1 Date Sample Taken 3/30/92

Building Number/Name PE-2 Ele Shaft Facility WTC-1

Sample delivered and secured within sample storage room by: Nick George date/time 3/30/92 2300

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pegola date/time 3/31/92 0900

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: Ken Blank date/time 5/12/92 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory Jane K. Lyn/NAS date/time 5-13-92 2 PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Bo ALTF- 148

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler N. George Sample Number CC-770-WTC-A Date Sample Taken 12-17-91

Building Number/Name Elevator Facility WTC-1

Sample delivered and secured within sample storage room by: Wed Gorze date/time 12/18/91 24:00

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 12/20/91 1500

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [illegible] date/time 5/12/92 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [illegible]/MAS date/time 5-13-92 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box ALTF-14F

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler NGeorge Sample Number CL-756-WTC-A Date Sample Taken 12-16-91

Building Number/Name 1WTC Elevator Facility WTC-1

Sample delivered and secured within sample [illegible] Neil George date/time 12-16-91 22:30

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 12/17/91 1000

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [illegible] Blear 5/12/92 date/time 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [illegible] /MAS 5-13-92 date/time 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box # ALTF-

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

mpler N George Sample Number LC-7604-WTC-C Date Sample Taken 12·17·91

ilding Number/Name Elevator Facility WTC-1

mple delivered and cured within sample orage room by: [illegible] date/time 12·18·91 24:00

ceipt of sample knowledged by: _____ date/time _____

mple found to be intact and not mpered with: _____ Yes No _____

ceipt of sample knowledged and filed Sampling Team Manager: Frank Pergola date/time 12/20/91 1500

mple found to be intact d not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [illegible] date/time 5/12/92 7pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [illegible] /MAS date/time 5-13-92 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

mple Relinquished by: _____ date/time _____
Signature/Organization

mple Received by: _____ date/time _____ Reason _____
Signature/Organization

mple found to be intact d not tampered with: _____ Yes No _____

mple Relinquished by: _____ date/time _____
Signature/Organization

mple Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

BOX [illegible]

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

pler N George Sample Number LL-183-WTC-B Date Sample Taken 12/19/91

lding Number/Name Elevator - WTC-1 Facility WTC-1

ple delivered and ured within sample rage room by: Neil George date/time 12/19/91 2200

eipt of sample nowledged by: _____ date/time _____

ple found to be act and not pered with: _____ Yes No _____

[illegible] of sample [illegible]owledged and filed [illegible]mpling Team Manager: Frank Peyrolo date/time 12/20/91 1500

[illegible] to be int[illegible]: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: Fed Ex date/time 5/12/92 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY:

Sample Received by Analytical Laboratory: Jane K Gilmas date/time 5-13-92 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

ple Relinquished by: _____ date/time _____
Signature/Organization

ple Received by: _____ date/time _____ Reason _____
Signature/Organization

ple found to be intact not tampered with: _____ Yes No _____

ple Relinquished by: _____ date/time _____
Signature/Organization

ple Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box ALTF-

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler N George Sample Number LL-790-WTC-C Date Sample Taken 12/19/91

Building Number/Name Elevator WTC-1 Facility WTC-1

Sample delivered and secured within sample storage room by: Neil George date/time 12/19/91 2200

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 12/20/91 1500

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [illegible] date/time 5/12/92 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [illegible] /MAS date/time 5-13-92 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

_____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box # ALTF-_____

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler F. Pergola Sample Number LL-851-WTC-C Date Sample Taken 4-2-92

Building Number/Name Tower II / elevator shaft Facility WTC.

Sample delivered and secured within sample storage room by: Frank Pergola date/time 4-2-92/1300

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 4-3-92/1000

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: Ron Blank 5/12/92 date/time 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory Jane K Rollins 5-13-92 date/time 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

found to be intact
[illegible]: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box # ALTF- 158

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler F. Pergola Sample Number LL-852-WTC-A Date Sample Taken 4-2-92

Building Number/Name Tower II / elevator shaft Facility WTC

Sample delivered and secured within sample storage room by: Frank Pergola date/time 4-2-92/1300

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 4-3-92/1000

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [signature] 4/14/92 date/time 4PM

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [signature] 5-13-92 date/time 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box # ALTF- 158

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler F. Pergola Sample Number LL-849-WTC-A Date Sample Taken 4-1-92

Building Number/Name Tower II / elevator shaft Facility WTC

Sample delivered and secured within sample storage room by: Frank Pergola date/time 4-1-92/2300

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 4-3-92/1000

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [signature] date/time 5/11/92 4 pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY:

Sample Received by Analytical Laboratory [signature] date/time 5-13-92 2 PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Box # ALTF- 158

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler N Gloria Sample Number LL-857-WTC-A Date Sample Taken 4-2-92

Building Number/Name PS-43 Facility WTC-2

Sample delivered and secured within sample storage room by: [signature] date/time 4-2-92 22:00

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Perzla date/time 4-3-92/1000

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [signature] 5/12/92 date/time 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY:

Sample Received by Analytical Laboratory [signature/MAS] 5-13-92 date/time 2PM
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Box # ALTF- 157

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler D Yeager Sample Number L-827-WTC-A Date Sample Taken 3/30/92

Building Number/Name PE-6B Facility WTC-2

Sample delivered and secured within sample storage room by: D Yeager date/time 3/30/92 22:00

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pizzola date/time 3/31/92 0900

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: Ron Brooks 5/11/92 date/time 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory Jane K. Ryl/MAS 5-13-92 date/time 2pm
Signature/Organization

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

Box # ALTF-

The Port Authority of New York and New Jersey
Litigation Sampling
Chain of Custody

Sampler: N. Geaz Sample Number LL-B3+WTC-B Date Sample Taken 3/30/92

Building Number/Name PE-56 Facility WTC-2

Sample delivered and secured within sample storage room by: [signature] date/time 3/30/92 23:00

Receipt of sample acknowledged by: _____ date/time _____

Sample found to be intact and not tampered with: _____ Yes No _____

Receipt of sample acknowledged and filed by Sampling Team Manager: Frank Pergola date/time 3/31/92 0900

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample Mailed to Analytical Laboratory by: [signature] date/time 5/12/92 4pm

TO BE COMPLETED BY ANALYTICAL LABORATORY ONLY!

Sample Received by Analytical Laboratory [signature/Organization] date/time 5-13-92 2PM

Sample found to be intact and not tampered with: ✓ Yes No _____

Sample re-sealed by: _____ date/time _____

Sample mailed from Analytical Laboratory to Port Authority _____ date/time _____
Signature/Organization

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

Sample found to be intact and not tampered with: _____ Yes No _____

Sample Relinquished by: _____ date/time _____
Signature/Organization

Sample Received by: _____ date/time _____ Reason _____
Signature/Organization

WTC STORAGE ROOM

THE PORT AUTHORITY OF NY & NJ

One World Trade Center 68N
New York N Y 10048

Office of Senior
Litigation Counsel

Milton H Pachter
Senior Litigation Counsel
(212) 435-6815

December 31, 1992

Paul F. Slater, Esq.
Danaher Tedford Lagnese & Neal
3 New York Plaza - 14th Floor
New York, NY 10004

Re: Port Authority v. Allied - 91 Civ. 0310 (CLB)

Dear Paul:

Enclosed is a copy of the Longo report for fireproofing in full floors of WTC 001 and WTC 002.

Very truly yours,

Ezra I. Bialik
Office of Senior Litigation
Counsel - 68 North
(212) 435-6818

cc: All Counsel (without enclosures)

ASBESTOS MANAGEMENT DIVISION

POST-BASELINE BULK SAMPLING RESULTS

World Trade Center 5/14/92

~~Yonkers Industrial Park~~

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 102

SAMPLE NUMBER	LOCATION	RESULT
WTC-28183	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 403.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28184	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 403.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28185	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 400.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28186	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 400.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28187	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 409.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28188	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 357 AND 409.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28189	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 351 AND 409.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28190	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 351 AND 409.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28191	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 347 AND 411.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28192	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 347 AND 411.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28193	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 341 AND 402 OF	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28194	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 341 AND 402.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28195	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 309 AND 410.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28196	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 309 AND 410.	NON ASBESTOS SAMPLE DATE: 01/14/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 102

SAMPLE NUMBER	LOCATION	RESULT
WTC-28197	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 333 AND 404.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28198	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 333 AND 404.	NON ASBESTOS SAMPLE DATE: 01/14/91
WTC-28199	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 327 AND 408.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/14/91
WTC-28369	INSULATION COLLECTED FROM INSIDE CORE OF DOOR.	NON ASBESTOS SAMPLE DATE: 01/29/91
WTC-28370	INSULATION COLLECTED FROM INSIDE CORE OF DOOR.	NON ASBESTOS SAMPLE DATE: 01/29/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: OFFICE # 1845 & 1849
AREA DESCRIPTION: PERIMETER / MAIN AREA

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-28590	18"X18" CEILING TILE TAKEN FROM ROOM 1845 NORTH WEST OFFICE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28591	WHITE FLUFFY SPRAYED ON INSULATION COLLECTED FROM METAL DECK CEILING ABOVE CEILING TILE TAKEN FROM ROOM 1845.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28592	WHITE FLUFFY SPRAYED ON INSULATION COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING TILE COLLECTED FROM ROOM 1845.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28593	WHITE FLUFFY SPRAYED ON INSULATION COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING TILE COLLECTED FROM ROOM 1845.	60% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28594	WHITE POWDERY DRY WALL SAMPLE COLLECTED FROM THE WALL OF ROOM 1845 WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28595	WHITE POWDERY CONVECTOR INSULATION MATERIAL COLLECTED OFFICE 1849 ON WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28596	WHITE CEMENTITIOUS CONVECTOR INSULATION MATERIAL COLLECTED FROM OFFICE 1849 NORTH SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28597	WHITE CEMENTITIOUS CONVECTOR INSULATION MATERIAL COLLECTED FROM OFFICE 1849 NORTH SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28598	WHITE CEMENTITIOUS CONVECTOR INSULATION MATERIAL COLLECTED FROM OFFICE 1849 NORTH SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28599	MASTIC FOR 12"X12" FLOOR TILE COLLECTED FROM OFFICE 1849 IN MIDDLE OF ROOM.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28600	MASTIC FOR 12"X12" FLOOR TILE COLLECTED FROM OFFICE 1849 ON WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28601	MASTIC FOR 12"X12" FLOOR TILE COLLECTED FROM OFFICE 1849 ON EAST SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28602	INTERLOCKING CEILING TILE COLLECTED FROM OFFICE 1849 NEAR MIDDLE OF ROOM.	NON ASBESTOS SAMPLE DATE: 02/07/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: OFFICE AREAS
AREA DESCRIPTION: PERIMETER / MAIN AREA

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-28603	WHITE FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM OFFICE 1849 NEAR MIDDLE OF ROOM ON METAL CEILING.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28604	WHITE FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING IN OFFICE 1849 ON EAST SIDE.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28640	WHITE FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING IN OFFICE 1849 ON WEST SIDE.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28641	WHITE INTERLOCKING CEILING TILE COLLECTED FROM OFFICE 1829 ON SOUTH END OF ROOM.	NON ASBESTOS SAMPLE DATE: 02/07/91
WTC-28642	WHITE FLUFFY SPRAYED ON FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28643	WHITE FLUFFY SPRAYED ON FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28644	WHITE FLUFFY SPRAYED ON FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91
WTC-28645	WHITE FLUFFY SPRAYED ON FIREPROOFING INSULATION MATERIAL COLLECTED FROM METAL DECK CEILING ABOVE DROP CEILING.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 60

SAMPLE NUMBER	LOCATION	RESULT
WTC-28657	FLUFFY SPRAYED ON INSULATION COLLECTED FROM COLUMN 327.	NON ASBESTOS SAMPLE DATE: 02/08/91
WTC-28658	FLUFFY SPRAYED ON INSULATION COLLECTED FROM COLUMN 251.	NON ASBESTOS SAMPLE DATE: 02/08/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: COLUMNS # 501, 508, 1001, 1008

BUILDING: 1
FLOOR: 77

SAMPLE NUMBER	LOCATION	RESULT
WTC-29024	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1008 LOCATED IN THE SE QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29025	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1008 LOCATED IN THE SE QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29026	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 501 LOCATED IN THE NW QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29027	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 501 LOCATED IN THE NW QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29028	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1001 LOCATED IN THE SW QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29029	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1001 LOCATED IN THE SW QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29030	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 508 LOCATED IN THE NE QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29031	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 508 LOCATED IN THE NE QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 84

SAMPLE NUMBER	LOCATION	RESULT
WTC-28793	BLACK MASTIC ADHESIVE SAMPLE COLLECTED UNDER GRAY 12"X12" FLOOR TILE ON 84TH FLOOR NORTHEAST QUAD AT EAST COLUMN 16 AND NORTH COLUMN 8.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/15/91
WTC-28794	BLACK MASTIC ADHESIVE FROM UNDER GRAY 12"X12" FLOOR TILE ON 84TH FLOOR NORTHEAST QUAD AT EAST COLUMN 17 AND NORTH COLUMN 9.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/15/91
WTC-28795	BLACK MASTIC ADHESIVE SAMPLE COLLECTED UNDER 12"X12" GRAY FLOOR TILE ON 84TH FLOOR NORTHEAST QUAD EAST COLUMN 20 AND NORTH COLUMN 8.	NON ASBESTOS SAMPLE DATE: 02/15/91
WTC-28796	12"X12" GRAY FLOOR TILE COLLECTED ON 84TH FLOOR NORTHEAST QUAD AT EAST COLUMN 16 AND NORTH COLUMN 8.	NON ASBESTOS SAMPLE DATE: 02/15/91
WTC-28797	12"X12" BEIGE FLOOR TILE COLLECTED FROM UNDERNEATH LAYER OF GRAY TILE AT EAST COLUMN 20 AND NORTH COLUMN 8.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/15/91
WTC-28805	BLACK MASTIC UNDER BEIGE 12"X12" TILE AT EAST COLUMN 20 AND NORTH COLUMN 8.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/15/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 90

SAMPLE NUMBER	LOCATION	RESULT
WTC-28147	YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHEAST CORNER OF OFFICE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/10/91
WTC-28150	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHEAST CORNER OF OFFICE.	NON ASBESTOS SAMPLE DATE: 01/10/91
WTC-28151	YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHEAST SIDE OF OFFICE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/10/91
WTC-28152	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHEAST SIDE OF OFFICE.	NON ASBESTOS SAMPLE DATE: 01/10/91
WTC-28153	YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHWEST SIDE OF OFFICE.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/10/91
WTC-28154	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE COLLECTED FROM NORTHEAST SIDE OF OFFICE.	NON ASBESTOS SAMPLE DATE: 01/10/91
WTC-28155	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 143 AND 204.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/11/91
WTC-28156	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 143 AND 204.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28157	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 155 AND 204.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/11/91
WTC-28158	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 155 AND 204.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28159	YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 155 AND 213.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/11/91
WTC-28160	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 155 AND 213.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28161	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 151 AND 220.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28162	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 145 AND 219.	NON ASBESTOS SAMPLE DATE: 01/11/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 90

SAMPLE NUMBER	LOCATION	RESULT
WTC-28163	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 158 AND 226.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28164	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 158 AND 211.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28165	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 153 AND 211.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28166	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 148 AND 211.	NON ASBESTOS SAMPLE DATE: 01/11/91
WTC-28167	BLACK MASTIC FROM UNDER YELLOW 12"X12" FLOOR TILE AT INTERSECTION OF COLUMNS 200 AND 202.	NON ASBESTOS SAMPLE DATE: 01/11/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: COLUMNS # 501, 508, 1001, 1008

BUILDING: 1
FLOOR: 92

SAMPLE NUMBER	LOCATION	RESULT
WTC-29032	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 501 LOCATED IN THE NW QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29033	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 501 LOCATED IN THE NW QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29034	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1001 LOCATED IN THE SW QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29035	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1001 LOCATED IN THE SW QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29036	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1008 LOCATED IN THE SE QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29037	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 1008 LOCATED IN THE SE QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29038	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 508 LOCATED IN THE NE QUAD APPROXIMATELY 2' BELOW THE CEILING TILES.	NON ASBESTOS SAMPLE DATE: 03/14/91
WTC-29039	FLUFFY FIREPROOFING INSULATION MATERIAL COLLECTED FROM COLUMN 508 LOCATED IN THE NE QUAD APPROXIMATELY 2' ABOVE THE FLOOR.	NON ASBESTOS SAMPLE DATE: 03/14/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: STEAM METER ROOM
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B-6

SAMPLE NUMBER	LOCATION	RESULT
WTC-28659	CEMENTITIOUS FIREPROOFING COLLECTED FROM I-BEAM IN STEAM METER ROOM.	NON ASBESTOS SAMPLE DATE: 02/08/91
WTC-28660	CEMENTITIOUS FIREPROOFING COLLECTED FROM I-BEAM IN STEAM METER ROOM.	NON ASBESTOS SAMPLE DATE: 02/08/91
WTC-28661	WHITE INSULATION COLLECTED FROM OVERHEAD STEAM PIPE.	20% CHRYSOTILE ASBESTOS 55% AMOSITE ASBESTOS SAMPLE DATE: 02/08/91
WTC-28662	WHITE INSULATION COLLECTED FROM OVERHEAD STEAM PIPE.	60% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/08/91
WTC-28663	WHITE INSULATION COLLECTED FROM OVERHEAD STEAM PIPE RISER TEE JOINT.	NON ASBESTOS SAMPLE DATE: 02/08/91
WTC-28690	BLUE SPONGY INSULATION COLLECTED FROM DECK OF STEAM METER ROOM.	NON ASBESTOS SAMPLE DATE: 02/08/91
WTC-28691	WHITE INSULATION COLLECTED FROM STEAM PIPE RISER.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/08/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 85

SAMPLE NUMBER	LOCATION	RESULT
WTC-28893	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM SLANTED COLUMN WITHIN 10' OF COLUMN J-76/3 (BOTTOM).	NON ASBESTOS SAMPLE DATE: 02/25/91
WTC-28894	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM SLANTED COLUMN WITHIN 10' OF COLUMN J-76/3 (TOP).	NON ASBESTOS SAMPLE DATE: 02/25/91
WTC-28895	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM CEILING BETWEEN COLUMNS J-76/3 J-76/51.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/91
WTC-28896	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM CEILING BETWEEN COLUMNS J-76/3 J-76/51.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/91
WTC-28897	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM HORIZONTAL BEAM JUST ABOVE COLUMN J-76/51 (BOTTOM).	NON ASBESTOS SAMPLE DATE: 02/25/91
WTC-28898	FLUFFY OFF WHITE SPRAYED ON SURFACING MATERIAL COLLECTED FROM HORIZONTAL BEAM JUST ABOVE COLUMN J-76/51 (TOP).	NON ASBESTOS SAMPLE DATE: 02/25/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: I-BEAMS
AREA DESCRIPTION: TELEPHONE CLOSETS

BUILDING: 1
FLOOR: 102

SAMPLE NUMBER	LOCATION	RESULT
WTC-28211	FLUFFY INSULATION TAKEN FROM I-BEAM IN SOUTHEAST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28211	FLUFFY INSULATION COLLECTED FROM I-BEAM IN SOUTHEAST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28212	CEMENTITIOUS INSULATION COLLECTED FROM I-BEAM IN SOUTHEAST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28213	FLUFFY INSULATION COLLECTED FROM I-BEAM IN SOUTHEAST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28214	FLUFFY INSULATION COLLECTED FROM I-BEAM IN SOUTHWEST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28215	FLUFFY INSULATION COLLECTED FROM I-BEAM IN SOUTHWEST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91
WTC-28216	CEMENTITIOUS INSULATION COLLECTED FROM I-BEAM IN SOUTHWEST TELEPHONE CLOSET.	NON ASBESTOS SAMPLE DATE: 01/15/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B2-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25018	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" WIDE FLANGE BEAM LOCATED BETWEEN CARS 1 AND 2 AT THE TOP OF 44TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25019	FLUFFY INSULATION MATERIAL ON AN 18" WIDE FLANGE BEAM LOCATED ALONG THE EAST WALL AT THE TOP OF THE 44TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25020	FLUFFY INSULATION MATERIAL ON A 15" WIDE FLANGE BEAM LOCATED ALONG THE EAST WALL AT THE TOP OF THE 5TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25021	FLUFFY INSULATION MATERIAL SPRAYED ON A 15" WIDE FLANGE BEAM LOCATED ALONG THE EAST WALL AT THE TOP OF THE 11TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25022	FLUFFY INSULATION MATERIAL ON A 36" WIDE FLANGE COLUMN LOCATED IN THE NORTHEAST CORNER AT THE TOP OF THE 11TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25023	FLUFFY INSULATION MATERIAL SPRAYED ON A 15" WIDE FLANGE BEAM LOCATED AL ONG THE EAST WALL AT THE TOP OF THE 18TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25024	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" WIDE FLANGE COLUMN LOCATED IN THE NORTH EAST CORNER AT THE TOP OF THE 26TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25025	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" WIDE FLANGE BEAM LOCATED ALONG THE SOUTH WALL AT THE TOP OF THE 41ST FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25026	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 3RD FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25027	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 6TH FL.	2% CHRYSOTILE ASBESTOS
R-1WTC-25028	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 9TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25029	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 12TH FL	10% CHRYSOTILE ASBESTOS
R-1WTC-25030	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 15TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25031	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 18TH FL	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25032	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 21ST FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25033	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 24TH FL	5% CHRYSOTILE ASBESTOS
R-1WTC-25034	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 27TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25035	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED ALONG THE NORTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 30TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25036	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 33RD FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25037	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 36TH FL	5% CHRYSOTILE ASBESTOS
R-1WTC-25038	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 39TH FLOOR	NON ASBESTOS
R-1WTC-25039	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" COLUMN LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 1&2 AT THE TOP OF THE 42ND FL	10% CHRYSOTILE ASBESTOS
R-1WTC-25040	FLUFFY FALLOUT MATERIAL LOCATED ON TOP OF PASSENGER ELEVATOR CAR #2	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25000	FLUFFY FIREPROOFING MATERIAL FROM OUTER ENCAPSULATED LAYER SPRAYED ON 36" W.F. COLUMN LOCATED AT THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CARS 3&4 AT THE 32ND FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25001	FLUFFY FIREPROOFING MATERIAL FROM BENEATH ENCAPSULATED LAYER SPRAYED ON 36" W.F. COLUMN LOCATED AT THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CARS 3&4 AT THE 32ND FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25002	FLUFFY FIREPROOFING MATERIAL SPRAYED ON AN 18" BEAM LOCATED ALONG THE EAST WALL OF THE ELEVATOR SHAFT FOR CARS 3&4 AT THE BOTTOM OF THE 14 FL.	5% CHRYSOTILE ASBESTOS
R-1WTC-25003	FLUFFY FIREPROOFING MATERIAL SPRAYED ON A 36" W.F. COLUMN LOCATED IN THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CARS 3&4 AT THE BOTTOM OF FLOOR 14	5% CHRYSOTILE ASBESTOS
R-1WTC-25004	FLUFFY FIREPROOFING MATERIAL SPRAYED ON A 36" WIDE FLANGE COLUMN LOCATED AT THE TOP OF THE 22ND FLOOR, WITHIN THE ELEVATOR SHAFT FOR CARS 3&4	10% CHRYSOTILE ASBESTOS
R-1WTC-25005	CEMENTITIOUS INSULATION MATERIAL FROM AN 18" BEAM LOCATED IN THE ELEVATOR SHAFT FOR CARS 3&4 ALONG THE EAST WALL AT THE TOP OF THE 43RD FLOOR	NON ASBESTOS
R-1WTC-25006	FLUFFY UNDER COATING INSULATION MATERIAL FROM A 36" COLUMN LOCATED WITH IN ELEVATOR SHAFT FOR CARS PE 3&4 IN THE NORTHWEST CORNER AT THE TOP OF THE 3RD FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25007	CEMENTITIOUS OVERCOATING INSULATION MATERIAL FROM A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 3RD FLOOR	NON ASBESTOS
R-1WTC-25008	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 5TH FLOOR	NON ASBESTOS
R-1WTC-25009	FLUFFY UNDERCOAT INSULATION MATERIAL FROM A 36" COLUMN AND RAIL SUPPORT CONNECTION LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 5TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25010	FLUFFY AND CEMENTITIOUS INSULATION MATERIAL FROM THE 36" COLUMN AND 18" BEAM CONNECTION LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE9TH FLOOR	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25011	FLUFFY OVERSPRAY MATERIAL FROM THE FLOOR SLAB END LOCATED IN THE ELEVATOR SHAFTS FOR CARS PE3 & PE4 AT THE TOP OF THE 15TH FLOOR	NON ASBESTOS
R-1WTC-25012	PLASTER LIKE MATERIAL FROM A WALL LOCATED IN THE SOUTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 17TH FLOOR	NON ASBESTOS
R-1WTC-25013	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 19TH FLOOR.	NON ASBESTOS
R-1WTC-25014	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 26TH FLOOR.	NON ASBESTOS
R-1WTC-25015	FLUFFY OVERSPRAY MATERIAL FROM A CONCRETE FLOOR SLAB END LOCATED IN THE NORTH WEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3&4 AT THE BOTTOM OF THE 27TH FLOOR	NON ASBESTOS
R-1WTC-25016	FLUFFY INSULATION MATERIAL UNDER CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN & RAIL SUPPORT CONNECTION LOCATED IN NW CORNER OF ELEVATOR SHAFT FOR CARS PE3 & PE4 ATH THE TOPOF THE 34TH FLOOR	NON ASBESTOS
R-1WTC-25017	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN & RAIL SUPPORT CONNECTION LOCATED IN THE NORTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS PE3 & PE4 AT THE TOP OF THE 42ND FLOOR	NON ASBESTOS
R-1WTC-25059	FLUFFY FALLOUT MATERIAL LOCATED ON TOP OF ELEVATOR CAR PE3	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 003

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25440	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 24" COLUMN LOCATED ON THE NW CORNER OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 38TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25441	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 32ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25442	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 26TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25443	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 19TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25444	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 8TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25445	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE NW CORNER OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 6TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25446	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 24" COLUMN LOCATED ON THE NW CORNER OF THE ELEVATOR SHAFT FOR CAR #48 AT THE TOP OF THE 2ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25492	CEMENTITIOUS OUTERLAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 41ST FLOOR	NON ASBESTOS
R-1WTC-25493	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 17" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 36TH FL	NON ASBESTOS
R-1WTC-25494	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 30TH FLOOR	NON ASBESTOS
R-1WTC-25495	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 28TH FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25496	FLUFFY WHITE INNER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 28TH FLOOR	15% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 003

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25497	FLUFFY BROWN INNER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 28TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25498	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 17" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 21ST FLOOR	NON ASBESTOS
R-1WTC-25499	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 17" BEAM LOCATED ON EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 21ST FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25500	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 16TH FLOOR	NON ASBESTOS
R-1WTC-25501	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 16TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25502	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 14" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 11TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25503	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 7TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25504	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE N.E. CORNER OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 7TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25505	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 17" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 4TH FLOOR	NON ASBESTOS
R-1WTC-25506	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 17" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #5 AT THE TOP OF THE 4TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25507	FLUFFY FALLOUT INSULATION MATERIAL TAKEN FROM THE TOP OF CAR #5	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 005

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25060	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CARS PE8 & PE9 AT THE TOP OF THE 10TH FLOOR	45% CHRYSOTILE ASBESTOS
R-1WTC-25061	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CARS PE8 & PE9 AT THE TOP OF THE 14TH FLOOR	35% CHRYSOTILE ASBESTOS
R-1WTC-25062	FLUFFY INSULATION MATERIAL SPRAYED ON A 36" W.F. COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CARS PE8 & PE9 AT THE TOP OF 33RD FLOOR	NON ASBESTOS
R-1WTC-25063	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CARS PE8 & PE9 AT THE TOP OF THE 41ST FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25064	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP ELEVATOR CAR #8	50% CHRYSOTILE ASBESTOS
R-1WTC-25429	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON N.W. CORNER OF THE ELEVATOR SHAFT FOR CAR #9 AT TOP OF THE 1ST FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25430	FLUFFY FALLOUT INSULATION MATERIAL FROM A CENTER BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 2ND FLOOR	<1% CHRYSOTILE ASBESTOS
R-1WTC-25431	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 5TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25432	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON N.W. CORNER OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 10TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25433	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 15TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25434	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" BEAM LOCATED ON N.W. CORNER OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 20TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25435	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 25TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25436	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON NW CORNER OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 30TH FLOOR	10% CHRYSOTILE ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 005

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25437	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 35TH FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25438	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON N.W. CORNER OF ELEVATOR SHAFT FOR CAR #9 AT THE TOP OF THE 44TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25439	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR #9	2% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 006

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B2-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25041	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM ALONG THE EAST WALL OF CAR #10 AT THE TOP OF THE 5TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25042	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM ALONG THE EAST WALL OF CAR #10 AT THE TOP OF THE 16TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25043	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM ALONG THE EAST WALL OF CAR #10 AT THE TOP OF THE 24TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25044	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM ALONG THE EAST WALL OF CAR #10 AT THE TOP OF THE 36TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25045	FLUFFY INSULATION MATERIAL SPRAYED ON AN 18" W.F. BEAM ALONG THE SOUTH WALL OF CAR #10 AT THE TOP OF THE 41ST FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25046	FLUFFY FALLOUT MATERIAL LOCATED ON TOP OF CAR #10	45% CHRYSOTILE ASBESTOS
R-1WTC-25047	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER AT THE TOP OF THE 2ND FLOOR (CAR #11)	25% CHRYSOTILE ASBESTOS
R-1WTC-25048	FLUFFY INSULATION MATERIAL SPRAYED ON A 28" W.F. BEAM LOCATED ON WEST WALL OF CAR #11 AT THE TOP OF THE 6TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25049	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER AT THE TOP OF THE 10TH FLOOR (CAR #11)	40% CHRYSOTILE ASBESTOS
R-1WTC-25050	FLUFFY INSULATION MATERIAL SPRAYED ON A 24" W.F. BEAM LOCATED ON WEST WALL OF CAR #11 AT THE TOP OF THE 14TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25051	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER OF CAR #11 AT THE TOP OF THE 18TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25052	FLUFFY INSULATION MATERIAL SPRAYED ON A 24" W.F. BEAM LOCATED ON WEST WALL OF CAR #11 AT THE TOP OF THE 22ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25053	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER OF CAR #11 AT THE TOP OF THE 26TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25054	FLUFFY INSULATION MATERIAL SPRAYED ON A 24" W.F. BEAM LOCATED ON WEST WALL OF CAR #11 AT THE TOP OF THE 30TH FLOOR	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT #
SURVEY # 006

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B2-45

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25055	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER OF CAR #11 AT THE TOP OF THE 34TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25056	FLUFFY INSULATION MATERIAL SPRAYED ON A 24" W.F. BEAM LOCATED ON WEST WALL OF CAR #11 AT THE TOP OF THE 38TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25057	FLUFFY INSULATION MATERIAL SPRAYED ON A 42" W.F. COLUMN LOCATED IN N.W. CORNER OF CAR #11 AT THE TOP OF THE 42ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25058	FLUFFY FALLOUT MATERIAL LOCATED ON THE TOP OF CAR #11	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 007

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 82-80

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25200	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 2ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25201	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 27" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 8TH FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25202	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 42" COLUMN LOCATED IN THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 16TH FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-25203	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 15" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 24TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25204	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 42" W.F. COLUMN LOCATED IN THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 32ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25205	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 15" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 40TH FLOOR.	3% CHRYSOTILE ASBESTOS
R-1WTC-25206	CEMENTITIOUS TROWELED ON INSULATION MATERIAL FROM A 15" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 47TH FLOOR.	NON ASBESTOS
R-1WTC-25207	FLUFFY NON-ENCAPSULATED INSULATION MATERIAL FROM A 15" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 56TH FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25208	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" W.F. COLUMN LOCATED IN THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 64TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25209	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 30" W.F. BEAM LOCATED ALONG THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 74TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 007

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B2-80

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25210	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 15" W.F. BEAM LOCATED ALONG THE NORTH WALL OF THE ELEVATOR SHAFT FOR CARS 12 AND 13 AT THE TOP OF THE 75TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25211	FLUFFY FALLOUT MATERIAL LOCATED ON TOP OF ELEVATOR CAR PE 12.	5% CHRYSOTILE ASBESTOS
R-1WTC-25212	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 15" BEAM LOCATED ON THE NORTH WALL OF THE ELEVATOR SHAFT FOR CAR 12 AND 13 AT THE TOP OF THE 41ST FLOOR.	2% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 007

FACILITY: WORLD TRADE CENTER
LOCATION: LOCAL ELEVATOR
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 7 THROU PE 9

BUILDING: 5
FLOOR: 1-9

SAMPLE NUMBER	LOCATION	RESULT
R-5WTC 30026	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 30" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #PE-7 AT THE TOP OF THE 9TH FLOOR.	NON ASBESTOS
R-5WTC 30027	CEMENTITIOUS MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #PE-7 AT THE TOP OF THE 3RD FLOOR.	NON ASBESTOS
R-5WTC 30028	CEMENTITIOUS MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #PE-7 AT THE TOP OF THE 1ST FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 81-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25588	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR 17 AT THE TOP OF THE 78TH FLOOR.	NON ASBESTOS
R-1WTC-25589	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR 17 AT THE TOP OF THE 78TH FLOOR.	NON ASBESTOS
R-1WTC-25737	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 1ST FLOOR.	INCOMPLETE ASBESTOS
R-1WTC-25738	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 1ST FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25739	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 4TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25740	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 4TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25741	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 8TH FLOOR.	NON ASBESTOS
R-1WTC-25742	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 12TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25743	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 12TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25744	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 16TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25745	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 21ST FLOOR.	NON ASBESTOS
R-1WTC-25746	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 22ND FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25747	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 26TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25748	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 26TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25749	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 26TH FLOOR.	NON ASBESTOS
R-1WTC-25750	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVAOR SHAFT FOR CAR 17 AT THE TOP OF THE 29TH FLOOR.	NON ASBESTOS
R-1WTC-25751	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVAOR SHAFT FOR CAR 17 AT THE TOP OF THE 34TH FLOOR.	NON ASBESTOS
R-1WTC-25752	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 34TH FLOOR.	NON ASBESTOS
R-1WTC-25753	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 38TH FLOOR.	NON ASBESTOS
R-1WTC-25754	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-25755	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 46TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25756	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 46TH FLOOR.	NON ASBESTOS
R-1WTC-25757	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 51ST FLOOR.	NON ASBESTOS
R-1WTC-25758	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 51ST FLOOR.	<1% CHRYSOTILE ASBESTOS
R-1WTC-25759	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 56TH FLOOR.	NON ASBESTOS
R-1WTC-25760	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 56TH FLOOR.	NON ASBESTOS
R-1WTC-25761	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 57TH FLOOR.	NON ASBESTOS
R-1WTC-25762	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 57TH FLOOR.	NON ASBESTOS
R-1WTC-25763	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-25764	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-25765	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 66TH FLOOR.	NON ASBESTOS
R-1WTC-25766	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 66TH FLOOR.	NON ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25767	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 72ND FLOOR.	NON ASBESTOS
R-1WTC-25768	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 17 AT THE TOP OF THE 72ND FLOOR.	NON ASBESTOS
R-1WTC-25793	FLUFFY OVERSPRAY FIREPROOFING MATERIAL COLLECTED FROM THE NORTH WALL OF THE ELEVATOR SHAFT FOR CAR 16 AT THE BOTTOM OF THE 3RD FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25794	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25795	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 7TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25796	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 11TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25797	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 11TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25798	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 14TH FLOOR.	NON ASBESTOS
R-1WTC-25799	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 14TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25800	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 20TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25801	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 20TH FLOOR.	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25802	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT, FOR CAR 16 AT THE TOP OF THE 24TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25803	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 24TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25804	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 28TH FLOOR.	NON ASBESTOS
R-1WTC-25805	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 32ND FLOOR.	NON ASBESTOS
R-1WTC-25806	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 35TH FLOOR.	NON ASBESTOS
R-1WTC-25807	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 35TH FLOOR.	NON ASBESTOS
R-1WTC-25808	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 40TH FLOOR.	NON ASBESTOS
R-1WTC-25809	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 40TH FLOOR.	NON ASBESTOS
R-1WTC-25810	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 44TH FLOOR.	NON ASBESTOS
R-1WTC-25811	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 48TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25812	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 48TH FLOOR.	NON ASBESTOS
R-1WTC-25813	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 52ND FLOOR.	NON ASBESTOS
R-1WTC-25814	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 52ND FLOOR.	NON ASBESTOS
R-1WTC-25815	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 58TH FLOOR.	NON ASBESTOS
R-1WTC-25816	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 58TH FLOOR.	NON ASBESTOS
R-1WTC-25817	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 62ND FLOOR.	NON ASBESTOS
R-1WTC-25818	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 68TH FLOOR.	NON ASBESTOS
R-1WTC-25819	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS
R-1WTC-25820	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF 73RD FLOOR.	NON ASBESTOS
R-1WTC-25821	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 16 AT THE TOP OF THE 73RD FLOOR.	NON ASBESTOS
R-1WTC-25822	CEMENTITIOUS FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR 16.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25823	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM THE TOP OF CAR 16.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25642	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25616	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 77TH FLOOR.	NON ASBESTOS
R-1WTC-25617	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 74TH FLOOR.	NON ASBESTOS
R-1WTC-25618	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 74TH FLOOR.	NON ASBESTOS
R-1WTC-25619	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 69TH FLOOR.	NON ASBESTOS
R-1WTC-25620	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 69TH FLOOR.	NON ASBESTOS
R-1WTC-25621	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 64TH FLOOR.	NON ASBESTOS
R-1WTC-25622	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT, FOR CAR 18 AT THE TOP OF THE 64TH FLOOR.	NON ASBESTOS
R-1WTC-25623	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 59TH FLOOR.	NON ASBESTOS
R-1WTC-25624	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 59TH FLOOR.	NON ASBESTOS
R-1WTC-25625	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 54TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25626	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 54TH FLOOR.	NON ASBESTOS
R-1WTC-25627	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 46TH FLOOR.	NON ASBESTOS
R-1WTC-25628	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 46TH FLOOR.	NON ASBESTOS
R-1WTC-25629	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 3RD FLOOR.	NON ASBESTOS
R-1WTC-25630	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 3RD FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-25631	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 9TH FLOOR.	NON ASBESTOS
R-1WTC-25632	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 9TH FLOOR.	45% CHRYSOTILE ASBESTOS
R-1WTC-25633	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 15TH FLOOR.	NON ASBESTOS
R-1WTC-25634	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 15TH FLOOR.	45% CHRYSOTILE ASBESTOS
R-1WTC-25635	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 21ST FLOOR.	NON ASBESTOS
R-1WTC-25636	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 27TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25637	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF THE 27TH FLOOR.	35% CHRYSOTILE ASBESTOS
R-1WTC-25638	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM THE ELEVATOR SHAFT WALL LOCATED ON THE SOUTH WALL OF THE ELEVATOR SHAFT FOR CAR 18 AT THE THE TOP OF THE 30TH FLOOR.	NON ASBESTOS
R-1WTC-25639	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE MIDDLE OF THE 35TH FLOOR.	NON ASBESTOS
R-1WTC-25640	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE MIDDLE OF THE 35TH FLOOR.	NON ASBESTOS
R-1WTC-25641	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 18 AT THE TOP OF 41ST FLOOR.	NON ASBESTOS
R-1WTC-25670	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 2ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25671	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 2ND FLOOR.	45% CHRYSOTILE ASBESTOS
R-1WTC-25672	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 7TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25673	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25674	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 13TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25675	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 13TH FLOOR.	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25676	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 19TH FLOOR.	4% CHRYSOTILE ASBESTOS
R-1WTC-25677	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 19TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25678	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 24TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25679	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 24TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25680	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 29TH FLOOR.	NON ASBESTOS
R-1WTC-25681	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 35TH FLOOR.	NON ASBESTOS
R-1WTC-25682	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 35TH FLOOR.	NON ASBESTOS
R-1WTC-25683	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 42ND FLOOR.	NON ASBESTOS
R-1WTC-25684	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 42ND FLOOR.	NON ASBESTOS
R-1WTC-25685	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 75TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25686	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-25687	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 71ST FLOOR.	NON ASBESTOS
R-1WTC-25688	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 71ST FLOOR.	NON ASBESTOS
R-1WTC-25689	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 66TH FLOOR.	NON ASBESTOS
R-1WTC-25690	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 66TH FLOOR.	NON ASBESTOS
R-1WTC-25691	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 61ST FLOOR.	NON ASBESTOS
R-1WTC-25692	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-25693	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 56TH FLOOR.	NON ASBESTOS
R-1WTC-25694	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 51ST FLOOR.	NON ASBESTOS
R-1WTC-25695	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF 45TH FLOOR.	NON ASBESTOS
R-1WTC-25696	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 19 AT THE TOP OF THE 45TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25590	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 2ND FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25591	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 7TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25592	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 12TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25593	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 17TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25594	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 22ND FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25595	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 28TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25596	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 33RD FLOOR.	NON ASBESTOS
R-1WTC-25597	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 39TH FLOOR.	NON ASBESTOS
R-1WTC-25598	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-25599	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 46TH FLOOR.	NON ASBESTOS
R-1WTC-25600	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 50TH FLOOR.	NON ASBESTOS
R-1WTC-25601	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 55TH FLOOR.	<1% CHRYSOTILE ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 81-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25602	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 59TH FLOOR.	NON ASBESTOS
R-1WTC-25603	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 65TH FLOOR.	NON ASBESTOS
R-1WTC-25604	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 70TH FLOOR.	NON ASBESTOS
R-1WTC-25605	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-25606	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 21 AT THE TOP OF THE 78TH FLOOR.	NON ASBESTOS
R-1WTC-25607	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR 21.	NON ASBESTOS
R-1WTC-25854	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 3RD FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25855	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 8TH FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25856	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 14TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25857	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 20TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25858	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 25TH FLOOR.	NON ASBESTOS
R-1WTC-25859	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 30TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25860	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 36TH FLOOR.	NON ASBESTOS
R-1WTC-25861	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-25862	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 46TH FLOOR.	NON ASBESTOS
R-1WTC-25863	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 51ST FLOOR.	NON ASBESTOS
R-1WTC-25864	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE MIDDLE OF THE 57TH FLOOR.	NON ASBESTOS
R-1WTC-25865	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-25866	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 67TH FLOOR.	NON ASBESTOS
R-1WTC-25867	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE SOUTHWEST OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 72ND FLOOR.	NON ASBESTOS
R-1WTC-25868	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 20 AT THE TOP OF THE 77TH FLOOR.	NON ASBESTOS
R-1WTC-25869	FLUFFY FALLOUT FIREPROOFING MATERIAL COLLECTED FROM THE TOP OF CAR 20.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 012

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-79

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25224	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 2ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25225	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 26" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 8TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25226	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 44" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 25TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25227	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 35TH FLOOR.	3% CHRYSOTILE ASBESTOS
R-1WTC-25228	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 17" BEAM LOCATED ON THE NORTH WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 41ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25229	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 75TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25230	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR #23.	NON ASBESTOS
R-1WTC-25231	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 2ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25232	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25233	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 12TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25234	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 17TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 012

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-79

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25235	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 22ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25236	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 27TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25237	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 32ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25238	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 37TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25239	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 42ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25240	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 47TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25241	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 52ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25242	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 57TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25243	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 62ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25244	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 67TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 012

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-79

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25245	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 72ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25246	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CARS 22 AND 23 AT THE TOP OF THE 77TH FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25247	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR 22.	30% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25714	FLUFFY FALLOUT MATERIAL COLLECTED OFF THE TOP OF CAR 49.	NON ASBESTOS
R-1WTC-25715	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 70TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25716	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 66TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25717	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 62ND FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25718	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 62ND FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25719	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 58TH FLOOR.	NON ASBESTOS
R-1WTC-25720	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 58TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25721	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 54TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25722	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 50TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25723	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 49TH FLOOR.	<1% CHRYSOTILE ASBESTOS
R-1WTC-25724	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 44TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25725	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 42ND FLOOR.	20% CHRYSOTILE ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limi for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25726	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 41ST FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25727	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 37TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25728	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 33RD FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25729	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 29TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25730	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 25TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25731	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 20TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25732	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 15TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25733	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR ~~SHAFT~~ FOR CAR 49 AT THE TOP OF THE 10TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25734	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 8TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25735	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 6TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25736	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 49 AT THE TOP OF THE 2ND FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25824	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 34TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25825	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 1ST FLOOR.	NON ASBESTOS
R-1WTC-25826	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 1ST FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25827	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 5TH FLOOR.	NON ASBESTOS
R-1WTC-25828	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 5TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25829	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 7TH FLOOR.	NON ASBESTOS
R-1WTC-25830	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 12TH FLOOR.	NON ASBESTOS
R-1WTC-25831	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 12TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25832	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 17TH FLOOR.	NON ASBESTOS
R-1WTC-25833	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 17TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25834	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 22ND FLOOR.	NON ASBESTOS
R-1WTC-25835	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 22ND FLOOR.	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25836	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 27TH FLOOR.	NON ASBESTOS
R-1WTC-25837	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER FO THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 27TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25838	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 32ND FLOOR.	NON ASBESTOS
R-1WTC-25839	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 37TH FLOOR.	NON ASBESTOS
R-1WTC-25840	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-25841	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 44TH FLOOR.	NON ASBESTOS
R-1WTC-25842	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 50TH FLOOR.	NON ASBESTOS
R-1WTC-25843	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 55TH FLOOR.	NON ASBESTOS
R-1WTC-25844	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 60TH FLOOR.	NON ASBESTOS
R-1WTC-25845	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 65TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B1-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25846	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 70TH FLOOR.	NON ASBESTOS
R-1WTC-25847	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-25848	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 102ND FLOOR.	NON ASBESTOS
R-1WTC-25849	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH BEAM OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 97TH FLOOR.	NON ASBESTOS
R-1WTC-25850	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 93RD FLOOR.	NON ASBESTOS
R-1WTC-25851	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 88TH FLOOR.	NON ASBESTOS
R-1WTC-25852	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 84TH FLOOR.	NON ASBESTOS
R-1WTC-25853	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 50 AT THE TOP OF THE 84TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 014

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 9-16

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25480	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 1ST FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25481	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 4TH FLOOR.	35% CHRYSOTILE ASBESTOS
R-1WTC-25482	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 35" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 6TH FLOOR.	35% CHRYSOTILE ASBESTOS
R-1WTC-25483	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 8TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25484	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 10TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25485	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 13TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25486	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 35" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #24 AT THE TOP OF THE 15TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25487	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 2ND FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25488	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 4TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25489	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 9TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25490	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 12TH FLOOR.	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 014

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 9-16

SAMPLE NUMBER	LOCATION	RESULT
R-1UTC-25491	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 15TH FLOOR.	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 015

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-16

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25555	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 1ST FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25556	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 3RD FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25557	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 5TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25558	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 7TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25559	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR # 29 AT THE TOP OF THE 10TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25560	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 12TH FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-25561	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #29 AT THE TOP OF THE 15TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25562	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #25 AT THE TOP OF THE 2ND FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25563	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR #28 AT THE TOP OF THE 6TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25564	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #28 AT THE TOP OF THE 8TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25565	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #28 AT THE TOP OF THE 11TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 015

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-16

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25566	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR #28 AT THE TOP OF THE 13TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25567	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #28 AT THE TOP OF THE 16TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25568	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #27 AT THE TOP OF THE 16TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-25569	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #27 AT THE TOP OF THE 12TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25570	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #27 AT THE TOP OF THE 9TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25571	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #27 AT THE TOP OF THE 5TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25572	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #27 AT THE TOP OF THE 2ND FLOOR.	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 016

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-24

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25573	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 1ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25574	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 4TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25575	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 7TH FLOOR.	3% CHRYSOTILE ASBESTOS
R-1WTC-25576	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 10TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25577	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 13TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25578	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 16TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25579	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #30 AT THE TOP OF THE 19TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25580	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # 30 AT THE TOP OF THE 22ND FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25581	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 2ND FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25582	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 5TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25583	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 9TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 016

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-24

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25584	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 14TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25585	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 19TH FLOOR.	15% CHRYSOTILE ASBESTOS
R-1WTC-25586	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #31 AT THE TOP OF THE 23RD FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25587	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR #31.	20% CHRYSOTILE ASBESTOS
R-1WTC-25652	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 23RD FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25653	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 19TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25654	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 12TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25655	FLUFFY TROWELED ON MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 6TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25656	FLUFFY TROWELED ON MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 4TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25657	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR #32 AT THE TOP OF THE 1ST FLOOR.	40% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 017

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-24

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25608	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 1ST FL	10% CHRYSOTILE ASBESTOS
R-1WTC-25609	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 3RD FL	10% CHRYSOTILE ASBESTOS
R-1WTC-25610	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 6" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 6TH FL	25% CHRYSOTILE ASBESTOS
R-1WTC-25611	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 31" COLUMN LOCATED ON THE S.W. CORNER OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 9TH FL	25% CHRYSOTILE ASBESTOS
R-1WTC-25612	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 13TH FL	25% CHRYSOTILE ASBESTOS
R-1WTC-25613	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 16TH FL	35% CHRYSOTILE ASBESTOS
R-1WTC-25614	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT, FOR CAR #34 AT THE TOP OF THE 20TH FL	35% CHRYSOTILE ASBESTOS
R-1WTC-25615	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 23" COLUMN LOCATED ON THE S.W. CORNER OF THE ELEVATOR SHAFT FOR CAR #34 ON THE MIDDLE OF THE 24TH FL.	25% CHRYSOTILE ASBESTOS
R-1WTC-25644	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE S.W. CORNER OF THE ELEVATOR SHAFT FOR CAR #35 AT THE TOP OF THE 2ND FL	25% CHRYSOTILE ASBESTOS
R-1WTC-25645	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR #35 AT THE TOP OF THE 5TH FL	15% CHRYSOTILE ASBESTOS
R-1WTC-25646	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SODE OF THE ELEVATOR SHAFT FOR CAR #35 AT THE TOP OF THE 8TH FL	25% CHRYSOTILE ASBESTOS
R-1WTC-25647	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR #35 AT THE TOP OF THE 11TH FL	10% CHRYSOTILE ASBESTOS
R-1WTC-25648	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR #35 AT THE TOP OF THE 16TH FL	30% CHRYSOTILE ASBESTOS
R-1WTC-25649	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE S.W. CORNER OF THE ELEVATOR SHAFT, FOR CAR #35 AT THE TOP OF THE 17TH FL	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 017

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-24

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25650	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT, FOR CAR #35 AT THE TOP OF THE 20TH FL	5% CHRYSOTILE ASBESTOS
R-1WTC-25651	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT, FOR CAR #35 AT THE TOP OF THE 23RD FL	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-32

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25447	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 2ND FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25448	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" BEAM LOCATED ON SOUTH WEST CORNER OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 5TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25449	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 9TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25450	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 13TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25451	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 17TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25452	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 22ND FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25453	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" BEAM LOCATED ON SOUTH WEST CORNER OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 26TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25454	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 36 AT TOP OF 32ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25455	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 37" BEAM LOCATED ON SOUTHWEST CORNER OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 2ND FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25456	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 22" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 6TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25457	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 10TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25458	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 16TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25459	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 37" BEAM LOCATED ON SOUTHWEST CORNER OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 21ST FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25460	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 27TH FLOOR	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-32

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25461	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 37 AT TOP OF 29TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25462	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 31ST FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25463	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 26TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25464	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 21ST FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25465	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 16TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25466	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 6TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25467	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 38 AT TOP OF 4TH FLOOR	15% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 019

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-32

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25468	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 39 AT TOP OF 2ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25469	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 39 AT TOP OF 12TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25470	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON WEST SIDE OF ELEVATOR SHAFT FOR CAR # 39 AT TOP OF 25TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25471	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM THE TOP OF CAR # 39	10% CHRYSOTILE ASBESTOS
R-1WTC-25472	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 2ND FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25473	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON EAST SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 7TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25474	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON SOUTHEAST CORNER OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 11TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25475	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 15TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25476	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 19TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25477	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24"COLUMN LOCATED ON THE SOUTHEAST CORNER OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 23RD FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25478	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 27TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25479	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 41 AT THE TOP OF 31ST FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25706	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 21" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 1ST FLOOR	30% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 019

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-32

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25707	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE SOUTHEAST CORNER OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 3RD FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25708	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 9TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25709	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 13TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25710	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 17TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25711	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 21ST FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25712	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 25TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25713	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE SOUTHEAST CORNER OF ELEVATOR SHAFT FOR CAR # 40 AT THE TOP OF 30TH FLOOR	15% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 020

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25510	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 32" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 2ND FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25511	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 6TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25512	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 10TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25513	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 14TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25514	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 18TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25515	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 22ND FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25516	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 26TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25517	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 30TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25518	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 34TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25519	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 37TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25520	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 42 AT THE TOP OF 39TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25521	FLUFFY FALLOUT MATERIAL COLLECTED FROM TOP OF CAR # 42	5% CHRYSOTILE ASBESTOS
R-1WTC-25522	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 4" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 2ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25523	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 6TH FLOOR	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 020

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25524	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE S/W CORER OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 12TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25525	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 17TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25526	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 24" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 22ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25527	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 27TH FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25528	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 32ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25529	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 43 AT THE TOP OF 33RD FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25530	FLUFFY FALLOUT MATERIAL COLLECTED FROM TOP OF CAR # 43	30% CHRYSOTILE ASBESTOS
R-1WTC-25531	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 39TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25532	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 6" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 34TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25533	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 28TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25534	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 22ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25535	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 12TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25536	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 7TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25537	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 44 AT THE TOP OF THE 5TH FLOOR	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 021

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25538	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 1ST FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25539	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 6TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25540	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 11TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25541	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 17TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25542	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 25TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25543	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 31ST FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25544	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 35TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25545	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 46 AT THE TOP OF THE 39TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25546	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 46	15% CHRYSOTILE ASBESTOS
R-1WTC-25547	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 2ND FLOOR	35% CHRYSOTILE ASBESTOS
R-1WTC-25548	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 6TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25549	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 12TH FLOOR	40% CHRYSOTILE ASBESTOS
R-1WTC-25550	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 34" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 20TH FLOOR	<1% CHRYSOTILE ASBESTOS
R-1WTC-25551	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 27TH FLOOR	25% CHRYSOTILE ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 021

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 1-40

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25552	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 32ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25553	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 47 AT THE TOP OF THE 38TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25554	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 47	15% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 022

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-55

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25065	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" X 17" COLUMN LOCATED AT THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 54TH FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25066	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 53RD FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25067	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 52ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25068	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 51ST FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25069	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25070	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 48TH FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25071	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" X 17" COLUMN ON THE S/E SIDE OF ELEVATOR SHAFT FOR CAR # 51, TOP OF 46TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25072	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM TOP OF CAR # 51	3% CHRYSOTILE ASBESTOS
R-1WTC-25073	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR #52, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25074	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 40" X 18" COLUMN LOCATED ON S/E CORNER OF ELEVATOR SHAFT FOR CAR #52, TOP OF 52ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25075	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE SOUTH SIDE ELEVATOR SHAFT FOR CAR #52, TOP OF 50TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25076	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE ELEVATOR SHAFT FOR CAR #52, TOP OF 48TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25077	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST SIDE ELEVATOR SHAFT FOR CAR #52, TOP OF 46TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25078	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM TOP OF CAR # 52	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 022

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-55

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25079	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 53, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25080	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 53, TOP OF 52ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25081	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 53, TOP OF 50TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25082	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 53, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25083	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 53, TOP OF 46TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 023

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-55

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25084	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" X 8" FLANGE, ON THE NORTH WALL OF ELEVATOR SHAFT FOR CAR # 54, TOP OF 54TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25085	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 54, TOP OF 52ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25086	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" X 8" FLANGE, ON THE NORTH WALL OF ELEVATOR SHAFT FOR CAR # 54, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25087	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 54, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25088	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" X 8" FLANGE, LOCATED ON THE NORTH WALL OF ELEVATOR SHAFT FOR CAR # 54, TOP OF 46TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25089	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25090	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN, ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 53RD FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25091	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 52ND FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25092	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 53RD FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25093	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN, ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25094	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25095	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT FOR CAR # 55, TOP OF 46TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25096	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25097	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 53RD FLOOR	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 023

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-55

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25098	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN LOCATED ON THE S/W CONER OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 52ND FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25099	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" BEAM LOCATED ON THE NORTH WALL OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25100	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25101	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 46TH FLOOR	NON ASBESTOS
R-1WTC-25102	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN, LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 56, TOP OF 45TH FLOOR	3% CHRYSOTILE ASBESTOS.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 024

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-60

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25658	FLUFFY FIREPROOFING INSULATION COLLECTED FROM A 21" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 57, TOP OF 44TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25659	FLUFFY FIREPROOFING INSULATION COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 57, TOP OF 48TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25660	FLUFFY FIREPROOFING INSULATION COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 57, TOP OF 51ST FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25661	FLUFFY FIREPROOFING INSULATION COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 57, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25662	FLUFFY FIREPROOFING INSULATION COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 57, TOP OF 57TH FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-25663	FLUFFY FIREPROOFING INSULATION COLLECTED FROM A 21" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FORCAR # 57, TOP OF 61ST FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-26006	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 61ST FLOOR	10% CHRYSOTILE ASBESTOS
R-1WTC-26007	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN, LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 58TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-26008	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 55TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-26009	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 52ND FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-26010	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" COLUMN, LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 49TH FLOOR	35% CHRYSOTILE ASBESTOS
R-1WTC-26011	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 58, TOP OF 46TH FLOOR	40% CHRYSOTILE ASBESTOS
R-1WTC-26012	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT FOR CAR # 59, TOP OF 60TH FLOOR	30% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 024

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-60

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-26013	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 59, TOP OF 57TH FLOOR	35% CHRYSOTILE ASBESTOS
R-1WTC-26014	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 59, TOP OF 54TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-26015	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 59, TOP OF 50TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-26016	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 59, TOP OF 45TH FLOOR	15% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 025

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-61

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25145	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 61ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25146	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 58TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25147	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 55TH FLOOR.	3% CHRYSOTILE ASBESTOS
R-1WTC-25148	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 20" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 51ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25149	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 57TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25150	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 20" BEAM LOCATED ON THE EAST BEAM OF THE ELEVATOR SHAFT FOR CAR 60 AT THE TOP OF THE 45TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25151	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 51ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25152	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE SOUTH WEST CORNER OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 59TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25153	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 57TH FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25154	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 54TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25155	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" COLUMN LOCATED ON THE SOUTH WEST CORNER OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 53RD FLOOR.	2% CHRYSOTILE ASBESTOS
R-1WTC-25156	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 51ST FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25157	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 20" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 49TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 025

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-61

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25158	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF THE 47TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25159	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 18" COLUMN LOCATED ON THE SOUTH WEST CORNER WALL OF THE ELEVATOR SHAFT FOR CAR 61 AT THE TOP OF 45TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25664	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 20" COLUMN LOCATED ON THE SOUTH WEST CORNER OF THE ELEVATOR SHAFT, FOR CAR 62 AT THE TOP OF THE 45TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25665	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 62 AT THE TOP OF THE 48TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25666	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 62 AT THE TOP OF THE 51ST FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25667	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 62 AT THE TOP OF THE 54TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25668	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVETOR SHAFT FOR CAR 62 AT THE TOP OF THE 57TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25669	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 20" COLUMN LOCATED ON THE SOUTH WEST CORNER OF THE ELEVATOR SHAFT FOR CAR 62 AT THE TOP OF THE 59TH FLOOR.	25% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 026

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 44-69

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25103	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 67TH FLOOR.	NON ASBESTOS
R-1WTC-25104	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 65TH FLOOR.	NON ASBESTOS
R-1WTC-25105	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 63TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25106	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 24" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 61ST FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25107	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 59TH FLOOR.	NON ASBESTOS
R-1WTC-25108	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 58TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25109	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 56TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25110	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 54TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25111	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 24" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 50TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25112	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 48TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25113	FLUFFY SPRAYED ON INSULATION MATERIAL FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 46TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-25114	FLUFFY SPRAYED ON INSULATION MATERIAL FROM A 38" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 64 AT THE TOP OF THE 44TH FLOOR.	2% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 026

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 44-69

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25698	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 45TH FLOOR.	NON ASBESTOS
R-1WTC-25699	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 35" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 48TH FLOOR.	1-3% CHRYSOTILE ASBESTOS
R-1WTC-25700	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 51ST FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25701	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 54TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25702	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 57TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25703	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 35" COLUMN LOCATED ON THE SOUTHWEST CORNER OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 60TH FLOOR.	25% CHRYSOTILE ASBESTOS
R-1WTC-25704	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 63RD FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-25705	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 63 AT THE TOP OF THE 66TH FLOOR.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 027

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-65

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25115	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 67TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25116	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH WALL OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 65TH FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25117	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 62ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25118	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 60TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25119	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 58TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25120	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 56TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25121	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25122	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 52ND FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25123	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25124	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25125	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 46TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25126	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 20" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 68, TOP OF 45TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25127	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 21" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 67TH FLOOR	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 027

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-65

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25128	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 13" FLANGE, ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 64TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25129	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 61ST FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25130	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 13" FLANGE, ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 58TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25131	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 54TH FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25132	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 13" FLANGE, ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 51ST FLOOR	3% CHRYSOTILE ASBESTOS
R-1WTC-25133	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 48TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25134	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 13" FLANGE, ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 66, TOP OF 45TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25135	FLUFFY FALLOUT MATERIAL COLLECTED FROM TOP OF CAR # 66	2% CHRYSOTILE ASBESTOS
R-1WTC-25136	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE S/E CORNER OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 67TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25137	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR # 67,TOP OF 64TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25138	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE S/E CORNER OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 61ST FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25139	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 59TH FLOOR	NON ASBESTOS
R-1WTC-25140	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 57TH FLOOR	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 028

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25172	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 70, TOP OF 61ST FLOOR	NON ASBESTOS
R-1WTC-25173	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 70, TOP OF 57TH FLOOR	NON ASBESTOS
R-1WTC-25174	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 70, TOP OF 53RD FLOOR	NON ASBESTOS
R-1WTC-25175	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 70, TOP OF 49TH FLOOR	NON ASBESTOS
R-1WTC-25176	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 70, TOP OF 44TH FLOOR	NON ASBESTOS
R-1WTC-25177	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 74TH FLOOR	NON ASBESTOS
R-1WTC-25178	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 68TH FLOOR	NON ASBESTOS
R-1WTC-25179	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 63RD FLOOR	NON ASBESTOS
R-1WTC-25180	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 58TH FLOOR	NON ASBESTOS
R-1WTC-25181	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 52ND FLOOR	NON ASBESTOS
R-1WTC-25182	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 71, TOP OF 46TH FLOOR	NON ASBESTOS
R-1WTC-25183	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM TOP OF CAR # 71	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 029

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25184	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON S/E CORNER OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 74TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25185	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 70TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25186	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON WEST WALL OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 66TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25187	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 62ND FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25188	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16"COLUMN LOCATED ON NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 58TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25189	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 54TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25190	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON WEST WALL OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 50TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-25191	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 74, TOP OF 46TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-25192	FLUFFY FALLOUT MATERIAL COLLECTED FROM TOP OF CAR # 74	15% CHRYSOTILE ASBESTOS
R-1WTC-25193	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 73, TOP OF 73RD FLOOR	35% CHRYSOTILE ASBESTOS
R-1WTC-25194	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 73, TOP OF 69TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-25195	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 73, TOP OF 65TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25196	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 73, TOP OF 59TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25197	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 73, TOP OF 55TH FLOOR	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 029

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25198	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 73, TOP OF 48TH FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-25199	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE S/E CORNER OF ELEVATOR SHAFT FOR CAR # 73, TOP OF 44TH FLOOR	30% CHRYSOTILE ASBESTOS
R-1WTC-26000	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 74TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-26001	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 68TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-26002	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 5" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 64TH FLOOR	15% CHRYSOTILE ASBESTOS
R-1WTC-26003	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 5" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 58TH FLOOR	20% CHRYSOTILE ASBESTOS
R-1WTC-26004	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 5" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 51ST FLOOR	25% CHRYSOTILE ASBESTOS
R-1WTC-26005	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 5" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT, FOR CAR # 72, TOP OF 45TH FLOOR	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 030

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-86

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25399	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 77, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25400	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 77, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25401	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT, FOR CAR # 77, TOP OF 85TH FLOOR	NON ASBESTOS
R-1WTC-25402	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT, FOR CAR # 76, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25403	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 76, TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25404	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 76, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25405	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 75, TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25406	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 75, TOP OF 83RD FLOOR	NON ASBESTOS
R-1WTC-25407	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 75, TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25408	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 75, TOP OF 86TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 031

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-80

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25308	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 17" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 78, TOP OF 78TH FLOOR.	NON ASBESTOS
R-1WTC-25309	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 78, TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25310	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 78, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25311	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 78, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25312	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 17" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 78, TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25313	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 79, TOP OF 78TH FLOOR	NON ASBESTOS
R-1WTC-25314	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 79, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25315	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 79, TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25316	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 79, TOP OF 83RD FLOOR	NON ASBESTOS
R-1WTC-25317	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 79, TOP OF 85TH FLOOR	NON ASBESTOS
R-1WTC-25318	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON TH SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25319	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 80TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 031

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-80

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25320	FLUFFY INNER LAYER INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25321	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25322	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25323	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 80, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25324	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT,FOR CAR # 80, TOP OF 85TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 032

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-94

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25325	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 14" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 78TH FLOOR	NON ASBESTOS
R-1WTC-25326	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25327	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25328	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 87TH FLOOR	NON ASBESTOS
R-1WTC-25329	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 90TH FLOOR	NON ASBESTOS
R-1WTC-25330	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 14" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 83, TOP OF 93RD FLOOR	NON ASBESTOS
R-1WTC-25331	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25332	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 17" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25333	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 85TH FLOOR	NON ASBESTOS
R-1WTC-25334	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 88TH FLOOR	NON ASBESTOS
R-1WTC-25335	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 91ST FLOOR	NON ASBESTOS
R-1WTC-25336	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 17 "COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 82, TOP OF 93RD FLOOR	NON ASBESTOS
R-1WTC-25409	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FORCAR # 81, TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25410	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 81ST FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 032

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-94

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25411	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25412	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FORCAR # 81, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25413	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25414	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT, FORCAR # 81, TOP OF 88TH FLOOR	NON ASBESTOS
R-1WTC-25415	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 91ST FLOOR	NON ASBESTOS
R-1WTC-25416	PLASTER LIKE INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 93RD FLOOR	NON ASBESTOS
R-1WTC-25417	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 81, TOP OF 93RD FLOOR	2% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 033

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-93

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25418	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 84, TOP OF 79TH FLOOR	<1% CHRYSOTILE ASBESTOS
R-1WTC-25419	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 84, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25420	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 84, TOP OF 85TH FLOOR	NON ASBESTOS
R-1WTC-25421	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 84, TOP OF 88TH FLOOR	NON ASBESTOS
R-1WTC-25422	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 84, TOP OF 92ND FLOOR	NON ASBESTOS
R-1WTC-25423	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 85, TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25424	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 85, TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25425	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 85, TOP OF 89TH FLOOR	NON ASBESTOS
R-1WTC-25426	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT, FOR CAR # 85, TOP OF 93RD FLOOR	NON ASBESTOS
R-1WTC-25427	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT, FOR CAR # 86, TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25428	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 86, TOP OF 90TH FLOOR	NON ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limi for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25248	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 78TH FLOOR	NON ASBESTOS
R-1WTC-25249	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH WALL OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25250	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL COLLECTED FROM 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25251	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25252	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM 16" BEAM LOCATED ON THE SOUTH WALL OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 89TH FLOOR	NON ASBESTOS
R-1WTC-25253	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT, FOR CAR # 89, TOP OF 93RD FLOOR	NON ASBESTOS
R-1WTC-25254	FLUFFY INNER LAYER INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON N/W CORNER OF THE ELEVATOR SHAFT FOR CAR # 89 AT THE TOP OF THE 93RD FLOOR	NON ASBESTOS
R-1WTC-25255	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 89 AT THE TOP OF THE 96TH FLOOR	NON ASBESTOS
R-1WTC-25256	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 89 AT THE TOP OF 100TH FLOOR	NON ASBESTOS
R-1WTC-25257	FLUFFY INNER LAYER INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 89 AT THE TOP OF 100TH FLOOR	NON ASBESTOS
R-1WTC-25258	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25259	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 84TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25260	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 88TH FLOOR	NON ASBESTOS
R-1WTC-25261	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 88TH FLOOR	NON ASBESTOS
R-1WTC-25262	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 92ND FLOOR	NON ASBESTOS
R-1WTC-25263	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 92ND FLOOR	NON ASBESTOS
R-1WTC-25264	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 95TH FLOOR	NON ASBESTOS
R-1WTC-25265	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 95TH FLOOR	NON ASBESTOS
R-1WTC-25266	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 88 AT THE TOP OF 99TH FLOOR	NON ASBESTOS
R-1WTC-25267	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 87 AT THE TOP OF 81ST FLOOR	NON ASBESTOS
R-1WTC-25268	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR #87 AT THE TOP OF THE 86TH FLOOR	NON ASBESTOS
R-1WTC-25269	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 87 AT THE TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25270	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM AN 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR #87 AT THE TOP OF THE 91ST FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25271	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 87 AT THE TOP OF 91ST FLOOR	NON ASBESTOS
R-1WTC-25272	CEMENTITIOUS OF INSULATION MATERIAL COLLECTED FROM AN 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR #87 AT THE TOP OF THE 97TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25273	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25274	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 79TH FLOOR	NON ASBESTOS
R-1WTC-25275	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25276	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 82ND FLOOR	NON ASBESTOS
R-1WTC-25277	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25278	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 86TH FLOOR	NON ASBESTOS
R-1WTC-25279	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF THE 89TH FLOOR	NON ASBESTOS
R-1WTC-25280	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 89TH FLOOR	NON ASBESTOS
R-1WTC-25281	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF THE 93RD FLOOR	NON ASBESTOS
R-1WTC-25282	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 93RD FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25283	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF THE 96TH FLOOR	NON ASBESTOS
R-1WTC-25284	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 96TH FLOOR	NON ASBESTOS
R-1WTC-25285	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF THE 99TH FLOOR	NON ASBESTOS
R-1WTC-25286	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 90 AT THE TOP OF 99TH FLOOR	NON ASBESTOS
R-1WTC-25287	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 80TH FLOOR	NON ASBESTOS
R-1WTC-25288	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 80TH FLOOR	NON ASBESTOS
R-1WTC-25289	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 18" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 84TH FLOOR	NON ASBESTOS
R-1WTC-25290	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 18" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 84TH FLOOR	NON ASBESTOS
R-1WTC-25291	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 88TH FLOOR	NON ASBESTOS
R-1WTC-25292	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 92ND FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25293	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 92ND FLOOR	NON ASBESTOS
R-1WTC-25294	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 94TH FLOOR	NON ASBESTOS
R-1WTC-25295	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 94TH FLOOR	NON ASBESTOS
R-1WTC-25296	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 97TH FLOOR	NON ASBESTOS
R-1WTC-25297	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 97TH FLOOR	NON ASBESTOS
R-1WTC-25298	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF THE 100TH FLOOR	NON ASBESTOS
R-1WTC-25299	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" COLUMN LOCATED ON THE N/E CORNER OF ELEVATOR SHAFT FOR CAR # 91 AT THE TOP OF 100TH FLOOR	NON ASBESTOS
R-1WTC-25300	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF THE 99TH FLOOR	NON ASBESTOS
R-1WTC-25301	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF 99TH FLOOR	NON ASBESTOS
R-1WTC-25302	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF THE 95TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 77-101

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25303	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF 95TH FLOOR	NON ASBESTOS
R-1WTC-25304	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF THE 87TH FLOOR	NON ASBESTOS
R-1WTC-25305	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF 87TH FLOOR	NON ASBESTOS
R-1WTC-25306	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF THE 81ST FLOOR	NON ASBESTOS
R-1WTC-25307	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 92 AT THE TOP OF 81ST FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 036

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-107

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25338	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 79TH FLOOR	NON ASBESTOS
R-1WTC-25339	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE NORTHWEST CORNER OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 83RD FLOOR	NON ASBESTOS
R-1WTC-25340	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FORCAR # 95 AT THE TOP OF THE 87TH FLOOR	NON ASBESTOS
R-1WTC-25341	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 91ST FLOOR	NON ASBESTOS
R-1WTC-25342	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF THE ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 91ST FLOOR	NON ASBESTOS
R-1WTC-25343	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 95TH FLOOR	NON ASBESTOS
R-1WTC-25344	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FORCAR # 95 AT THE TOP OF THE 99TH FLOOR	NON ASBESTOS
R-1WTC-25345	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 101ST FLOOR	NON ASBESTOS
R-1WTC-25346	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 101ST FLOOR	NON ASBESTOS
R-1WTC-25347	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 105TH FLOOR	NON ASBESTOS
R-1WTC-25348	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 105TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 036

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-107

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25349	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 103RD FLOOR	NON ASBESTOS
R-1WTC-25350	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF THE ELEVATOR SHAFT FOR CAR # 95 AT THE TOP OF THE 103RD FLOOR	NON ASBESTOS
R-1WTC-25351	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 80TH FLOOR	NON ASBESTOS
R-1WTC-25352	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 80TH FLOOR	NON ASBESTOS
R-1WTC-25353	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 84TH FLOOR	NON ASBESTOS
R-1WTC-25354	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 84TH FLOOR	NON ASBESTOS
R-1WTC-25355	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 88TH FLOOR	NON ASBESTOS
R-1WTC-25356	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 92ND FLOOR	NON ASBESTOS
R-1WTC-25357	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE N/W CORNER OF THE ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 92ND FLOOR	NON ASBESTOS
R-1WTC-25358	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 15" COLUMN LOCATED ON THE BACK SIDE OF THE COLUMN N/W SIDE OF THE ELEVATOR SHAFT FOR CAR # 94 THE TOP OF 96TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 036

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-107

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25359	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 100TH FLOOR	NON ASBESTOS
R-1WTC-25360	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 100TH FLOOR	NON ASBESTOS
R-1WTC-25361	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 104TH FLOOR	NON ASBESTOS
R-1WTC-25362	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # 94 AT THE TOP OF THE 104TH FLOOR	NON ASBESTOS
R-1WTC-25363	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 79TH FLOOR	NON ASBESTOS
R-1WTC-25364	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 84TH FLOOR	NON ASBESTOS
R-1WTC-25365	CEMENTITIOUS OUTER LAYER OF INSULATION MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 89TH FLOOR	NON ASBESTOS
R-1WTC-25366	FLUFFY INNER LAYER OF INSULATION MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 89TH FLOOR	NON ASBESTOS
R-1WTC-25367	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 93RD FLOOR	NON ASBESTOS
R-1WTC-25368	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE WEST SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 98TH FLOOR	NON ASBESTOS
R-1WTC-25369	CEMENTITIOUS INSULATION MATERIAL COLLECTED FROM A 6" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 93 AT THE TOP OF THE 106TH FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 037

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25370	CEMENTITIOUS INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 79TH FLOOR.	NON ASBESTOS
R-1WTC-25371	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 84TH FLOOR.	NON ASBESTOS
R-1WTC-25372	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 84TH FLOOR.	NON ASBESTOS
R-1WTC-25373	CEMENTITIOUS INNER LAYER INSULATION MATERIAL FROM A 8" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 89TH FLOOR.	NON ASBESTOS
R-1WTC-25374	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 8" BEAM LOCATED ON THE WEST FLOOR OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 89TH FLOOR.	NON ASBESTOS
R-1WTC-25375	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT CAR 96 AT THE TOP OF THE 94TH FLOOR.	NON ASBESTOS
R-1WTC-25376	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT CAR 96 AT THE TOP OF THE 94TH FLOOR.	NON ASBESTOS
R-1WTC-25377	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 99TH FLOOR.	NON ASBESTOS
R-1WTC-25378	FLUFFY OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 99TH FLOOR.	NON ASBESTOS
R-1WTC-25379	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT CAR 96 AT THE TOP OF THE 105TH FLOOR.	NON ASBESTOS
R-1WTC-25380	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT CAR 96 AT THE TOP OF THE 105TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 037

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25381	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED ON NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 96 AT THE TOP OF THE 80TH FLOOR.	NON ASBESTOS
R-1WTC-25382	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 80TH FLOOR.	NON ASBESTOS
R-1WTC-25383	CEMENTITIOUS INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 85TH FLOOR.	NON ASBESTOS
R-1WTC-25384	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 90TH FLOOR.	NON ASBESTOS
R-1WTC-25385	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 95TH FLOOR.	NON ASBESTOS
R-1WTC-25386	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" BEAM LOCATED ON THE NORTH SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 95TH FLOOR.	NON ASBESTOS
R-1WTC-25387	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 100TH FLOOR.	NON ASBESTOS
R-1WTC-25388	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 16" COLUMN LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 100TH FLOOR.	NON ASBESTOS
R-1WTC-25389	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 14" BEAM LOCATED ON WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 105TH FLOOR.	NON ASBESTOS
R-1WTC-25390	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 14" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 97 AT THE TOP OF THE 105TH FLOOR.	NON ASBESTOS
R-1WTC-25391	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 8" BEAM LOCATED ON SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 80TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 037

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 78-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25392	CEMENTITIOUS INSULATION MATERIAL FROM A 14" BEAM LOCATED ON WEST SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 86TH FLOOR.	NON ASBESTOS
R-1WTC-25393	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 91ST FLOOR.	NON ASBESTOS
R-1WTC-25394	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 8" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 91ST FLOOR.	NON ASBESTOS
R-1WTC-25395	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 12" BEAM LOCATED ON EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 96TH FLOOR.	NON ASBESTOS
R-1WTC-25396	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 96TH FLOOR.	NON ASBESTOS
R-1WTC-25397	CEMENTITIOUS OUTER LAYER INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 101ST FLOOR.	NON ASBESTOS
R-1WTC-25398	FLUFFY INNER LAYER INSULATION MATERIAL FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR 98 AT THE TOP OF THE 101ST FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 67
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: I-BEAM
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 81

SAMPLE NUMBER	LOCATION	RESULT
WTC-28854	FLUFFY FIREPROOFING INSULATION FROM I-BEAM COLLECTED FROM INSIDE WALL ENCLOSURES.	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: LOBBY CEILING AREA, (ALL QUADRANT)

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1111	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1112	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1113	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1114	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1115	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
WTC-1116	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1117	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1118	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1119	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1120	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1121	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1122	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1123	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1124	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: LOBBY CEILING AREA, (ALL QUADRANT)

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1125	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1126	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1127	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1128	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1129	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1130	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1131	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1132	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1133	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1134	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1135	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1136	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN NORTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1137	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1138	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: LOBBY CEILING AREA

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1139	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1140	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1141	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1142	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1143	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
-WTC-1144	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHEAST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1145	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1146	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1147	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1148	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1149	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1150	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1151	OUTER WHITE PLASTER MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1152	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM CEILING OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: LOBBY CEILING AREA

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1153	OUTER WHITE PLASTER MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1154	INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM OUTER FACADE OF MEZZANINE LEVEL IN SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1155	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING AT THE SOUTH END OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1156	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING AT THE SOUTH END OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1157	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING AT THE CENTER OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
WTC-1158	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING AT THE CENTER OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1159	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING AT THE NORTH END OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1160	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING AT THE NORTH END OF THE MAIN ELEVATOR CORRIDOR.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1161	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING OF THE EXTREME NORTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1162	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING OF THE EXTREME NORTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1163	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING OF THE MID-NORTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1164	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING OF THE MID-NORTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1165	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING OF THE MID-SOUTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1166	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING OF THE MID-SOUTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: LOBBY CEILING AREA

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1167	AN OUTER WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING OF THE EXTREME SOUTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1168	AN INNER GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE CEILING OF THE EXTREME SOUTH ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 03/23/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: SOUTHEAST LOBBY CEILING AREA

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1100	A MULTI-ELEMENT CONCRETE-LIKE MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1101	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1102	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1103	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
WTC-1104	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1105	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	45% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1106	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1107	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1108	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1109	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE LEVEL
AREA DESCRIPTION: SOUTHEAST LOBBY CEILING AREA

BUILDING:
FLOOR: 1

SAMPLE NUMBER	LOCATION	RESULT
B-WTC-1110	A WHITE FLUFFY SPRAYED ON MATERIAL COLLECTED FROM THE CEILING OF THE INNER PLENUM AREA BETWEEN THE LOBBY CEILING AND MEZZANINE FLOOR IN THE SOUTHEAST CORNER OF THE LOBBY.	NON ASBESTOS SAMPLE DATE: 03/22/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 109
SURVEY # 008

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SUB-LEVEL ELEVATOR SHAFT/CARS J3-J5

BUILDING: 1
FLOOR: 1-86

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-29000	CEMENTITIOUS MATERIAL COLLECTED FROM AN 8" BEAM LOCATED ON THE SOUTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # J3 AT THE TOP OF THE B-2 FLOOR.	NON ASBESTOS
R-1WTC-29001	CEMENTITIOUS MATERIAL COLLECTED FROM AN 16" BEAM LOCATED ON THE SOUTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR # J3 AT THE TOP OF THE B-3 FLOOR.	NON ASBESTOS
R-1WTC-29002	CEMENTITIOUS MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE SOUTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR # J3 AT THE TOP OF THE B-4 FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 133
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: OLD VALVE ROOM / PIT AREA

BUILDING: 1
FLOOR: SUB-LEVEL

SAMPLE NUMBER	LOCATION	RESULT
WTC-29199	CEMENTITIOUS PIPE JOINT INSULATION TAKEN FROM 6" O.D PIPE ON SOUTH SIDE OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91
WTC-29200	CEMENTITIOUS PIPE JOINT INSULATION TAKEN FROM 6" O.D. PIPE ON NORTH SIDE OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91
WTC-29201	CEMENTITIOUS PIPE JOINT INSULATION TAKEN FROM 6" O.D. PIPE IN CENTER OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6100	PAPER AND FOIL LIKE OUTER COVERING COLLECTED FROM A 5" O.D. PIPE, CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6102	INNER FIBEROUS INSULATION MATERIAL COLLECTED FROM A 5" O.D. CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6103	CLOTH LIKE OUTER COVERING COLLECTED FROM A 5" O.D. ELBOW CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6104	INNER FIBEROUS INSULATION MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6105	INNER FIBEROUS INSULATION MATERIAL COLLECTED FROM A 6" O.D. PIPE FITTING CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6106	OUTER WHITE PLASTER MATERIAL COLLECTED FROM 6" O.D. PIPE FITTING CHILLED WATER SUPPLY AT THE WEST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6107	PAPER AND FOIL LIKE COVERING MATERIAL COLLECTED FROM A 6" O.D. PIPE CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6108	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. PIPE CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6109	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE FITTING CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6110	OUTER CLOTH COVERING MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6111	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6112	OUTER CLOTH LIKE COVERING COLLECTED FROM A 6" O.D. ELBOW CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6113	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW CWS WEST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6114	OUTER WHITE CLOTH MATERIAL COLLECTED FROM A 12" O.D. VALVE/FITTING CWS SOUTH SIDE OF ACS 7-13	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6115	WHITE WET PLASTER MATERIAL COLLECTED FROM A 10" O.D. PIPE /FITTING CWS SOUTH SIDE NEAR P 7-13.	NON ASBESTOS
R-WTC-6116	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE /ELBOW CWS SOUTH EAST CORNER OF ACS 7-13.	NON ASBESTOS
R-WTC-6117	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D ELBOW CWS SOUTH EAST CORNER OF ACS 7-13.	NON ASBESTOS
R-WTC-6118	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW CWS EAST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6119	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D.PIPE/ELBOW CWS EAST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6120	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE CWS EAST SIDE OF ACS 7-13.	NON ASBESTOS
R-WTC-6121	OUTER CLOTH AND PLASTER COMBINATION COVERING MATERIAL COLLECTED FROM 14" O.D. FITTING CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6122	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW CWS EAST SIDE.OF ACS 7-13	NON ASBESTOS
R-WTC-6123	INNER FIBROUS MATERIAL COLLECTED FROM A 5' O.D. PIPE ELBOW CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6124	OUTER PAPER AND FOIL COMBINATIONS MATERIAL COLLECTED FROM A 5" O.D. PIPE CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6125	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6126	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6127	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. FITTING CWS EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6128	OUTER WHITE PLASTER MATERIAL COLLECTED FROM A 8" O.D. FITTING CWS EAST SIDE OF ACS 7-13	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6129	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6130	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6131	OUTER PAPER LIKE AND FOIL MATERIAL FROM A 8" O.D. FITTING LOCATED EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6132	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 8" O.D. FITTING LOCATED EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6133	OUTER PAPER LIKE AND FOIL MATERIAL COLLECTED FROM A 12" O.D. FITTING LOCATED AT EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6134	BLACK TAR LIKE MATERIAL COLLECTED FROM A 12" O.D. FITTING LOCATED AT EAST SIDE OF ACS 7-13	35% CHRYSOTILE ASBESTOS
R-WTC-6135	INNER FIBROUS MATERIAL COLLECTED FROM A 12" O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6136	WHITE OUTER PLASTER LIKE MATERIAL COLLECTED FROM A 14 O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6137	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 14" O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6138	INNER FIBROUS MATERIAL COLLECTED FROM A 12" O.D. FITTING LOCATED ON EAST SIDE OF ACS 7-13	NON ASBESTOS
R-WTC-6139	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED IN ASILE BETWEEN ACS 7-13 AND ACS 7-5.	NON ASBESTOS
R-WTC-6140	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED IN ASILE BETWEEN ACS 7-13 AND ACS 7-5.	NON ASBESTOS
R-WTC-6141	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED IN ASILE BETWEEN ACS 7-13 AND ACS 7-5.	NON ASBESTOS
R-WTC-6142	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. FITTING LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6143	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS
R-WTC-6144	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. FITTING LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS
R-WTC-6145	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS
R-WTC-6147	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6"O.D. PIPE LOCATED BETWEEN ACS 7-13	NON ASBESTOS
R-WTC-6148	INNER FIBROUS MATERIAL COLLECTED FROM A 6"O.D. ELBOW LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS
R-WTC-6149	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED IN WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6150	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED IN WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6151	INNER FIBROUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED IN WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6152	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 14" O.D. FITTING LOCATED IN WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6153	OUTER CLOTH LIKE MATERIAL COLLECTED FROMA A 6" O.D. ELBOW LOCATED IN WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6154	INNER FIBROUS MATERIAL COLLECTED A 6" O.D. ELBOW LOCATED ON WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6155	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6156	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED FLOOR LEVEL ON WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6157	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED FLOOR LEVEL ON WEST SIDE OF ACS 7-5.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6158	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED FLOOR LEVEL WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6159	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED FLOOR LEVEL WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6160	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE FITTING LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6161	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE FITTING LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6162	OUTER WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. PIPE FITTING LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6163	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6164	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6165	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED ON THE WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6166	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE FITTING LOCATED ON WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6167	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D PIPE FITTING LOCATED ON WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6168	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE FITTING/ELBOW LOCATED WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6169	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A FITTING LOCATED WEST SIDE OF ACS 7-5	NON ASBESTOS
R-WTC-6170	OUTER CLOTH LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE FITTING LOCATED ON WEST SIDE OF ACS 7-5.	NON ASBESTOS
R-WTC-6171	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. PIPE FITTING LOCATED ON WEST SIDE OF ACS 7-5.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6101	INNER FIBROUS INSULATION MATERIAL COLLECTED FROM A 5" O.D. CHILLED WATER SUPPLY PIPE AT THE WEST SIDE OF ACS 7-13	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6146	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED BETWEEN ACS 7-13 AND ACS 7-5	NON ASBESTOS
R-WTC-6182	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6183	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6184	OUTER WHITE PLASTER LIKE MATERIAL A 6" O.D. FITTING EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6185	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE EAST OF ACS-7-5	NON ASBESTOS
R-WTC-6186	OUTER COTH LIKE MATERIAL COLLECTED FROM 5" O.D. ELBOW EAST OF ACS-7-5	NON ASBESTOS
R-WTC-6187	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS-7-5	NON ASBESTOS
-WTC-6188	PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. FITTING EAST OF ACS-7-5	NON ASBESTOS
R-WTC-6189	OUTER CLOTH LIKE MATERIAL COOLECTED FROM A 5" O.D. ELBOW EAST OF ACS-7-5	NON ASBESTOS
R-WTC-6190	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS-7-5	NON ASBESTOS
R-WTC-6191	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6192	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6193	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6194	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6195	GREY CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. FITTING, WEST END OF COIL PUMP P 7-1	NON ASBESTOS
R-WTC-6196	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. FITTING AT WEST END OF COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6197	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. FITTING AT WEST END OF COIL PUMP P-7-1	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6172	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 14" O.D. PIPE FITTING LOCATED AT SOUTH END OF ACS 7-5	NON ASBESTOS
R-WTC-6173	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE FITTING LOCATED AT SOUTH END OF ACS 7-5.	NON ASBESTOS
R-WTC-6174	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. FITTING LOCATED AT THE SOUTH END OF ACS 7-5.	NON ASBESTOS
R-WTC-6175	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE AT SOUTH END OF ACS 7-5.	NON ASBESTOS
R-WTC-6176	OUTER CLOTH LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE FITTING LOCATED AT SOUTH END OF ACS 7-5.	NON ASBESTOS
R-WTC-6177	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. PIPE FITTING LOCATED AT SOUTH END OF ACS 7-5.	NON ASBESTOS
R-WTC-6178	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE EAST OF ACS 7-5.	NON ASBESTOS
R-WTC-6179	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5.	NON ASBESTOS
R-WTC-6180	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5.	NON ASBESTOS
R-WTC-6181	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW EAST OF ACS 7-5.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6198	OUTER WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. FITTING AT EAST END OF COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6199	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW AT WEST END OF COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6200	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW AT WEST END OF COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6201	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE AT WEST END COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6202	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW AT THE EAST END COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6203	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW AT THE EAST END COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6204	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE AT EAST END COIL PUMP P-7-1	NON ASBESTOS
R-WTC-6205	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW SOUTH OF ACS 7-1	NON ASBESTOS
R-WTC-6206	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW SOUTH OF ACS 7-1	NON ASBESTOS
R-WTC-6207	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED SOUTH OF ACS 7-1	NON ASBESTOS
R-WTC-6208	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6209	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6210	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6211	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-1	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6212	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6213	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6214	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6215	OUTER WHITE PLASTER MATERIAL COLLECTED FROM 6" O.D. COUPLING LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6216	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6217	INNER FIBROUS MATERIAL COLLECTED FROM A 6' O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6218	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6219	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6220	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6221	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. PIPE ELBOW LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6222	OUTER PAPER AND TAR LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-1	NON ASBESTOS
R-WTC-6223	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED EAST ACS 7-1	NON ASBESTOS
R-WTC-6224	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6225	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

CILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: MECHANICAL EQUIPMENT RM. S.W. QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6307	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED SOUTH OF ACS 7-2	NON ASBESTOS
R-WTC-6308	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6309	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATE SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6310	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: N.E. QUADRANT-MECHANICAL EQUIP. RM.C

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6311	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6312	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6313	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH OF ACS 7-2(COIL P7-2)	NON ASBESTOS
R-WTC-6314	CEMENTITIOUS LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH OF ACS 7-2(COIL P7-2)	NON ASBESTOS
R-WTC-6315	CLOTH LIKE MATERIAL COLLECTED FROM A FREEZE PROTECTOR LOCATED SOUTH OF ACS 7-2(COIL P7-2)	NON ASBESTOS
R-WTC-6316	PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED SOUTH OF ACS 7-2 (COIL P7-2)	NON ASBESTOS
R-WTC-6317	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED SOUTH OF ACS 7-2	NON ASBESTOS
R-WTC-6318	INNER FIBROUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6319	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6320	OUTER WHITE PLASTER MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6321	OUTER CLOTH MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED SOUTH OF ACS 7-2.	NON ASBESTOS
R-WTC-6322	OUTER PAPER FOIL AND TAR MATERIAL COLLECTED FROM A 16" O.D. VALVE SOUTH OF ACS 7-2.	40% CHRYSOTILE ASBESTOS
R-WTC-6323	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED FROM A EAST OF ACS7-2.	NON ASBESTOS
R-WTC-6324	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: N.E. QUADRANT-MECHANICAL EQUIP. RM.C

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6325	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6 "O.D. COUPLING LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6326	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6327	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6328	INNER FIBROUS MATERIAL COLLECTED FROM A 5"O.D. ELBOW LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6329	OUTER WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6330	OUTE PAPER AND FOIL MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-2.	NON ASBESTOS
R-WTC-6331	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED EAST OF ACS 7-2, 14' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6332	INNER FIBROUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED EAST OF ACS 7-2, 14' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6333	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-2 , 14'ABOVE FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6334	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-2 10' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6335	INNER FIBROUS MATERIAL COLLECTED FROM 5" O.D. ELBOW LOCATED EAST OF ACS 7-2, 10 ABOVE FLOOR.	NON ASBESTOS
R-WTC-6336	PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-2, 10' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6337	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED ON COIL P7-14.	NON ASBESTOS
R-WTC-6338	CLOTH LIKE MATERIAL COLLECTED FROM A FREEZE PROTECTOR LOCATED ON COIL P7-14.	NON ASBESTOS
R-WTC-6339	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 10" O.D. VALVE LOCATED ON COIL P7-14.	NON ASBESTOS
R-WTC-6340	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6341	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6342	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D COUPLING LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6343	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6344	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6345	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6346	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6347	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-14.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6348	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-14.	NON ASBESTOS
R-WTC-6524	WHITE PLASTER MATERIAL COLLECTED FROM A 14" O,D, PIPE LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6525	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 14" O.D. PIPE NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6526	CLOTH MATERIAL COLLECTED FROM A 8" O.D. NEAR NORTH EAST CORNER AT SC-7-2	NON ASBESTOS
R-WTC-6527	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6528	CLOTH MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED NEAR NORTH EAST CORNER AT SC-7-2	NON ASBESTOS
R-WTC-6529	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6530	CLOTH MATERIAL COLLECTED FROM A 8" O.D. COUPLING LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6531	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. COUPLING LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS
R-WTC-6532	CLOTH MATERIAL COLLECTED FROM A 8 " O.D. ELBOW LOCATED NEAR NORTH EAST CORNER AT SC-7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT RM. S.W. QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6305	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6306	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6270	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6271	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6272	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM AN 8"O.D. PIPE WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6273	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE/ELBOW LOCATED AT THE WEST SIDE OF THE COIL PUMP P 7-6	NON ASBESTOS
R-WTC-6274	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. PIPE/ELBOW LOCATED AT THE WEST SIDE OF THE COIL PUMP P 7-6	NON ASBESTOS
R-WTC-6275	WHITE PLASTER MATERIAL COLLECTED FROM BELOW FREEZE PROTECTOR CENTER OF COIL PUMP P 7-6.	NON ASBESTOS
R-WTC-6276	PAPER AND FOIL-LIKE OUTER COVERING COLLECTED FROM A 8" O.D. FITTING CENTER OF COIL PUMP P 7-6.	NON ASBESTOS
R-WTC-6277	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE/ELBOW LOCATED WEST SIDE OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6278	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW/LOCATED WEST SIDE OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6279	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST SIDE OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6280	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST SIDE OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6281	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE WEST OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6282	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE EAST SIDE OF COIL PUMP P7-6.	NON ASBESTOS
R-WTC-6283	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW WEST SIDE OF COIL PUMP P7-6.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

ACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT RM. S.W. QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6284	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST SIDE OF COIL PUMP P7-6	NON ASBESTOS
R-WTC-6285	OUTER CLOTH-LIKE MATERIAL COLLETED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6286	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6287	WHITE PLASTER MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6288	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6289	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6290	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6291	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6292	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6293	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6294	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6295	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6296	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6297	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT RM. S.W. QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6298	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6299	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6300	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6301	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6302	INNER FIBROUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6303	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-2.	NON ASBESTOS
R-WTC-6304	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-2.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

ACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6251	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6252	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6253	WHITE PLASTER MATERIAL COLLECTED FROM 6" O.D. COUPLING LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6254	OUTER PAPER ANSD FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATE WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6255	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6256	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6257	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6258	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE WEST OF THE ACS 7-6.	NON ASBESTOS
R-WTC-6259	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6260	INNER FIBROUS MATERIAL COLLECTED FRIOM A 5" O.D. PIPE/ELBOW LOCATED WET OF ACS 7-6.	NON ASBESTOS
R-WTC-6261	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. PIPE/COUPLING LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6262	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6263	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6264	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 002

.ITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6265	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING WEST OF ACS 7-6	NON ASBESTOS
R-WTC-6266	OUTER PAPER AND FOIL-LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATE WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6267	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6268	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6269	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE/ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 003

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6419	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE/FITTING LOCATED ON THE WEST SIDE OF ACS 7-3	NON ASBESTOS
R-WTC-6420	OUTER CLOTH, TAR AND PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED AT WEST OF ACS 7-3	1-3% CHRYSOTILE ASBESTOS
R-WTC-6421	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6422	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6423	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. COUPLING LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6424	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6425	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6426	INNER FIBROUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6427	OUTER CLOTH LIKE MATERAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6428	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6429	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6430	OUTER PAPER AND FOIL LIKE MATERIAL COLLCTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6431	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6432	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 003

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6433	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED ON WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6434	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6435	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-6436	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6437	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6438	OUTER PAPER AND FOIL LIKE MATEIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6439	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6440	WHITE PLASTER MATEIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6441	OUTER PAPER FOIL MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6442	OUTER PAPER FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6443	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6444	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. COUPLING LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6445	OUTER PAPER FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6446	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED EAST OF ACS 7-10	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 003

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6447	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6448	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6449	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-10	NON ASBESTOS
R-WTC-6450	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE/FITTING LOCATED EAST OF COIL PUMP P 7-10	NON ASBESTOS
R-WTC-6451	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED EAST OF COIL PUMP P 7-10	NON ASBESTOS
R-WTC-6452	CEMENTITIOUS MATERIAL COLLECTED FROM THE BASE OF A VALVE EAST SIDE OF P 7-10	NON ASBESTOS
R-WTC-6453	OUTER PAPER FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST SIDE IF COIL PUMP P 7-10	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 004

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6454	OUTER PAPER FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6455	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6456	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6457	WHOTE PLASTER MATERIAL COLLECTED FROM A 6"O.D. COUPLING LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6458	OUTER PAPER FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6459	OUTER CLOTH LIKE MATERIAL COLLECED FROM A 5"O.D. ELBOW LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6460	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6461	OUTER PAPER FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6462	OUTER PAPER FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST SIDE OF COIL PUMP P 7-8.	NON ASBESTOS
R-WTC-6463	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. FITTING BELOW FREEZE PROTECTOR WEST SIDE OF COIL PUMP 7-8.	NON ASBESTOS
R-WTC-6464	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE/FITTING LOCATED WEST SIDE OF PUMP P 7-8.	NON ASBESTOS
R-WTC-6465	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW ABOVE COIL PUMP NORTH OF ACS 7-8.	NON ASBESTOS
R-WTC-6466	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW ABOVE COIL PUMP NORTH OF ACS 7-8.	NON ASBESTOS
R-WTC-6467	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. FITTING LOCATED WEST SIDE OF ACS 7-8.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 004

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6468	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST SIDE OF ACS 7-8.	NON ASBESTOS
R-WTC-6469	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED WEST SIDE OF THE ACS 7-8.	NON ASBESTOS
R-WTC-6470	OUTER CLOTH MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED WEST SIDE OF THE ACS 7-8.	NON ASBESTOS
R-WTC-6471	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST SIDE OF ACS 7-8.	NON ASBESTOS
R-WTC-6472	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED WEST SIDE OF ACS 7-8.	NON ASBESTOS
R-WTC-6473	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6474	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6475	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6476	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6477	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6478	OUTER CLOTH MATERIAL COLLECTED FROM A 8"O.D. PIPE LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6479	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON COIL PUMP P 7-4.	NON ASBESTOS
R-WTC-6480	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. COUPLING LOCATED ON COIL PUMP P 7-4.	NON ASBESTOS
R-WTC-6481	CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED ON COIL PUMP P 7-4.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 004

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6482	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. FITTING BELOW THE FREEZE PROTECTOR, ON COIL PUMP P 7-4	NON ASBESTOS
R-WTC-6483	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED ON COIL PUMP P 7-4	NON ASBESTOS
R-WTC-6484	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON COIL PUMP P 7-4	NON ASBESTOS
R-WTC-6485	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED ON COIL PUMP P 7-4.	NON ASBESTOS
R-WTC-6486	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED ON COIL PUMP P 7-4.	NON ASBESTOS
R-WTC-6487	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE EAST SIDE OF ACS 7-11.	NON ASBESTOS
R-WTC-6488	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE EAST SIDE OF ACS 7-11.	NON ASBESTOS
R-WTC-6489	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE EAST END OF COIL PUMP P 7-11.	NON ASBESTOS
R-WTC-6490	WHITE PLASTER MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED ON COIL PUMP P 7-11.	NON ASBESTOS
R-WTC-6491	CEMENTITIOUS MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED ON COIL PUMP P 7-11.	NON ASBESTOS
R-WTC-6492	OUTER CLOTH MATERIAL COLLECTED FROM BELOW A FREEZE PROTECTOR LOCATED ON COIL PUMP P 7-11.	NON ASBESTOS
R-WTC-6493	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. PIPE, BENEATH FREEZE PROTECTOR ON COIL PUMP P 7-11.	NON ASBESTOS
R-WTC-6494	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON COIL PUMP 7-11.	NON ASBESTOS
R-WTC-6495	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE WEST SIDE OF ACS 7-11.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 004

ACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6496	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON THE WEST SIDE OF ACS 7-11.	NON ASBESTOS
R-WTC-6497	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6498	WHITE PLASTER MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6499	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6500	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" ELBOW LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6501	WHITE PASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6502	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6503	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6504	WHITE PLASTER MATERIAL COLLECTED FROM A 5" O.D. COUPLING LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-6505	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6506	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6507	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6508	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6509	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED EAST OF ACS 7-11.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 004

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6510	WHITE PLASTER MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6511	OUTER CLOTH MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-6512	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6513	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6514	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6515	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6516	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED NEAR WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6517	WHITE PLASTER MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED NEAR WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6518	OUTER CLOTH-LIKE MATERIAL COLLECTED FROM BELOW FREEZE PROTECTOR NEAR WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6519	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED NEAR THE WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6520	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 14" O.D. PIPE LOCATED NEAR THE WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6521	WHITE PLASTER MATERIAL COLLECTED FROM A 14" O.D. VALVE LOCATED NEAR THE WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6522	CLOTH-LIKE MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED NEAR WEST WALL RISERS AT SC 7-1.	NON ASBESTOS
R-WTC-6523	PAPER AND FOIL MATERIAL COLLECTED FROM 8" O.D. PIPE LOCATED NEAR WEST WALL RISERS AT SC 7-1.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 005

ACILITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT
AREA DESCRIPTION: MECHANICAL EQUIPMENT ROOM

BUILDING: 1
FLOOR: 7TH

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6533	CLOTH MATERIAL COLLECTED FROM A 12" O.D. ELBOW LOCATED SOUTH SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6534	WHITE PLASTER MATERIAL COLLECTED FROM A 18" O.D. COUPLING LOCATED SOUTH SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6535	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 18" O.D. PIPE LOCATED SOUTH SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6536	OUTER CLOTH MATERIAL COLLECTED FROM A 18" O.D. VALVE LOCATED SOUTH SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6537	OUTER CLOTH MATERIAL COLLECTED FROM A 24" O.D. ELBOW ON RISER ON WEST SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6538	OUTER PAPER FOIL AND TAR MATERIAL COLLECTED FROM A 24" O.D. RISER LOCATED THE WEST SIDE OF THE ROOM.	NON ASBESTOS
R-WTC-6550	OUTER PAPER FOIL AND TAR MATERIAL COLLECTED FROM A 32" O.D. PIPE RISER LOCATED IN AIR PLENUM.	NON ASBESTOS
R-WTC-6551	OUTER PAPER FOIL AND TAR MATERIAL COLLECTED FROM A 32" O.D. PIPE RISER LOCATED IN AIR PLENUM.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 006

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6539	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 18" O.D. PIPE LOCATED NORTH OF ACS 7-10, 20'ABOVE FLOOR IN S.E. QUADRANT	NON ASBESTOS
R-WTC-6540	WHITE PLASTER MATERIAL COLLECTED FROM A 24" O.D. COUPLING LOCATED NORTH OF ACS 7-10 20' ABOVE FLOOR IN SOUTH EAST QUADRANT	NON ASBESTOS
R-WTC-6541	CLOTH MATERIAL COLLECTED FROM A 20" O.D. VALVE LOCATED NORTH OF ACS 7-10 20 ABOVE FLOOR IN SOUTH EAST QUADRANT	NON ASBESTOS
R-WTC-6542	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 24" O.D. COUPLING LOCATED NORTH OF ACS 7-10 20' ABOVE FLOOR IN SOUT EAST QUADRANT.	NON ASBESTOS
R-WTC-6543	WHITE PLASTER MATERIAL COLLECTED FROM A 24" O.D. VALVE COUPLING LOCATED NORTH OF ACS 7-8 20' ABOVE FLOOR IN SOUTH EAST QUADRANT.	NON ASBESTOS
R-WTC-6573	MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED 20' FROM EAST WALL SOUTH OF ACS 7-11 UPPER LEVEL, SOUTH EAST QUADRANT.	35% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 007

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6544	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 18' O.D. PIPE LOCATED EAST OF ACS 7-8 20' ABOVE FLOOR IN SOUT WEST QUADRANT.	NON ASBESTOS
R-WTC-6545	MOLDED SECTION MATERIAL COLLECTED FROM A 18" O.D. PIPE LOCATED EAST OF ACS 7-8 20' ABOVE FLOOR IN SOUT WEST QUADRANT.	40% CHRYSOTILE ASBESTOS
R-WTC-6572	GREY MOLDED SECTION MATERIAL COLLECTD FROM A 12" O.D. PIPE LOCATED NORTH OF ACS 7-11 UPPER LEVEL SOUTH WEST QUADRANT.	60% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 008

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6546	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR IN NORTH WEST QUADRANT.	NON ASBESTOS
R-WTC-6547	MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR IN NORTH WEST QUADRANT.	45% CHRYOTILE ASBESTOS
R-WTC-6569	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED SOUTH OF ACS 7-13 UPPER LEVEL NORTH WEST QUADRANT.	NON ASBESTOS
R-WTC-6570	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED SOUTH OF ACS 7-13 UPPER LEVEL NORTH WEST QUADRANT.	NON ASBESTOS
R-WTC-6571	MOLDED SECTION MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED SOUTH OF ACS 7-13 UPPER LEVEL NORTH WEST QUADRANT.	1-3% AMOSITE ASBESTOS 35% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 009

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6548	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED WEST OF ACS 7-6 20' ABOVE FLOOR IN NORTH EAST QUAD.	NON ASBESTOS
R-WTC-6549	MOLDED SECTION MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED WEST OF ACS 7-6 20' ABOVE FLOOR IN NORTH EAST QUAD.	40% CHRYSOTILE ASBESTOS
R-WTC-6574	MOLDED SECTION MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED SC 7-2 20 ABOVE FLOOR NEAR NORTH EAST CORNER.	35% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 010

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6553	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF 7-13 5 FEET FROM NORTH WEST CORNER	NON ASBESTOS
R-WTC-6554	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-13 5 FEET NORTH WEST CORNER.	NON ASBESTOS
R-WTC-6555	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-13 5 FEET NEAR WEST WALL.	NON ASBESTOS
R-WTC-6556	INNER FIB MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF WEST OF ACS 7-13 5 FEET NEAR WEST WALL.	NON ASBESTOS
R-WTC-6557	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST WEST OF ACS 7-13 5 FEET NEAR WEST WALL.	NON ASBESTOS
R-WTC-6558	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST WEST OF HOT WATER HEATER # 2 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6559	INNER FIBROUS MATERIAL COLLECTED FROM 3" O.D. PIPE/VALVE LOCATED WEST OF HOT WATER HEATER # 2 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6560	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF HOT WATER HEATER # 2 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6561	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-13 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6562	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-13 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6563	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-13 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6564	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-13 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6565	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-5 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6566	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-5 NEAR NORTH WALL.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 010

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6567	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-9 NEAR NORTH WALL.	NON ASBESTOS
R-WTC-6568	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-9 NEAR NORTH WALL.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 010

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6552	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-13 5 FEET FROM NORTH WEST CORNER.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6226	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM 5" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6227	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6228	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6229	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6230	OUTER PAPER AND FOIL AND TAR LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6231	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6232	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6233	INNER FIBROUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6234	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 8" O.D. COUPLING/VALVE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6235	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6236	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6237	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6238	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6239	OUTER WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST OF ACS 7-9	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 001

CILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6240	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6241	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6242	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6243	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6244	INNER FIBROUS MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6245	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6246	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. FITTING LOCATED SOUTH END OF ACS 7-9	NON ASBESTOS
R-WTC-6247	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH END OF ACS 7-9	NON ASBESTOS
R-WTC-6248	CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH OF ACS 7-9	NON ASBESTOS
R-WTC-6249	OUTER CLOTH LIKE MATERIAL COLLECTED FROM THE BASE OF A FREEZE PROTECTOR SOUTH OF ACS 7-9	NON ASBESTOS
R-WTC-6250	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED SOUTH OF ACS 7-9	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6584	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-6	NON ASBESTOS
R-WTC-6585	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-6	NON ASBESTOS
R-WTC-6586	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-6	NON ASBESTOS
R-WTC-6587	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-6	NON ASBESTOS
R-WTC-6588	INNER FIBROUS MATERIAL COLLECTED FROM A FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-6	NON ASBESTOS
R-WTC-6589	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6590	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6591	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6592	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	1-3% CHRYSOTILE ASBESTOS
R-WTC-6593	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6594	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6595	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6596	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6597	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6598	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6599	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE/ELBOW LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6600	INNER FIBROUS MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6601	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6602	OUTER CLOTH LIKE MATERIAL COLLECTED A 10" O.D. ELBOW LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6603	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT THE NORTH END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6604	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT THE NORTH END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6605	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED AT THE NORHT END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6606	OUTER PAPER AND FOIL LIKE MATEIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT NORTH END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6607	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED AT THE NORTH END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6608	INNER FIBROUS MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED AT THE NORTH END OF PUMP P7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6609	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6610	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6611	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE/HOUSING LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6612	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE NORTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6613	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED AT THE SOUTH END OF END OF PUMP P 7-3SECTION 9-24	NON ASBESTOS
R-WTC-6614	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE SOUTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6615	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE SOUTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
R-WTC-6616	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED AT THE SOUTH END OF PUMP P 7-3 SECTION 9-24	NON ASBESTOS
-WTC-6617	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBLOW LOCATED AT THE SOUTH END OF PUMP P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6618	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6619	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6620	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. PIPE LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6621	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6622	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6623	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED AT THE SOUTH END OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6624	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF PUMP P7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6625	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED A 10" O.D. PIPE LOCATED SOUTH OF P 7-4 SECTION 9-24	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6626	OUTER CLOTH LIKE MATERIAL COLLECTED FRM A 10" O.D. ELBOW LOCATED SOUTH OF P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6627	OUTER TAR,PAPER AND FOIL COMBINATION MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED SOUTH OF P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6628	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED WEST OF PPUMP P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6629	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED WEST OF PUMP P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6630	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED WEST OF PUMP P 7-4 SECTION 9-24	NON ASBESTOS
R-WTC-6631	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH OF SC 7-2	NON ASBESTOS
R-WTC-6632	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED NORTH OF SC 7-2	NON ASBESTOS
R-WTC-6633	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED AT NORHT OF SC 7-2	NON ASBESTOS
R-WTC-6634	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED AT NORHT END OF SC 7-2	NON ASBESTOS
R-WTC-6635	WHITE PLASTER LIKE MATERIAL COLLECT ED FROM A 16" O.D. COUPLING LOCATED AT NORHT END OF SC 7-2	NON ASBESTOS
R-WTC-6636	WHITE PLASTER LIKE MATERIAL COLLECT ED FROM A 16" O.D. COUPLING LOCATED AT NORHT END OF SC 7-2	NON ASBESTOS
R-WTC-6637	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE AT THE NORTH END OF SC 7-2	NON ASBESTOS
R-WTC-6638	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED NORTH END OF SC 7-2	NON ASBESTOS
R-WTC-6639	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE LOCATED AT NORTH END OF SC 7-2	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 011

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6640	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH END OF SC 7-2	NON ASBESTOS
R-WTC-6641	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 30" X 18" PIPE LABELED SC 7-2	NON ASBESTOS
R-WTC-6642	OUTER VINLY LIKE WRAP MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED ABOVE SC 7-2	NON ASBESTOS
R-WTC-6643	CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. COUPLING LOCATED ABOVE AT SC 7-2	NON ASBESTOS
R-WTC-6644	CEMENTITIOUS MATERIAL COLLECTED FROM A 16" O.D. TANK HX 7-2 LOCATED AT SC 7-2	NON ASBESTOS
WTC-6645	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 16" O.D.TANK HX 7-2 LOCATED AT SC 7-2	NON ASBESTOS
R-WTC-6646	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED ABOVE TANK HX 7-2 AT SC 7-2	NON ASBESTOS
R-WTC-6647	WHITE PLASTER MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED ABOVE TANK HX 7-2 AT SC 7-2	NON ASBESTOS
R-WTC-6648	CEMENTITIOUS MATERIAL COLLECTED FROM A 14" O.D. COUPLING LOCATED BELOW TANK HX 7-2 AT SC 7-2	NON ASBESTOS
R-WTC-6649	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED BELOW TANK HX 7-2 AT SC 7-2	NON ASBESTOS
R-WTC-6650	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED BELOW TANK HX 7-2 AT SC 7-2	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 012

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6655	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF P-7-5 (NEAR EAST WALL)	NON ASBESTOS
R-WTC-6656	INNER FIBROUS MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED EAST OF P-7-5 (NEAR EAST WALL)	NON ASBESTOS
R-WTC-6657	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED EAST OF P-7-5 (NEAR EAST WALL)	NON ASBESTOS
R-WTC-6658	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED EAST OF P-7-12 IN SOUTH EAST CORNER.	NON ASBESTOS
R-WTC-6659	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED EAST OF P-7-12 IN SOUTH EAST CORNER.	NON ASBESTOS
·WTC-6660	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-12 NEAR SOUTH WALL.	NON ASBESTOS
R-WTC-6661	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-12 NEAR SOUTH WALL.	NON ASBESTOS
R-WTC-6662	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-7 NEAR SOUTH WALL.	NON ASBESTOS
R-WTC-6663	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-7 NEAR SOUTH WALL.	NON ASBESTOS
R-WTC-6664	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-10 NEAR SOUTH WALL.	NON ASBESTOS
R-WTC-6665	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED WEST OF ACS 7-10 NEAR SOUTH WALL.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6704	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED NORTH END OF SC 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6705	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D PIPE LOCATED NORTH END OF SC 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6706	WHITER PLASTER MATERIAL COLLECTED FROM A 12" O.D. VALVE LOCATED NORTH SC 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6707	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH OF SC 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6708	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED NORTH OF ASC 7-1 NEAR WEST WALL.	NON ASBESTOS
WTC-6709	WHITE PLASTER MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED NORTH OF ACS 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6710	OUTER CLOTH MATERIAL COLLECTED FROM THE BASE OF THE FREEZ PROTECTOR LOCATED NORTH OF ACS 7-1 ON A 14" O.D. COUPLING.	NON ASBESTOS
R-WTC-6711	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NORTH ACS 7-1 ON A NEAR WEST WALL.	NON ASBESTOS
R-WTC-6712	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH OF SC 7-1 ON A NEAR WEST WALL.	NON ASBESTOS
R-WTC-6713	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED NORTH OF ACR 7-10 ON A NEAR WEST WALL.	NON ASBESTOS
R-WTC-6714	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED ACR 7-10 ON A NEAR WEST WALL.	NON ASBESTOS
R-WTC-6715	CEMENTITIOUS MATERIAL COLLECTED FROM A 2" O.D. ELBOW LOCATED NORTH OF PUMP 7-2 EAST OF SC 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6716	CEMENTITIOUS MATERIAL COLLECTED FROM A 2" O.D. ELBOW LOCATED NORTH OF PUMP 7-2 EAST OF SC 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6717	CEMENTITIOUS MATERIAL COLLECTED FROM A 2" O.D. ELBOW LOCATED NORTH OF PUMP 7-2 EAST OF SC 7-1 EAST OF SC 7-1	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6718	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 2" O.D. PIPE LOCATED NORTH PUMP 7-2 EAST OF SC7-1.	NON ASBESTOS
R-WTC-6719	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NORTH OF PUMP 7-2 EAST OF SC7-1.	NON ASBESTOS
R-WTC-6720	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH OF PUMP 7-2 EAST OF SC7-1.	NON ASBESTOS
R-WTC-6721	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED NORTH OF PUMP 7-2 EAST OF SC7-1.	NON ASBESTOS
R-WTC-6722	OUTER WHITER PLASTER MATERIAL COLLECTED FROM A 12" O.D. COUPLING LOCATED NORTH OF PUMP 7-2 EAST OF SC 7-1	NON ASBESTOS
-WTC-6723	WHITER PLASTER MATERIAL COLLECTED FROM A 14" O.D. VALVE LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6724	VINYL LIKE MATERIAL COLLECTED FROM A 10" O.D ELBOW LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6725	PAPER AND FOIL LIKE COLLECTED FROM A 16" O.D COUPLING LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6726	CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D ELBOW LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6727	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6728	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS
R-WTC-6729	WHITE PLASTER MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NORTH OF PUMP 7-1 EAST OF SC 7-1	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6671	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6672	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-6673	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-4.	NON ASBESTOS
R-WTC-6674	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS ST OF ACS 7-4.	NON ASBESTOS
R-WTC-6675	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-4.	NON ASBESTOS
-WTC-6676	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6677	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6678	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH WEST OF ACS 7-11.	NON ASBESTOS
R-WTC-6679	INNER FIBROUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH WEST OF ACS 7-1 WEST WALL.	NON ASBESTOS
R-WTC-6680	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH WEST OF ACS 7-1 WEST WALL.	NON ASBESTOS
R-WTC-6681	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH WEST OF ACS 7-10 WEST WALL.	NON ASBESTOS
R-WTC-6682	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH WEST OF ACS 7-10 WEST WALL.	NON ASBESTOS
R-WTC-6683	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 30' WATER COOLING TANK SC 7-1 ALONG WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6684	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED SOUTH END OF SC 7-1 WEST WALL NORTH OF ACS 7-11	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6685	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. FITTING SOUTH END OF SC 7-1 WEST WALL NORTH OF ACS 7-11	NON ASBESTOS
R-WTC-6686	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. TANK HX 7-1 WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6687	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D. HX 7-1 TANK WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6688	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW NORTH END OF HX 7-1 LOCATED WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6689	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING NORTH END OF HX 7-1 WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
-WTC-6690	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW NORTH END OF HX 7-1 WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6691	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 18" O.D. COUPLING NORTH END OF HX 7-1 WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6692	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 18" O.D. VALVE NORTH HX 7-1 WEST WALL NORTH OF ACS 7-11.	NON ASBESTOS
R-WTC-6693	OUTER PAPER AND FOIL KIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE/HOUSING SOUTH END OF PUMP P7-1EAST OF SC7-1	NON ASBESTOS
R-WTC-6694	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE HOUSING SOUTH END OF PUMP 9 7-1, EAST OF SC 7-1.	NON ASBESTOS
R-WTC-6695	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 12" O.D. ELBOW SOUTH END OF P 7-1, EAST OF SC 7-1	NON ASBESTOS
R-WTC-6696	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. PIPE ABOVE P 7-1, EAST OF SC 7-1	NON ASBESTOS
R-WTC-6697	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 16" O.D. COUPLING LOCATED NORTH END OF SC 7-1 NEAR WEST WALL.	NON ASBESTOS
R-WTC-6698	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED NORTH END OF SC 7-1 WEST WALL.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 013

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6699	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 12" O.D. ELBOW LOCATED NORTH END OF SC 7-1 WEST WALL.	NON ASBESTOS
R-WTC-6700	WHITE PLASTE LIKE MATERIAL COLLECTED FROM A 16" O.D. VALVE/HOUSING AT NO RTH END OF SC 7-1 WEST WALL.	NON ASBESTOS
R-WTC-6701	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. ELBOW AT NORTH END OF SC 7-1 WST WALL.	NON ASBESTOS
R-WTC-6702	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 10" O.D. COUPLING AT NORTH END OF SC 7-1 WEST WALL	NON ASBESTOS
R-WTC-6703	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 16" O.D COUPLING LOCATED AT NORH END OF SC 7-1 NEAR WEST WALL.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 014

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6575	PAPER AND FOIL LIKE TAPE MATERIAL COLLECTED FROM 8" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR NORTH WEST QUADRANT.	NON ASBESTOS
R-WTC-6576	MOLDED SECTION MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR NORTH WEST QUADRANT.	40% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS
R-WTC-6577	PAPER AND FOIL LIKE OUTER COVERING MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6578	GRAY MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED SOUTH OF ACS 7-13 20' ABOVE FLOOR.	60% AMOSITE ASBESTOS
R-WTC-6579	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED EAST OF ACS 7-13 20' ABOVE FLOOR NORTH WEST QUADRANT	NON ASBESTOS
WTC-6580	GRAY MOLDED SECTION MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED EAST OF ACS 7-13 20' ABOVE FLOOR NORTH WEST QUADRANT	25% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
R-WTC-6581	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED EAST OF ACS 7-13 20' ABOVE FLOOR NORTH EAST QUADRANT.	NON ASBESTOS
R-WTC-6582	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED EAST OF ACS 7-5 20' ABOVE FLOOR NOR TH EAST QUADRANT.	NON ASBESTOS
R-WTC-6583	GRAY MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. LOCATED EAST OF ACS 7-5 20' ABOVE FLOOR NORTH EAST QUADRANT.	40% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS
R-WTC-6651	OUTER PAPER AND FOIL AND TAR MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED ON TOP OF SUB STATION WEST OF ACS 7-6	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 015

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6652	GRAY MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ON TO OF SUBSTATION WEST OF ACS 7-6 N.E. Q.	70% AMOSITE ASBESTOS
R-WTC-6653	WHITE MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-6 NORTH EAST QUADRANT	60% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
R-WTC-6654	WHITE MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-6 NORTH EAST QUADRANT	60% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 016

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: M.E.R. UPPER LEVEL SE QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6730	MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ABOVE SUB STATION EAST OF ACS 7-8.	40% AMOSITE ASBESTOS 15% CHRYSOTILE ASBESTOS
R-WTC-6731	MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED ABOVE SUB STATION EAST OF ACS 7-8.	50% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS
R-WTC-6732	MOLDED SECTION MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED ABOVE SUB STATION EAST OF ACS 7-8.	80% AMOSITE ASBESTOS
R-WTC-6733	MOLDED SECTION MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED ABOVE SUB STATION EAST OF ACS 7-8.	80% AMOSITE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 017

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6666	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED NORTH OF TANK HX-7-5.	NON ASBESTOS
R-WTC-6667	GRAY MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED NORTH OF TANK HX-7-5. (S.E. GRANT)	70% AMOSITE ASBESTOS
R-WTC-6668	WHITE MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-10 ABOVE SUB STATION (S.E. GRANDANT)	50% AMOSITE ASBESTOS 15% CHRYSOTILE ASBESTOS
R-WTC-6669	WHITE MOLDED SECTION MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-10 ABOVE SUB STATION (S.E. GRANDANT)	NON ASBESTOS
R-WTC-6670	GRAY MOLDED SECTION MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED WEST OF ACS 7-10 ABOVE SUB STATION (S.E. GRANDANT)	70% AMOSITE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6735	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4 " O.D. ELBOW LOCATED NORTH OF HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6736	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4 " O.D. VALVE (#43) LOCATED NORTH OF HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6737	INNER CEMENTITOUS MATERIAL COLLECTED FROM A 4" O.D. VALVE (#43) LOCATED NORTH OF HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6738	OUTER PAPER AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH OF HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6739	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH OF HOT WATER WATER # 2 NEAR (WEST WALL)	NON ASBESTOS
WTC-6740	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH OF HOT WATER HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6741	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF HOT WATER HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6742	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF HOT WATER HEATER #7A2A (WEST WALL)	NON ASBESTOS
R-WTC-6743	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF FIRE SPRINKLER PUMP STATION NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6744	OUTER PAPE AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF FIRE SPRINKLER PUMP STATION NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6745	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF FIRE SPRINKLER PUMP STATION NEAR (WEST WALL	NON ASBESTOS
R-WTC-6746	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST ACR 7-10 NEAR WEST WALL	NON ASBESTOS
R-WTC-6747	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED EAST OF FIRE SPRINKLER PUMP STATION NEAR HALLWAY	NON ASBESTOS
R-WTC-6748	INNER CEMENTITIOUS MATERIAL COLLECTED FROM 8" O.D. ELBOW LOCATED EAST OF FIRE SPRINKLER PUMP STATION NEAR HALLWAY	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6749	OUTER CLOTH LIKE MATERIAL COLLECTED FROM 8" O.D. FITTING LOCATED EAST OF FIRE SPRINKLER PUMP STATION NEAR HALLWAY	NON ASBESTOS
R-WTC-6750	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 8" O.D. FITTING LOCATED EAST OF FIRE SPRINKLER PUMP STATION NEAR EAST WALL	NON ASBESTOS
R-WTC-6751	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED AT SOUTH EAST CORNER OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6752	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED AT SOUTH EAST CORNER OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6753	OUTER CLOTH MATERIAL COLLECTED FROM AN 10" O.D. VALVE LOCATED AT SOUTH EAST CORNER OF PRV RIG NEAR EAST WALL	NON ASBESTOS
-WTC-6754	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NEAR SOUTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6755	OUTER CLOTH MATERIAL COLLECTED FROM A PRESURE GARGE LOCATED NEAR SOUTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6756	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A PRESSURE GARGE LOCATED NEAR SOUTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6757	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED AT NORTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6758	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED AT NORTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6759	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED AT NORTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6760	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 6" O.D. LOCATED AT NORTH EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6761	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. "T" LOCATED AT NORTH EAST CORNER OF PRV RIG	NON ASBESTOS
R-WTC-6762	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6763	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 10" O.D. PIPE LOCATED EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6764	TAR MATERIAL COLLECTED FROM INSIDE PAPER AND FOIL OUTER COVERING LOCATED ON A 10" O.D. PIPE EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6765	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. PIPE ELBOW LOCATED EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6766	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10 O.D. PIPE ELBOW LOCATED EAST OF PRV RIG NEAR EAST WALL	NON ASBESTOS
R-WTC-6767	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF CENTER OF PRV RIG	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6734	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF HOT WATER HEATER # 2 NEAR (WEST WALL)	NON ASBESTOS
R-WTC-6765	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6768	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF CENTER OF PRV RIG	NON ASBESTOS
R-WTC-6769	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED NORTH SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6770	OUTER PAPER AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6771	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6772	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6773	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6774	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6775	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED WEST SIDE OF PRV RIG	NON ASBESTOS
R-WTC-6776	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH WEST SECTION OF PRV RIG	NON ASBESTOS
R-WTC-6777	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4"O.D. ELBOW LOCATED SOUTH WEST SECTION OF PRV RIG	NON ASBESTOS
R-WTC-6778	OUTER CLOTH LIKE MATERIAL COLLECTED FROM AN 8" O.D. "T" FITTING LOCATED SOUTH WEST SECTION OF PRV RIG.	NON ASBESTOS
R-WTC-6779	INNER CEMENTITIOUS MATERIAL COLLECT ED FROM AN 8" O.D. "T" FITTING LOCATED SOUTH WEST SECTION OF PRV RIG.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6780	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH END OF PRV RIG	NON ASBESTOS
R-WTC-6781	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10" O.D. VALVE LOCATED SOUTH END OF PRV RIG	NON ASBESTOS
R-WTC-6782	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED SOUTH END OF PRV RIG	NON ASBESTOS
R-WTC-6783	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED SOUTH END OF PRV RIG	NON ASBESTOS
R-WTC-6784	OUTER CLOTH LIKE MATERIAL COLLECTED ROM A 4" O.D. ELBOW LOCATED SOUTH OF PRV RIG	NON ASBESTOS
R-WTC-6785	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF PRV RIG	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUODRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6786	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6787	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6788	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A FROM A 6"O.D. VALVE LOCATED WEST OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6792	A BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-5	NON ASBESTOS
R-WTC-6793	A BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-1	NON ASBESTOS
WTC-6794	A BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-9	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 018

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUOCDRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6789	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 6" O.D. VALVE LOCATED WEST OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6790	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 6" O.D. VALVE LOCATED WEST OF WATER HEATER PH 7A-1	NON ASBESTOS
R-WTC-6791	A BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-5	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 019

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6807	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF ACS 7-6	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 020

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: HALLWAY

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6795	A BLACK TAR LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE LOCATED AT WEST END OF HALLWAY	NON ASBESTOS
R-WTC-6796	BLACK TAR LIKE MATERIAL COLLECTED FROM A 8" O.D. PIPE LOCATED AT WEST E ND OF HALLWAY 10' FROM END	NON ASBESTOS
R-WTC-6797	OUTER CLOTH LIKE MATERIAL COLLECTED FROM AN 8" O.D. PIPE "T" FITTING LOCATED 15' FROM WEST END OF HALLWAY	NON ASBESTOS
R-WTC-6798	INNER CEMENTITIOUS MATERIAL COLLECTD FROM AN 8" O.D. FITTING LOCATED 15' FROM WEST END OF HALLWAY	NON ASBESTOS
R-WTC-6799	INNER CEMENTITIOUS MATERIAL COLLECTED FROM AN 8" O.D. FITTING LOCATED 30' FROM WEST END OF HALLWAY	NON ASBESTOS
WTC-6800	OUTER CLOTH LIKE MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED AT CENTER OF HALLWAY	5% CHRYSOTILE ASBESTOS
R-WTC-6801	INNER CEMENTITIOUS MATERIAL COLLECTED FROM AN 8" O.D. ELBOW LOCATED AT CENTER OF HALLWAY	NON ASBESTOS
R-WTC-6802	INNER CEMENTITIOUS MATERIAL COLLECTED FROM AN 4" O.D. ELBOW LOCATED AT EAST END OF HALLWAY - 30' FROM END	NON ASBESTOS
R-WTC-6803	A BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED AT 25' FROM END OF HALLWAY	NON ASBESTOS
R-WTC-6804	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH AT EAST END OF HALLWAY	NON ASBESTOS
R-WTC-6805	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF SC 7-2	NON ASBESTOS
R-WTC-6806	FOIL AND TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED SOUTH OF SC 7-2	NON ASBESTOS
R-WTC-6815	OUTER CLOTH MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED SOUTH OF SC 7-2	NON ASBESTOS
R-WTC-6816	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 10"O.D. VALVE IN ROOM JUST OUTSIDE BATHROOM OFF HALLWAY	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 021

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUODRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6808	BLACK TAR MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-10	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 022

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6809	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-8.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 023

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPERLEVEL-NORTH EAST QUODRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6810	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED ABOVE SUB STATION IN NORTH EAST QUADRANT	NON ASBESTOS
R-WTC-6811	TAR LIKE MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED ABOVE SUB STATION IN NORTH EAST QUADRANT	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 024

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6812	TAR LIKE MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED ABOVE SUB STATION IN NORTH WEST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 025

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6813	TAR LIKE AND FOIL MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED ABOVE SUB STATION IN SOUTH WEST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 026

ACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6814	TAR LIKE AND FOIL MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED ABOVE SUB STATION IN SOUTH EAST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 027

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6817	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. VALVE LOCATED NORTH OF HOT WATER HEATER #2	NON ASBESTOS
R-WTC-6818	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. VALVE LOCATED NORTH OF HOT WATER HEATER #2.	NON ASBESTOS
R-WTC-6819	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH OF HOT WATER HEATER #2.	NON ASBESTOS
R-WTC-6820	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF HOT WATER HEATER #2.	NON ASBESTOS
R-WTC-6821	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED NORTH OF HOT WATER HEATER #2.	NON ASBESTOS
R-WTC-6822	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED NORTH OF HOT WATER HEATER #2.	NON ASBESTOS
R-WTC-6823	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. VALVE LOCATED IN FRONT OF HOT HEATER 7A 2B.	NON ASBESTOS
R-WTC-6824	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. VALVE LOCATED IN FRONT OF HOT HEATER 7A 2B.	NON ASBESTOS
R-WTC-6825	BLACK TAR AND FOIL MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED EAST OF HOT WATER HEATER 7A 2A AND 2B.	NON ASBESTOS
R-WTC-6826	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED SOUTH OF HOT WATER HEATER 7A 2A.	NON ASBESTOS
R-WTC-6827	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6828	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6829	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6830	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF WATER TANK PH 7A-1.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 027

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6831	BLACK TAR AND FOIL LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6832	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED ON TOP OF WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6833	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED ABOVE WATER TANK PH 7A-1.	NON ASBESTOS
R-WTC-6834	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF PRV RIG.	NON ASBESTOS
R-WTC-6835	AN INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED SOUTH OF PRV RIG.	NON ASBESTOS
R-WTC-6836	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED SOUTH OF PRV RIG.	NON ASBESTOS
R-WTC-6837	BLACK TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED SOUTH OF PRV RIG.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 028

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: HALLWAY

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6838	OUTER CLOTH MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED AT FAR WEST END OF HALLWAY	NON ASBESTOS
R-WTC-6839	INNER CEMENTITIOUS MATERIAL COLLECTED FROM 3" O.D. PIPE LOCATED AT FAR END OF HALLWAY	NON ASBESTOS
R-WTC-6840	TAR LIKE MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED 10'FROM THE WEST END OF HALLWAY	NON ASBESTOS
R-WTC-6841	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. FITTEN LOCATED MID-HALLWAY JUST OUTSIDE BATHROOM.	NON ASBESTOS
R-WTC-6842	INNER CEMETITIOUS MATERIAL COLLECTED FROM A 4" O.D. FITTENG ELBOW LOCATED JUST WEST OF INTERSECTION OF TWO HALLWAYS.	NON ASBESTOS
R-WTC-6843	INNER CEMETITROUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED JUST OUTSIDE BATHROOM.	NON ASBESTOS
R-WTC-6844	TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED JUST WEST OF INTERSECTION OF TWO HALLWAYS.	NON ASBESTOS
R-WTC-6845	OUTER CLOTH MATERIAL COLLECTED FROM 4" O.D. ELBOW LOCATED JUST WEST OF INTERSECTION OF TWO HALLWAYS.	NON ASBESTOS
R-WTC-6846	INNER CEMENTITIOUS MATERIAL COLLECTED FROM 4" O.D. ELBOW LOCATED JUST INTERSECTION OF TWO HALLWAYS.	NON ASBESTOS
R-WTC-6847	TAR AND FOIL LIKE MATERIAL COLLECTED FROM 3" O.D. ELBOW LOCATED EAST OF INTERSECTION OF TWO HALLWAYS 10' ABOVE FLOOR.	NON ASBESTOS
R-WTC-6848	OUTER CLOTH MATERIAL COLLECTED FROM 3" O.D. ELBOW LOCATED EAST OF INTERSECTION OF TWO HALLWAYS 10' AB VE FLOOR.	NON ASBESTOS
R-WTC-6849	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED EAST OF INTERSECTION OF TWO HALLWAYS 10' ABOVE FLOOR	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 029

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6850	TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED ABOVE SUB STATION IN NORTH EAST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 030

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6851	TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED ABOVE SUB STATION IN NORTH WEST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 031

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6852	TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED ABOVE SUB STATION IN SOUTH WEST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 032

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: UPPER LEVEL SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6853	TAR LIKE MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED ABOVE SUB STATION IN SOUTH EAST QUADRANT.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 033

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6854	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6855	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6856	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6857	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6858	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED WEST OF ACS 7-13	NON ASBESTOS
-WTC-6859	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6860	INNER BROWN MASTIC MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED WEST OF ACS 7-13	NON ASBESTOS
R-WTC-6861	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-13	NON ASBESTOS
R-WTC-6862	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-13	NON ASBESTOS
R-WTC-6863	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED EAST OF ACS 7-13	NON ASBESTOS
R-WTC-6864	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-13	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 033

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6865	BROWN MASTIC MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-13	NON ASBESTOS
R-WTC-6866	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-5	NON ASBESTOS
R-WTC-6867	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-5	NON ASBESTOS
R-WTC-6868	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED WEST OF ACS 7-5	NON ASBESTOS
R-WTC-6869	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-5	NON ASBESTOS
WTC-6870	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST ACS 7-5	NON ASBESTOS
R-WTC-6871	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED FROM EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6872	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED FROM EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6873	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED FROM WEST OF ACS 7-1	NON ASBESTOS
R-WTC-6874	BLACK TAR LIKE MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED EAST OF ACS 7-5	NON ASBESTOS
R-WTC-6875	OUTER CLOTH MATERIAL COLLECTED FROM A 3" O.D. PIPE LOCATED WEST OF ACS 7-1	NON ASBESTOS
R-WTC-6876	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. ELBOW LOCATED WEST OF ACS 7-1	NON ASBESTOS
R-WTC-6877	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-1	NON ASBESTOS
R-WTC-6878	CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. VALVE LOCATED WEST OF ACS 7-9	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 033

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6879	OUTER CLOTH MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6880	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6881	BROWN MASTIC MATERIAL COLLECTED FROM A 5" O.D. PIPE LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6882	CEMENTITOUS MATERIAL COLLECTED FROM A 2" O.D. FITTING LOCATED WEST OF ACS 7-9	NON ASBESTOS
R-WTC-6883	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. FITTING LOCATED WEST OF ACS 7-9	NON ASBESTOS
-WTC-6884	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED SOUTH OF ACRS 7-12	NON ASBESTOS
R-WTC-6885	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED SOUTH OF ACRS 7-12	NON ASBESTOS
R-WTC-6886	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED SOUTH OF ACRS 7-12	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6888	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS
R-WTC-6889	CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-6	NON ASBESTOS
R-WTC-6890	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6891	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-6.	NON ASBESTOS
R-WTC-6892	TAR LIKE MATERIAL COLLECTED FROM INSIDE OUTER CLOTH MATERIAL FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-6	NON ASBESTOS
R-WTC-6893	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6894	OUTER CLOTH MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6895	OUTER CLOTH MATERIAL COLLECTED FROM A 10" O.D. ELBOW LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6896	TAR LIKE MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6897	CEMENTITIOUS MATERIAL COLLECTED FROM A 4"O.D. ELBOW LOCATED EAST OF ACS 7-2	NON ASBESTOS
R-WTC-6898	CEMENTITIOUS MATERIAL COLLECTED FROM A 3"O.D. ELBOW LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6899	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6900	TAR LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-14	NON ASBESTOS
R-WTC-6901	MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED NORTH WEST OF ACR 1-13	35% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER NORTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6902	MOLDED SECTION MATERIAL COLLECTED FROM A 12" O.D. PIPE LOCATED NORTH WEST OF ACR 1-13	35% AMOSITE ASBESTOS 5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 034

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-6887	OUTER CLOTH MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-6.	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-7100	A VINYL LIKE OUTER COVERING COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-12	NON ASBESTOS
R-WTC-7101	A CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-12	NON ASBESTOS
R-WTC-7102	A CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF OF ACS 7-12	NON ASBESTOS
R-WTC-7102	A VINYL LIKE MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED EAST OF ACS 7-12	NON ASBESTOS
R-WTC-7103	A WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED EAST OF ACS 7-12	NON ASBESTOS
-WTC-7104	WHITE PLASTER LIKE AND HORSE HAIR MATERIAL COLLECTED FROM A 8" O.D. VALVE LOCATED EAST OF ACS 7-12	NON ASBESTOS
R-WTC-7105	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7106	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7107	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 4" O.D. FITTING LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7108	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. FITTING LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7109	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. FITTING LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7110	OUTER CLOTH AND WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-7111	OUTER CLOTH LIKE MATERAIL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-12	NON ASBESTOS
R-WTC-71113	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. VALVE LOCATED EAST OF ACS 7-7	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-7112	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. VALVE LOCATED EAST OF ACS 7-12	NON ASBESTOS
R-WTC-7114	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 4" O.D. FITTING LOCATED EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7115	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7116	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. VALVE LOCATED 12' ABOVE FLOOR AND EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7117	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. FITTING LOCATED 12' ABOVE FLOOR AND EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7118	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 8" O.D. FITTING LOCATED 12' ABOVE FLOOR AND EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7119	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED 12' ABOVE FLOOR AND EAST OF ACS 7-7	NON ASBESTOS
R-WTC-7120	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED 12' ABOVE FLOOR AND WEST OF ACS 7-7	NON ASBESTOS
R-WTC-7121	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. VALVE LOCATED 12' ABOVE FLOOR AND WEST OF ACS 7-7	NON ASBESTOS
R-WTC-7122	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. VALVE LOCATED WEST OF ACS 7-7	NON ASBESTOS
R-WTC-7123	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D ELBOW LOCATED WEST OF ACS 7-7	NON ASBESTOS
R-WTC-7124	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D ELBOW LOCATED EAST OF ACS 7-3	NON ASBESTOS
R-WTC-7125	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D ELBOW LOCATED EAST OF ACS 7-3	NON ASBESTOS
R-WTC-7126	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED EAST OF ACS 7-3	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 035

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTH EAST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-7127	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-7128	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-3	NON ASBESTOS
R-WTC-7129	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS
R-WTC-7130	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS
R-WTC-7131	INNER CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS
-WTC-7132	OUTER VINYL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-10	NON ASBESTOS
R-WTC-7133	WHITE PLASTER MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS
R-WTC-7134	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS
R-WTC-7135	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3' O.D. ELBOW LOCATED WEST OF ACS 7-10	NON ASBESTOS

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 036

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: LOWER SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-7136	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-8	NON ASBESTOS
R-WTC-7137	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED EAST OF ACS 7-8	<1% TREMOLITE ASBESTOS
R-WTC-7138	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED EAST OF ACS 7-8.	NON ASBESTOS
R-WTC-7139	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-7140	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-7141	OUTER VINYL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-8.	NON ASBESTOS
R-WTC-7142	INNER WHITE CEMENTITOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED WEST OF ACS 7-8	NON ASBESTOS
R-WTC-7143	WHITE PLASTER LIKE MATERIAL COLLECTED FROM A 4" O.D. FITTING LOCATED WEST OF ACS 7-8	NON ASBESTOS
R-WTC-7144	INNER WHITE CEMENTITIOUS MATERIAL COLLECTED FROM A 3" O.D. ELBOW LOCATED EAST OF ACS 7-4	NON ASBESTOS
R-WTC-7145	OUTER CLOTH LIKE-MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-4	NON ASBESTOS
R-WTC-7146	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED EAST OF ACS 7-4	NON ASBESTOS
R-WTC-7147	OUTER VINYL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED EAST OF ACS 7-11.	NON ASBESTOS
R-WTC-7148	OUTER CLOTH LIKE MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED WEST OF ACS 7-4.	NON ASBESTOS
R-WTC-7149	OUTER VINYL LIKE MATERIAL COLLECTED FROM A 6" O.D. PIPE LOCATED WEST OF ACS 7-4.	NON ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 147
SURVEY # 040

.ITY: WORLD TRADE CENTER
'ION:
DESCRIPTION: LOWER SOUTH WEST QUADRANT

BUILDING: 1
FLOOR: 7

E R	LOCATION	RESULT
:-6919	WHITE PLASTER MATERIAL COLLECTED FROM A 6" O.D. COUPLING LOCATED WEST OF ACS 7-8.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 406
SURVEY #

CILITY: WORLD TRADE CENTER
.OCATION: ROOM # 2067 / CORE CORRIDOR
AREA DESCRIPTION:

BUILDING: 1 WTC
FLOOR: 20

SAMPLE NUMBER	LOCATION	RESULT
WTC-30498	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A DECK 12' NORTH OF CORE WALL FROM THE ENTRANCE OF SUITE # 2067, AND 6' WEST OF ENTRANCE.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30499	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM 13 1/2 ' NORTH OF CORE WALL FROM THE ENTRANCE OF SUITE # 2067, AND 6' WEST OF ENTRANCE.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30500	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A DECK, 14' NORTH OF CORE WALL FROM THE ENTRANCE OF SUITE # 2067, AND 3' WEST OF ENTRANCE.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30501	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED BETWEEN COLUMNS # 127 AND 128 LOCATED 28 1/2' SOUTH OF DECK.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
'C-30502	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED BETWEEN COLUMNS # 127 AND 128 LOCATED 30' SOUTH OF DECK.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30503	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED 23' SOUTH OF COLUMN # 131.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30504	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED 23' SOUTH OF COLUMN # 133.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30505	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM DECK LOCATED 23' SOUTH OF COLUMN # 133 AND 1' EAST OF BEAM.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 406
SURVEY #

CILITY: WORLD TRADE CENTER
/CATION:
AREA DESCRIPTION: NORTH

BUILDING: 1 WTC
FLOOR: 37

SAMPLE NUMBER	LOCATION	RESULT
WTC-29938	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMN # 136 & # 137, 25' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29939	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMNS # 136 & # 137, 22' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29940	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM DECK LOCATED BETWEEN COLUMNS # 134 & # 135, 25' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29941	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMNS # 130 & # 131, 22' SOUTH OF NORTH PERIMETER.	NON ASBESTOS SAMPLE DATE: 06/12/91
WTC-29942	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM CROSS BEAM LOCATED BETWEEN COLUMNS # 138 & # 139, 9' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29943	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMNS # 136 AND # 137, 9' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29944	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMNS # 134 AND # 135, 9' SOUTH OF NORTH PERIMETER.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29945	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED BETWEEN COLUMNS # 132 AND # 133, 6' SOUTH OF NORTH PERIMETER.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/12/91
WTC-29946	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM NORTH PERIMETER WALL LOCATED BETWEEN COLUMNS # 130 AND # 131.	NON ASBESTOS SAMPLE DATE: 06/12/91

..UTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 406
SURVEY #

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: ESCALATOR

BUILDING: 1 WTC
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-29947	PLASTER MATERIAL COLLECTED FROM WEST SIDE OF ESCALATOR, 16' NORTH OF EXIT "DOWN" SIGN.	NON ASBESTOS SAMPLE DATE: 06/12/91
WTC-29948	PLASTER MATERIAL COLLECTED FROM NORTH SIDE (UNDER SIDE) OF ESCALATOR CENTER.	NON ASBESTOS SAMPLE DATE: 06/12/91
WTC-29949	PLASTER MATERIAL COLLECTED FROM (EAST SIDE) OF ESCALATOR, 16' NORTH OF ENTER "UP" SIGN.	NON ASBESTOS SAMPLE DATE: 06/12/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 410
SURVEY #

CILITY: WORLD TRADE CENTER
OCATION:
AREA DESCRIPTION: JOY PUMP ROOM

BUILDING: 1
FLOOR: B-6

SAMPLE NUMBER	LOCATION	RESULT
WTC-29450	INNER LAYER OF FIBROUS PIPE INSULATION COLLECTED FROM 12" O.D. PIPE.	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29451	INNER LAYER OF FIBROUS PIPE INSULATION COLLECTED FROM 12" O.D. PIPE.	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29452	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM EAST SIDE (BEAM RUNS EAST TO WEST).	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29453	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM WEST SIDE (BEAM RUNS EAST TO WEST).	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29454	GASKET MATERIAL COLLECTED.	NON ASBESTOS SAMPLE DATE: 05/08/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 411
SURVEY #

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: OLD VALVE ROOM / PIT AREA

BUILDING: 1
FLOOR: SUB-LEVEL

SAMPLE NUMBER	LOCATION	RESULT
WTC-29199	CEMENTITIOUS PIPE JOINT INSULATION MATERIAL TAKEN FROM 6" O.D PIPE ON SOUTH SIDE OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91
WTC-29200	CEMENTITIOUS PIPE JOINT INSULATION MATERIAL TAKEN FROM 6" O.D. PIPE ON NORTH SIDE OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91
WTC-29201	CEMENTITIOUS PIPE JOINT INSULATION MATERIAL TAKEN FROM 6" O.D. PIPE IN CENTER OF ROOM.	NON ASBESTOS SAMPLE DATE: 04/03/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 412
SURVEY #

ICILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: ELEVATOR MECHANICAL ROOM

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-29352	FLUFFY FIREPROOFING MATERIAL TAKEN FROM I BEAM ALONG WEST WALL.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91
WTC-29353	CEMENTITIOUS FIREPROOFING MATERIAL TAKEN FROM I BEAM ALONG EAST WALL.	NON ASBESTOS SAMPLE DATE: 05/02/91
WTC-29354	CEMENTITIOUS FIREPROOFING MATERIAL TAKEN FROM I BEAM ALONG EAST WALL.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91
WTC-29355	CEMENTITIOUS FIREPROOFING MATERIAL TAKEN FROM I BEAM ALONG WEST WALL.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 413
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL EQUIPMENT ROOM
AREA DESCRIPTION: ELEVATOR

BUILDING: 1
FLOOR: 26

SAMPLE NUMBER	LOCATION	RESULT
WTC-29362	FLUFFY FIREPROOFING MATERIAL TAKEN FROM EAST WALL OF ELEVATOR MECHANICAL ROOM.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 04/11/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 414
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTHWEST QUADRANT

BUILDING: 1
FLOOR: 37

SAMPLE NUMBER	LOCATION	RESULT
WTC-29785	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR APPROXIMATELY 22' SOUTH OF WET COLUMN #129.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29786	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR APPROXIMATELY 6' SOUTH OF WET COLUMN #125.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29787	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR APPROXIMATELY 28' SOUTH OF WET COLUMN #122.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29788	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR APPROXIMATELY 8' SOUTH OF WET COLUMN #120.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29789	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR APPROXIMATELY 8' SOUTH OF WET COLUMN #123.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29790	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR ON A BEAM APPROXIMATELY 26' SOUTH OF WET COLUMN #122.	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29791	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTHWEST QUADRANT OF 37TH FLOOR ON CROSS BEAM RUNNING EAST/WEST 26' SOUTH OF WET COLUMN #122.	NON ASBESTOS SAMPLE DATE: 06/05/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 415
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR MECHANICAL ROOM

BUILDING: 1
FLOOR: 33

SAMPLE NUMBER	LOCATION	RESULT
WTC-29264	FLUFFY FIREPROOFING MATERIAL TAKEN FROM EAST WALL ADJACENT TO ELEVATOR MECHANICAL ROOM.	NON ASBESTOS SAMPLE DATE: 04/11/91
WTC-29265	CEMENTITIOUS FIREPROOFING MATERIAL TAKEN FROM WEST WALL OF ELEVATOR MECHANICAL ROOM.	NON ASBESTOS SAMPLE DATE: 04/11/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 183
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: BAR (MARKET DINNING)

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-29350	FLUFFY FIREPROOFING TAKEN FROM I BEAM ALONG EAST WALL	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91
WTC-29351	FLUFFY FIREPROOFING TAKEN FROM I BEAM ALONG EAST WALL	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 183
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR MECHANICAL

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-29352	FLUFFY FIREPROOFING TAKEN FROM I BEAM ALONG WEST WALL	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91
WTC-29353	CEMENTITIOUS FIREPROOFING TAKEN FROM I BEAM ALONG EAST WALL	NON ASBESTOS SAMPLE DATE: 05/02/91
WTC-29354	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM I BEAM LOCATED ALONG THE EAST WALL.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91
WTC-29355	CEMENTITIOUS FIREPROOFING TAKEN FROM I BEAM ALONG WEST WALL	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 05/02/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 183
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR MEHANICAL ROOM

BUILDING: 1
FLOOR: 26

SAMPLE NUMBER	LOCATION	RESULT
WTC-29362	FLUFFY FIREPROOFING TAKEN FROM EAST WALL OF ELEVATOR MECHANICAL ROOM	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 04/11/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 183
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR MECHANICAL

BUILDING: 1
FLOOR: 33

SAMPLE NUMBER	LOCATION	RESULT
WTC-29264	FLUFFY FIREPROOFING TAKEN FROM EAST WALL BE ELEVATOR MECHANICAL ROOM	NON ASBESTOS SAMPLE DATE: 04/30/91
WTC-29265	CEMENTITIOUS FIREPROOFING TAKEN FROM WEST WALL OF ELEVATOR MECHANICAL ROOM	NON ASBESTOS SAMPLE DATE: 04/30/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 183
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: JOY PUMP ROOM

BUILDING: 1
FLOOR: B-J

SAMPLE NUMBER	LOCATION	RESULT
WTC-29450	INNER LAYER OF FIBROUS PIPE INSULAT ION COLLECTED FROM 12" O.D. PIPE	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29451	INNER LAYER OF FIBROUS PIPE INSULAT ION COLLECTED FROM 12" O.D. PIPE	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29452	GRAYISH FLUFFY SPRAYED ON FIREPROOFING COLLECTED FROM A BEAM EAST (BEAM RUNS EAST TO WEST)	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29453	GRAYISH FLUFFY SPRAYED ON FIREPROOFING COLLECTED FROM A BEAM WEST SIDE (BEAM RUNS EAST TO WEST)	NON ASBESTOS SAMPLE DATE: 05/08/91
WTC-29454	GASKET MATERIAL	NON ASBESTOS SAMPLE DATE: 05/08/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 219
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTH WEST QUADRANT

BUILDING: 1
FLOOR: 37

SAMPLE NUMBER	LOCATION	RESULT
WTC-29785	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR APPROXIMATELY 22' SOUTH OF WET COLUMN #129	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29786	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR APPROXIMATELY 6' SOUTH OF WET COLUMN #125	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29787	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR APPROXIMATELY 28' SOUTH OF WET COLUMN #122	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29788	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR APPROXIMATELY 8' SOUTH OF WET COLUMN #120	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29789	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR APPROXIMATELY 8' SOUTH OF WET COLUMN #123	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29790	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR ON A BEAM APPROXIMATELY 26' SOUTH OF WET COLUMN #122	NON ASBESTOS SAMPLE DATE: 06/05/91
WTC-29791	GRAYISH FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM IN NORTH WEST QUADRANT OF 37TH FLOOR ON CROSS BEAM RUNNING EAST/WEST 26' SOUTH OF WET COLUMN #122	NON ASBESTOS SAMPLE DATE: 06/05/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 223
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTHEAST & SOUTHWEST RETURN AIR SHAFT

BUILDING: 1WTC
FLOOR: 75TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-30003	GRAY SPRAY ON FIREPROOFING ON COLUMN AT 74TH FLOOR NORTHEAST AIR SHAFT LEFT SIDE OF COLUMN FACING IT	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30004	GRAY SPRAY ON FIREPROOFING ON COLUMN AT 74TH FLOOR NORTHEAST AIR SHAFT RIGHT SIDE OF COLUMN FACING IT	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30005	GRAY SPRAY ON FIREPROOFING FALLOUT MATERIAL ON BEAM IN NORTHEAST AIR SHAFT ADJACENT TO SQUARE DUCT OF THE NORTHEAST AIR SHAFT	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30006	TROWELED ON PATCH MATERIAL IN NORTHEAST COLUMN 15' TO THE LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30007	GRAY SPRAY ON FIREPROOFING IN NORTHEAST AIR SHAFT ON COLUMN 15' TO THE LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30008	GRAY SPRAY ON FIREPROOFING IN SOUTHWEST AIR SHAFT INSIDE SHAFT BEAM	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30009	GRAY SPRAY ON FIREPROOFING SOUTH WEST AIR SHAFT INSIDE SHAFT FALLOUT DEBRIS	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30010	GRAY SPRAY ON FIREPROOFING IN SOUTHWEST AIR SHAFT ON COLUMN 15' INSIDE OF ENTRANCE	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30011	TROWELED ON PATCH MATERIAL IN SOUTHWEST AIR SHAFT ON COLUMN 15' INSIDE OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 224
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTHEAST AND SOUTHWEST AIR SHAFT

BUILDING: 1WTC
FLOOR: 41ST

SAMPLE NUMBER	LOCATION	RESULT
WTC-30012	GRAY SPRAY ON FIREPROOFING, NORTHEAST AIR SHAFT COLUMN 40TH FLOOR INSIDE SHAFT.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30013	GRAY SPRAY ON FIREPROOFING, NORTHEAST AIR SHAFT COLUMN 40TH FLOOR INSIDE SHAFT.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30014	NORTHEAST RETURN AIR SHAFT, GRAY SPRAY ON FIREPROOFING ON THE WALL 9' TO THE RIGHT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30015	NORTHEAST AIR SHAFT, TROWELED ON PATCHED MATERIAL ON THE WALL 9' TO THE RIGHT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30016	GRAY SPRAY ON FIREPROOFING, NORTHEAST RETURN AIR SHAFT, 15' TO THE LEFT OF ENTRANCE COLUMN.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30017	GRAY SPRAY ON FIREPROOFING, NORTHEAST RETURN AIR SHAFT, 30' TO THE LEFT OF ENTRANCE COLUMN.	< 1% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30018	GRAY SPRAY ON FIREPROOFING, SOUTHWEST RETURN AIR SHAFT.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30019	GRAY SPRAY ON FIREPROOFING, SOUTHWEST RETURN AIR SHAFT.	< 1% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30020	TROWELED ON FIREPROOFING PATCH MATERIAL, SOUTHWEST RETURN AIR SHAFT 9' TO THE RIGHT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30021	GRAY SPRAY ON FIREPROOFING BENEATH TROWELED ON PATCH MATERIAL, SOUTHWEST RETURN AIR SHAFT 9' TO THE RIGHT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30022	GRAY SPRAY ON FIREPROOFING, SOUTHWEST RETURN AIR SHAFT, 15' TO THE LEFT OF ENTRANCE COLUMN BOTTOM.	NON ASBESTOS SAMPLE DATE: 06/14/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 224
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: RETURN AIR SHAFT NORTHWEST & SOUTHEAST

BUILDING: 1WTC
FLOOR: 41ST

SAMPLE NUMBER	LOCATION	RESULT
WTC-30028	GRAY SPRAY ON FIREPROOFING, IN NORTHWEST AIR SHAFT ON COLUMN 15'ON THE LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30029	NORTHWEST AIR SHAFT, PATCH MATERIAL ON COLUMN 15' ON THE LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30030	NORTHWEST AIR SHAFT, GRAY SPRAY ON FIREPROOFING ON COLUMN 30' ON THE LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30031	NORTHWEST AIR SHAFT, TROWELED ON PATCH MATERIAL ON COLUMN 30' ON THE LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
TC-30032	SOUTHEAST AIR SHAFT WALL, 9' TO RIGHT OF ENTRANCE TROWELED ON PATCH MATERIAL.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30033	SOUTHEAST AIR SHAFT, GRAY SPRAY ON FIREPROOFING ON WALL 9' TO THE RIGHT OF ENTRANCE BENEATH TROWELED ON PATCH MATERIAL.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30034	SOUTHEAST AIR SHAFT, GRAY SPRAY ON FIREPROOFING ON COLUMN 15' OF THE LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30035	SOUTHEAST AIR SHAFT, TROWELED ON PATCH MATERIAL ON COLUMN 15' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30036	SOUTHEAST AIR SHAFT, GRAY SPRAY ON FIREPROOFING ON COLUMN 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30037	SOUTHEAST AIR SHAFT, TROWELED ON PATCH MATERIAL ON COLUMN 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 237
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTHWEST & NORTHEAST RETURN AIR SHAFT

BUILDING: 1WTC
FLOOR: 41

SAMPLE NUMBER	LOCATION	RESULT
WTC-29890	GRAY SPRAY ON FIREPROOFING FROM BEAM INSIDE SOUTHWEST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29891	GRAY SPRAY ON FIREPROOFING FROM COLUMN INSIDE SOUTHWEST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29892	GRAY SPRAY ON FIREPROOFING FROM COLUMN INSIDE NORTHEAST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 237
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SOUTHWEST & NORTHEAST RETURN AIR SHAFT

BUILDING: 1WTC
FLOOR: 75

SAMPLE NUMBER	LOCATION	RESULT
WTC-29885	GRAY SPRAY ON FIREPROOFING FROM BEAM INSIDE SOUTH WEST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29886	GRAY SPRAY ON FIREPROOFING FROM BEAM INSIDE SOUTH WEST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29887	GRAY SPRAY ON FIREPROOFING FROM BEAM ABOVE SOUTH WEST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29888	GRAY SPRAY ON FIREPROOFING FROM BEAM INSIDE NORTH EAST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91
WTC-29889	GRAY SPRAY ON FIREPROOFING FROM COLUMN INSIDE NORTH EAST RETURN AIR SHAFT	NON ASBESTOS SAMPLE DATE: 06/10/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 27
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST CORNER OF BUILDING
AREA DESCRIPTION: SUIT # 8401

BUILDING: 1
FLOOR: 84

SAMPLE NUMBER	LOCATION	RESULT
WTC-28638	BLACKISH GLUE-LIKE MATERIAL COLLECTED FROM UNDER VINYL TILE NEAR SOUTH WALL APPROXIMATELY 32' WEST OF WINDOWS.	NON ASBESTOS SAMPLE DATE: 02/07/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 27
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST CORNER OF BUILDING
AREA DESCRIPTION: SUIT # 8401

BUILDING: 1
FLOOR: 84

SAMPLE NUMBER	LOCATION	RESULT
WTC-28637	VINYL TILE SAMPLE COLLECTED NEAR SOUTH WALL APPROXIMATELY 32' WEST OF WINDOWS.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/07/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 27
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST QUADRANT
AREA DESCRIPTION: ROOM # 8401

BUILDING: 1
FLOOR: 84

SAMPLE NUMBER	LOCATION	RESULT
WTC-28811	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 140 AND 204.	NON ASBESTOS SAMPLE DATE: 02/19/91
WTC-28812	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 149 AND 204.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/19/91
WTC-28813	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 156 AND 204.	NON ASBESTOS SAMPLE DATE: 02/19/91
WTC-28814	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 156 AND 213.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/19/91
WTC-28815	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 149 AND 213.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/19/91
WTC-28816	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 140 AND 213.	NON ASBESTOS SAMPLE DATE: 02/19/91
WTC-28817	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 140 AND 222.	NON ASBESTOS SAMPLE DATE: 02/19/91
WTC-28818	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 149 AND 222.	NON ASBESTOS SAMPLE DATE: 02/19/91
WTC-28819	BLACK MASTIC UNDER GRAY 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 156 AND 220.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/19/91
WTC-28820	BLACK MASTIC UNDER BEIGE 12"X12" TILE COLLECTED AT INTERSECTION OF COLUMNS 156 AND 220.	NON ASBESTOS SAMPLE DATE: 02/19/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos. Samples collected at the Passenger Ship Terminal after January 1992 will be assigned the "BP_" prefix.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 389
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: SOUTH CORE CORRIDOR
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 25

SAMPLE NUMBER	LOCATION	RESULT
WTC-32059	FALLOUT MATERIAL IN THE SOUTH CORE CORRIDOR IN FRONT OF FREIGHT ELEVATOR.	NON ASBESTOS SAMPLE DATE: 10/04/91
WTC-32060	FALLOUT MATERIAL IN THE SOUTH CORE CORRIDOR NEAR THE BACKDOOR OF ACS SUPPLY ROOM.	NON ASBESTOS SAMPLE DATE: 10/04/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 389
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHWEST
AREA DESCRIPTION: LOADING DOCK

BUILDING: 1
FLOOR: B-1

SAMPLE NUMBER	LOCATION	RESULT
WTC-31849	WTC FLOOR: B-1 LOADING DOCK NORTHWEST SIDE ADJACENT TO TRASH COMPACTOR FIREPROOFING DEBRIS.	NON ASBESTOS SAMPLE DATE: 09/26/91
WTC-31850	WTC FLOOR: B-1 LOADING DOCK NORTHWEST SIDE ADJACENT TO TRASH COMPACTOR FIREPROOFING DEBRIS.	NON ASBESTOS SAMPLE DATE: 09/26/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 401
SURVEY #

CILITY: WORLD TRADE CENTER
.OCATION: NORTH ELECTRICAL CLOSET
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 31

SAMPLE NUMBER	LOCATION	RESULT
WTC-32533	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM THE NORTHWEST SIDE OF THE BEAM LOCATED AT 1 WTC - 31ST FLOOR NORTH ELECTRICAL CLOSET.	NON ASBESTOS SAMPLE DATE: 11/20/91
WTC-32534	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM THE NORTHEAST SIDE OF BEAM LOCATED AT 1 WTC - 31ST FLOOR NORTH ELECTRICAL CLOSET.	NON ASBESTOS SAMPLE DATE: 11/20/91
WTC-32535	PATCHING MATERIAL COLLECTED FROM THE SOUTHEAST SIDE OF THE CONCRETE SOFFIT PATCHING LOCATED AT 1 WTC - 31ST FLOOR NORTH ELECTRICAL CLOSET.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/20/91
WTC-32536	PACTHING MATERIAL COLLECTED FROM THE SOUTHWEST SIDE OF THE CONCRETE SOFFIT LOCATED AT 1 WTC - 31ST FLOOR NORTH ELECTRICAL CLOSET.	NON ASBESTOS SAMPLE DATE: 11/20/91
WTC-32537	FIREPROOFING DEBRIS COLLECTED FROM THE SOUTH WALL LOCATED AT, 1 WTC - 31ST FLOOR NORTH ELECTRICAL CLOSET.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/20/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 406
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: ABOVE PLENUM
AREA DESCRIPTION: SOUTHWEST QUADRANT

BUILDING: 1
FLOOR: 37

SAMPLE NUMBER	LOCATION	RESULT
WTC-29852	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 16' NORTH OF WET COLUMN # 339 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29853	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 30' NORHT OF WET COLUMN # 339 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29854	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 50' NORTH OF WET COLUMN # 333 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29855	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 25' NORTH OF WET COLUMN # 336 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29856	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 35' NORTH OF WET COLUMN # 336 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29857	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 8' NORTH OF WET COLUMN # 344 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29858	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM SAME BEAM AS SAMPLE NUMBER WTC-29857 APPROXIMATELY 40' NORTH OF WET COLUMN # 344.	NON ASBESTOS SAMPLE DATE: 06/07/91
WTC-29859	WHITE FLUFFY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM APPROXIMATELY 40' NORTH OF WET COLUMN # 345 SOUTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 06/07/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 406
SURVEY #

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION:

BUILDING: 1 WTC
FLOOR: 20

SAMPLE NUMBER	LOCATION	RESULT
WTC-30506	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM BEAM LOCATED 23' SOUTH OF COLUMN # 135.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30507	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM DECK LOCATED 23' SOUTH OF COLUMN # 135.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30508	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM DECK, PAINTED GREEN, LOCATED 2 1/2' WEST OF PIPE RUN AND 4' NORTH OF ELEVATOR CASE WALL.	NON ASBESTOS SAMPLE DATE: 07/09/91
WTC-30509	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM DECK, PAINTED GREEN, LOCATED 1/2' EAST OF PIPE RUN AND 5' NORTH OF ELEVATOR CORE WALL.	NON ASBESTOS SAMPLE DATE: 07/09/91
WTC-30493	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A PAINTED GREEN BEAM CORE AREA, 5' WEST OF SUITE # 2067 ENTRANCE AND 2' NORTH OF ELEVATOR CORE WALL (RIGHT OF EAST PIPE).	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30494	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A PAINTED GREEN BEAM CORE AREA, 10' WEST OF SUITE # 2067 ENTRANCE AND 3' NORTH OF ELEVATOR CORE WALL. (LEFT OF WEST PIPE).	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30495	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM INSIDE SUITE # 2067, 2' WEST OF PIPE RUN (1ST ROOM WEST OF ENTRANCE) AND 4' NORTH OF CORE WALL.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30496	GREY SPRAY-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM INSIDE SUITE # 2067, 3' EAST OF PIPE RUN (1ST ROOM WEST OF ENTRANCE) AND 4' NORTH OF CORE WALL.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91
WTC-30497	GREY SPRAY FIREPROOFING MATERIAL COLLECTED FROM A DECK LOCATED INSIDE SUITE # 2067, 2' EAST OF PIPE RUN (1ST ROOM WEST OF ENTRANCE) AND 6' NORTH OF CORE WALL.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/09/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 416
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: ROOM # 1829 AND ROOM # 1849
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 18

SAMPLE NUMBER	LOCATION	RESULT
WTC-28700	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91
WTC-28701	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91
WTC-28702	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, WEST SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91
WTC-28703	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, CENTRAL SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91
WTC-28704	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, CENTRAL SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91
WTC-28705	BLACK MASTIC FROM UNDER 12"X12" YELLOW FLOOR TILE, EAST SIDE.	NON ASBESTOS SAMPLE DATE: 02/11/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 417
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL ELECTRICAL ROOM
AREA DESCRIPTION: NORTHEAST & SOUTHWEST RETURN AIR SHAFT

BUILDING: 1WTC
FLOOR: 75

SAMPLE NUMBER	LOCATION	RESULT
WTC-30003	GRAY SPRAY ON FIREPROOFING ON COLUMN AT 74TH FLOOR NORTHEAST AIR SHAFT FACING LEFT SIDE OF COLUMN.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30004	GRAY SPRAY ON FIREPROOFING ON COLUMN AT 74TH FLOOR NORTHEAST AIR SHAFT FACING RIGHT SIDE OF COLUMN.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30005	GRAY SPRAY ON FIREPROOFING FALLOUT MATERIAL ON BEAM IN NORTHEAST AIR SHAFT ADJACENT TO SQUARE DUCT OF THE NORTHEAST AIR SHAFT.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30006	TROWELED ON PATCH MATERIAL ON COLUMN INSIDE NORTHEAST AIR SHAFT, 15' TO THE LEFT OF DOORWAY.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30007	GRAY SPRAY ON FIREPROOFING ON COLUMN INSIDE NORTHEAST AIR SHAFT, 15' TO THE LEFT OF DOORWAY.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30008	GRAY SPRAY ON FIREPROOFING IN SOUTHWEST AIR SHAFT, INSIDE SHAFT BEAM.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30009	GRAY SPRAY ON FIREPROOFING IN SOUTHWEST AIR SHAFT, INSIDE SHAFT. FALLOUT DEBRIS.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30010	GRAY SPRAY ON FIREPROOFING IN SOUTHWEST AIR SHAFT ON COLUMN. 15' INSIDE OF ENTRANCE.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/14/91
WTC-30011	TROWELED ON PATCH MATERIAL IN SOUTHWEST AIR SHAFT ON COLUMN. 15' INSIDE OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 417
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL ELECTRICAL ROOM
AREA DESCRIPTION: NORTHWEST & SOUTHEAST RETURN AIR SHAFT

BUILDING: 1WTC
FLOOR: 75

SAMPLE NUMBER	LOCATION	RESULT
WTC-30023	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SHAFT ON COLUMN. 15' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30024	TROWELED ON PATCH MATERIAL IN NORTHWEST AIR SHAFT ON COLUMN, 15' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30025	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SHAFT ON COLUMN, 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30026	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SHAFT ON COLUMN, 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30027	TROWELED ON PATCH MATERIAL IN NORTHWEST AIR SHAFT ON COLUMN, 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 418
SURVEY # 002

FACILITY: PORT AUTHORITY BUS TERMINAL
LOCATION:
AREA DESCRIPTION: EAST END MER ABOVE KITCHEN RESTURANT

BUILDING:
FLOOR: 4

SAMPLE NUMBER	LOCATION	RESULT
R-PABT-6300	MASTIC DUCT TAPE MATERIAL COLLECTED FROM A FIBERGLASS DUCT LOCATED AT ABOUT 10' FROM SOUTH WALL AND 12' FROM EAST WALL.	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6301	MOLDED INSULATION MATERIAL COLLECTED FROM A DUCT INSULATION LOCATED AT ABOUT 9' FROM SOUTH WALL AND 4' FROM EAST WALL	45% AMOSITE ASBESTOS 10% CHRYSOTILE ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6302	WET PLASTER INSULATION MATERIAL COLLECTED FROM A 4" O.D. ELBOW LOCATED AT ABOUT 9' FROM SOUTH AND 4' FROM EAST WALL	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6303	MOLDED PIPE MATERIAL COLLECTED FROM A 4" O.D. ELBOW WITH ALUMINUM COVER LOCATED AT ABOUT 15' FROM 4' FROM EAST WALL	60% AMOSITE ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6304	MOLDED PIPE MATERIAL COLLECTED FROM A 6" O.D. PIPE WITH ALUMINUM COVER LOCATED AT ABOUT 13' FROM SOUTH WALL AND 3' FROM EAST WALL	60% AMOSITE ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6305	WET PLASTER INSULATION MATERIAL COLLECTED FROM A 6" O.D. ELBOW LOCATED AT ABOUT 16' FROM SOUTH WALL AND 4' FROM EAST WALL	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6306	WET PLASTER INSULATION MATERIAL COLLECTED FROM A 8" O.D. ELBOW LOCATED AT ABOUT 15' FROM SOUTH WALL AND 4' FROM EAST WALL	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6307	CEMENT PLASTER MATERIAL COLLECTED FROM A CEILING LOCATED THROUGHOUT THE AREA	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6308	WET PLASTER INSULATION MATERIAL COLLECTED FROM A DUCT INSULATION LOCATED AT ABOUT 1' FROM SOUTH WALL AND 4' FROM EAST WALL	NON ASBESTOS SAMPLE DATE: 06/10/91
R-PABT-6309	MOLDED INSULATION MATERIAL COLLECTED FROM A DUCT INSULATION LOCATED AT ABOUT 1' FROM SOUTH WALL AND 4' FROM EAST WALL	NON ASBESTOS SAMPLE DATE: 06/10/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

CILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25213	CEMENTITIOUS INSULATION MATERIAL FROM A 18' BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 2ND FLOOR.	NON ASBESTOS SAMPLE DATE: 07/19/91
R-1WTC-25214	CEMENTITIOUS INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 5TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/19/91
R-1WTC-25215	CEMENTITIOUS INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 21ST FLOOR.	NON ASBESTOS SAMPLE DATE: 07/19/91
R-1WTC-25216	CEMENTITOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE OUTER LAYER OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 25TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/19/91
R-1WTC-25217	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF INNER LAYER OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 25TH FLOOR.	25% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/19/91
1WTC-25218	CEMENTITIOUS INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 36TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/19/91
R-1WTC-25219	CEMENTITIOUS INSULATION MATERIAL FROM A 15" BEAM LOCATED ON THE NORTH WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS SAMPLE DATE: 07/18/91
R-1WTC-25220	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE OUTER LAYER OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 50TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/18/91
R-1WTC-25221	CEMENTITIOUS INSULATION MATERIAL FROM A 36" COLUMN LOCATED ON THE SOUTHEAST CORNER OF THE INNER LAYER OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 50TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/18/91
R-1WTC-25222	CEMENTITIOUS INSULATION MATERIAL FROM A 18" BEAM LOCATED ON THE EAST WALL OF THE ELEVATOR SHAFT FOR CAR # PE 15 AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS SAMPLE DATE: 07/18/91
R-1WTC-25223	FLUFFY FALLOUT INSULATION MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # PE 15.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 07/18/91
R-1WTC-31651	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 77TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

:ILITY: WORLD TRADE CENTER
.CATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31652	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 77TH FLOOR.	NON ASBESTOS
R-1WTC-31653	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 77TH FLOOR.	NON ASBESTOS
R-1WTC-31654	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
1WTC-31655	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-31656	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 15" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-31657	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 75TH FLOOR.	NON ASBESTOS
R-1WTC-31658	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31659	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS
R-1WTC-31660	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS
R-1WTC-31661	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
1WTC-31662	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 61ST FLOOR.	NON ASBESTOS
R-1WTC-31663	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 54TH FLOOR.	NON ASBESTOS
R-1WTC-31664	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 54TH FLOOR.	NON ASBESTOS
R-1WTC-31665	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 54TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

CILITY: WORLD TRADE CENTER
_OCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31666	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE AT THE TOP OF THE 54TH FLOOR.	NON ASBESTOS
R-1WTC-31667	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 47TH FLOOR.	NON ASBESTOS
R-1WTC-31668	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 47TH FLOOR.	NON ASBESTOS
·1WTC-31669	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 47TH FLOOR.	NON ASBESTOS
R-1WTC-31670	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP THE 47TH FLOOR.	NON ASBESTOS
R-1WTC-31671	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-31672	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

:ILITY: WORLD TRADE CENTER
-OCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31673	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-31674	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 41ST FLOOR.	NON ASBESTOS
R-1WTC-31675	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 34TH FLOOR.	NON ASBESTOS
·1WTC-31676	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 34TH FLOOR.	NON ASBESTOS
R-1WTC-31677	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 27TH FLOOR.	1-3% CHRYSOTILE ASBESTOS
R-1WTC-31678	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 27TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-31679	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 27TH FLOOR.	10% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31680	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 27TH FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-31681	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 20TH FLOOR.	1-3% CHRYSOTILE ASBESTOS
R-1WTC-31682	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 20TH FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-31683	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 20TH FLOOR.	10% CHRYSOTILE ASBESTOS
R-1WTC-31684	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 20TH FLOOR.	30% CHRYSOTILE ASBESTOS
R-1WTC-31685	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 13TH FLOOR.	5% CHRYSOTILE ASBESTOS
R-1WTC-31686	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 13TH FLOOR.	20% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31687	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 13TH FLOOR.	1-3% CHRYSOTILE ASBESTOS
R-1WTC-31688	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 13TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-31689	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 8TH FLOOR.	20% CHRYSOTILE ASBESTOS
. 1WTC-31690	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 8TH FLOOR.	20% CHRYSOTILE ASBESTOS
R-1WTC-31691	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 8TH FLOOR.	NON ASBESTOS
R-1WTC-31692	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT TOP OF THE 4TH FLOOR.	NON ASBESTOS
R-1WTC-31693	FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM A 37" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 4TH FLOOR.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 435
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ELEVATOR SHAFT/CARS # PE 14 & PE 15

BUILDING: 1
FLOOR: 1-78

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-31694	TROWELED ON FIREPROOFING MATERIAL COLLECTED FROM A 20" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT FOR CAR # PE 14 AT THE TOP OF THE 4TH FLOOR.	NON ASBESTOS
R-1WTC-31695	TROWELED ON FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR SHAFT FOR CAR # PE 14.	NON ASBESTOS
R-1WTC-31696	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR SHAFT FOR CAR # PE 14.	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 438
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: SHUTTLE ELEVATORS
AREA DESCRIPTION: ELEVATOR CARS # PE 6

BUILDING: 1
FLOOR: B1-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25769	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 3RD FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25770	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 3RD FLOOR.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25771	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTD FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 9TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25772	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 13TH FLOOR.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25773	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 13TH FLOOR.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25774	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 20TH FLOOR.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25775	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 20TH FLOOR.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25776	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 26TH FLOOR.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 438
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: SHUTTLE ELEVATORS
AREA DESCRIPTION: ELEVATOR CARS # PE 6

BUILDING: 1
FLOOR: B1-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25777	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 26THE FLOOR.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25778	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 32ND FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25779	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 39TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25780	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 45TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25781	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 51ST FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25782	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 57ST FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25783	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 63RD FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25784	FLUFFY FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 63RD FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 438
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: SHUTTLE ELEVATORS
AREA DESCRIPTION: ELEVATOR CARS # PE 6

BUILDING: 1
FLOOR: B1-106

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25785	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE AT THE TOP OF THE 68TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25786	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 36" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 74TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25787	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 14" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 78TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25788	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 29" BEAM LOCATED ON THE EAST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 79TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25789	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 24" BEAM LOCATED ON THE WEST SIDE OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 85TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25790	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 14" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 91ST FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25791	CEMENTITIOUS FIREPROOFING MATERIAL COLLECTED FROM A 14" COLUMN LOCATED ON THE NORTHEAST CORNER OF THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 97TH FLOOR.	NON ASBESTOS SAMPLE DATE: 09/14/90
R-1WTC-25792	PLASTER-LIKE FIREPROOFING MATERIAL COLLECTED FROM A BEAM LOCATED ON THE SOUTH SIDE OF THE THE ELEVATOR SHAFT, FOR CAR # PE 6 AT THE TOP OF THE 82ND FLOOR.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 09/14/90

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 469
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: SKIN AREA (EXTERIOR BUILDING)

BUILDING: 1
FLOOR:

SAMPLE NUMBER	LOCATION	RESULT
WTC-32840	GRAY FLUFFY INSULATION COLLECTED FROM THE NORTH SIDE OF WTC # 1 (SKIN AREA).	NON ASBESTOS SAMPLE DATE: 12/16/91
WTC-32841	GRAY FLUFFY INSULATION COLLECTED FROM THE NORTH SIDE OF WTC # 1 (SKIN AREA).	NON ASBESTOS SAMPLE DATE: 12/16/91
WTC-32842	GRAY FLUFFY INSULATION COLLECTED FROM THE SOUTH SIDE OF WTC # 1 (SKIN AREA).	NON ASBESTOS SAMPLE DATE: 12/16/91
WTC-32843	GRAY FLUFFY INSULATION COLLECTED FROM THE SOUTH SIDE OF WTC # 1 (SKIN AREA).	NON ASBESTOS SAMPLE DATE: 12/16/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 472
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: DUANE READE
AREA DESCRIPTION:

BUILDING: 1
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-32801	WTC - CONCOURSE LEVEL DUANE READE, GREY SPRAYED ON FIREPROOFING MATERIAL ON THE NORTHWEST SIDE.	NON ASBESTOS SAMPLE DATE: 12/12/91
WTC-32802	WTC - CONCOURSE LEVEL DUANE READE, GREY SPRAYED ON FIREPROOFING ON THE NORTH SIDE.	NON ASBESTOS SAMPLE DATE: 12/12/91
WTC-32803	WTC - CONCOURSE LEVEL DUANE READE, GREY SPRAYED ON FIREPROOFING ON THE NORTH SIDE.	NON ASBESTOS SAMPLE DATE: 12/12/91
WTC-32804	WTC - CONCOURSE LEVEL DUANE READE, GREY SPRAYED ON FIREPROOFING ON THE EAST SIDE.	NON ASBESTOS SAMPLE DATE: 12/12/91
WTC-32805	WTC - CONCOURSE LEVEL DUANE READE, GREY SPRAYED ON FIREPROOFING ON THE SOUTH SIDE.	NON ASBESTOS SAMPLE DATE: 12/12/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 477
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST CRAWL SPACE
AREA DESCRIPTION:

BUILDING: 1
FLOOR: B-3 LEVEL

SAMPLE NUMBER	LOCATION	RESULT
WTC-32959	WHITE FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM COLUMN.	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/02/92
WTC-32960	GREY FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM BEAM.	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/02/92
WTC-32961	WHITE FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM COLUMN.	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/02/92
WTC-32962	GREY FLUFFY SPRAYED ON FIREPROOFING MATERIAL COLLECTED FROM BEAM.	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/02/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 487
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL EQUIPMENT ROOM
AREA DESCRIPTION: STEAM RISERS

BUILDING: 1
FLOOR: 41

SAMPLE NUMBER	LOCATION	RESULT
WTC-32849	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 41ST FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32850	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 41ST FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORHTWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32851	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 41ST FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32852	SHEET ROCK MATERIAL COLLECTED FROM INSIDE THE STEAM RISER CLOSET.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32853	SHEET ROCK MATERIAL COLLECTED FROM INSIDE THE STEAM RISER CLOSET.	NON ASBESTOS SAMPLE DATE: 12/17/91
C-32854	SHEET ROCK MATERIAL COLLECTED FROM INSIDE THE STEAM RISER CLOSET.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32855	PIPE INSULATION FALLOUT MATERIAL COLLECTED FROM INSIDE THE STEAM RISER CLOSET.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32856	PIPE INSULATION MATERIAL COLLECTED FROM INSIDE THE STEAM RISER CLOSET.	NON ASBESTOS SAMPLE DATE: 12/17/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 488
SURVEY # 001

ICILITY: WORLD TRADE CENTER
JCATION: MECHANICAL EQUIPMENT ROOM
AREA DESCRIPTION: STEAM RISERS

BUILDING: 1
FLOOR: 7

SAMPLE NUMBER	LOCATION	RESULT
WTC-32844	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 7TH FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 12/17/91
WTC-32845	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 7TH FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 12/17/91
WTC-32846	FLUFFY INSULATION MATERIAL COLLECTED FROM BEAM ON THE 7TH FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 12/17/91
WTC-32847	PIPE INSULATION MATERIAL COLLECTED FROM INSIDE THE STEAM RISER ON THE 7TH FLOOR FROM THE MECHANICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	L1 - 35% AMOSITE ASBESTOS L2 - 15% CHRYOSTILE ASBESTOS SAMPLE DATE: 12/17/91
WTC-32848	PIPE INSULATION MATERIAL COLLECTED FROM INSIDE THE STEAM RISER ON THE 7TH FLOOR FROM THE MECHENICAL EQUIPMENT ROOM, NORTHWEST QUADRANT.	L1 - 35% AMOSITE ASBESTOS L2 - 10% CHRYOSTILE ASBESTOS SAMPLE DATE: 12/17/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 490
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL EQUIPMENT ROOM
AREA DESCRIPTION: STEAM RISERS

BUILDING: 1
FLOOR: 75

SAMPLE NUMBER	LOCATION	RESULT
WTC-32857	FLUFFY INSULATION MATERIAL COLLECTED FROM THE BEAM LOCATED IN THE NORTHWEST QUADRANT OF MECHANICAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32858	FLUFFY INSULATION MATERIAL COLLECTED FROM THE BEAM LOCATED IN THE NORTHWEST QUADRANT OF MECHANICAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32859	FLUFFY INSULATION MATERIAL COLLECTED FROM THE BEAM LOCATED IN THE NORTHWEST QUADRANT OF MECHANICAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32860	PIPE INSULATION MATERIAL COLLECTED FROM THE STEAM RISER IN THE NORTHWEST QUADRANT OF MECHANICAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32861	PIPE INSULATION MATERIAL COLLECTED FROM THE STEAM RISER IN THE NORTHWEST QUADRANT OF MECHANICAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32862	SHEET ROCK MATERIAL COLLECTED FROM THE STEAM RISER CLOSET IN THE NORTHWEST QUADRANT OF MECHANCIAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91
WTC-32863	SHEET ROCK MATERIAL COLLECTED FROM THE STEAM RISER CLOSET IN THE NORTHWEST QUADRANT OF MECHANCIAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/17/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 491
SURVEY # 001

ACILITY: WORLD TRADE CENTER
LOCATION: MECHANICAL EQUIPMENT ROOM
AREA DESCRIPTION: STEAM RISERS

BUILDING: 1
FLOOR: 108

SAMPLE NUMBER	LOCATION	RESULT
WTC-32864	PIPE INSULATION MATERIAL COLLECTED FROM THE INSIDE STEAM RISER CLOSET LOCATED IN THE NORTHWEST QUADRANT OF MECHANCIAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/18/91
WTC-32865	PIPE INSULATION MATERIAL COLLECTED FROM THE STEAM RISER CLOSET LOCATED IN THE NORTHWEST QUADRANT OF MECHANCIAL EQUIPMENT ROOM.	NON ASBESTOS SAMPLE DATE: 12/18/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 589
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: ON TOP OF THE ELEVATOR CAR # 3 & 4
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 44TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-33054	FLUFFY WHITE FIREPROOFING FALLOUT MATERIAL COLLECTED FROM DEBRIS LOCATED ON TOP OF THE CAR # 3.	35% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/18/92
WTC-33055	FLUFFY WHITE FIREPROOFING FALLOUT MATERIAL COLLECTED FROM DEBRIS LOCATED ON TOP OF CAR # 4.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/18/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 590
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: ROOFTOP OF ELEVATOR
AREA DESCRIPTION: ELEVATOR # 3

BUILDING: 1
FLOOR: SKYLOBBY

SAMPLE NUMBER	LOCATION	RESULT
WTC-33044	FIREPROOFING MATERIAL COLLECTED FROM ABOVE THE ELEVATOR # 3 LOCATED ON THE SKYLOBBY LEVEL.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/14/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 591
SURVEY # 001

CILITY: WORLD TRADE CENTER
JCATION: TOP OF ELEVATOR CARS # 1, 8 & 11
AREA DESCRIPTION: SKYLOBBY ELEVATORS

BUILDING: 1
FLOOR: 44TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-33216	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # 1. (IDENTICAL TO SPRAY-ON FIREPROOFING).	35% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/92
WTC-33217	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # 8. (IDENTICAL TO SPRAY-ON FIREPROOFING).	40% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/92
WTC-33218	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # 11 (IDENTICAL TO SPRAY-ON FIREPROOFING).	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 592
SURVEY # 001

ACILITY: WORLD TRADE CENTER
XCATION: WEST OF ENTRANCE TO SUIT # 1933
AREA DESCRIPTION: SUITE # 1933

BUILDING: 1
FLOOR: 19TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-33238	FLUFFY FALLOUT MATERIAL COLLECTED FROM A RETURN AIR VENT LOCATED 25' FEET WEST OF ENTRANCE TO SUITE # 1933.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/26/92
WTC-33239	FLUFFY FALLOUT MATERIAL COLLECTED FROM A RETURN AIR VENT LOCATED 25' FEET WEST OF ENTRANCE TO SUITE # 1933.	<1% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/26/92

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 593
SURVEY # 001

\CILITY: WORLD TRADE CENTER
JCATION: NORTHEAST OF NORTHWEST TELEPHONE CLOSET
AREA DESCRIPTION: SUITE # 2563

BUILDING: 1
FLOOR: 25TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-33236	FLUFFY FALLOUT MATERIAL COLLECTED FROM A RETURN AIR VENT LOCATED 10' FEET NORTHEAST OF THE NORTHWEST TELEPHONE CLOSET.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/26/92
WTC-33237	FLUFFY FALLOUT MATERIAL COLLECTED FROM A RETURN AIR VENT LOCATED 10' FEET NORTHEAST OF THE NORTHWEST TELEPHONE CLOSET.	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/26/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

CILITY: WORLD TRADE CENTER
OCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33061	WHITE TROWELED-ON PATCHING FIREPROOFING MATERIAL COLLECTED FROM BEAM (UNDERSIDE) LOCATED ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33062	WHITE TROWELED-ON PATCHING FIREPROOFING MATERIAL COLLECTED FROM A BEAM (UNDERSIDE) LOCATED ABOUT 60' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33063	WHITE TROWELED-ON PATCHING FIREPROOFING MATERIAL COLLECTED FROM A BEAM (UNDERSIDE) LOCATED ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33064	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM (UNDERSIDE) LOCATED ABOUT 25' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33065	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM (UNDERSIDE) LOCATED ABOUT 15' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33066	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM (UNDERSIDE) LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33067	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM (FROM SIDE OF BEAM), LOCATED ABOUT 60' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33068	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM A BEAM (FROM SIDE OF BEAM), LOCATED ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33069	GREY SPRAYED-ON FIREPROOFING OVERSPRAY MATERIAL COLLECTED FROM THE DECKING LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33070	GREY SPRAYED-ON FIREPROOFING OVERSPRAY MATERIAL COLLECTED FROM THE DECKING LOCATED ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33071	GREY SPRAYED-ON FIREPROOFING OVERSPRAY MATERIAL COLLECTED FROM THE DECKING LOCATED ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

CILITY: WORLD TRADE CENTER
JCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33072	GREY SPRAYED-ON FIREPROOFING OVERSPRAY MATERIAL COLLECTED FROM THE DECKING LOCATED ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33073	2' X 2' WHITE CEILING TILES MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33074	2' X 2' WHITE CEILING TILES MATERIAL COLLECTED FROM ABOUT 10' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33075	2' X 2' WHITE CEILING TILES MATERIAL COLLECTED FROM ABOUT 15' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33076	2' X 2' WHITE CEILING TILES REPLACEMENTS MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33077	2' X 2' WHITE CEILING TILES REPLACEMENTS MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
/TC-33078	2' X 2' WHITE CEILING TILES REPLACEMENTS MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33079	4' X 8' GREY GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33080	4' X 8' GREY GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33081	4' X 8' GREY GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33082	4' X 8' GREY GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33083	4' X 8' GREY GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33084	WHITE CEMENTITIOUS SURFACING MATERIAL, FUNCTIONING AS CEILING PLASTER COLLECTED FROM ABOUT 5' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33085	WHITE CEMENTITIOUS SURFACING MATERIAL, FUNCTIONING AS CEILING PLASTER COLLECTED FROM ABOUT 10' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33086	WHITE CEMENTITIOUS SURFACING MATERIAL, FUNCTIONING AS CEILING PLASTER COLLECTED FROM ABOUT 10' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33087	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 45' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33088	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 50' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33089	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 65' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33090	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 80' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33091	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 85' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33092	MASTIC MATERIAL COLLECTED FROM A 12" WHITE TILE LOCATED ABOUT 45' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33093	MASTIC MATERIAL COLLECTED FROM A 12" WHITE FLOOR TILE LOCATED ABOUT 50' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33094	MASTIC MATERIAL COLLECTED FROM A 12" WHITE FLOOR TILE LOCATED ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

CILITY: WORLD TRADE CENTER
.OCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33095	MASTIC MATERIAL COLLECTED FROM A 12" WHITE FLOOR TILE LOCATED ABOUT 80' FEET EAST OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33096	MASTIC MATERIAL COLLECTED FROM A 12" WHITE FLOOR TILE LOCATED ABOUT 85' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33097	GREY FIREPROOFING, FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE 2' X 2' CEILING TILE LOCATED ABOUT 35' EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33098	PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE CONDENSATION LINE ELBOW, LOCATED ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33099	PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE HOT WATER LINE ELBOW LOCATED ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33100	PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE CHILLED WATER LINE ELBOW, LOCATED ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33101	PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE CHILLED WATER LINE ELBOW, LOCATED ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33102	PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE HOT WATER LINE VALVE, LOCATED ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33103	GREY FLUFFY SPRAYED-ON MATERIAL COLLECTED FROM THE WASTE WATER TUB (SIDE OF THE TUB), LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33104	GREY FLUFFY SPRAYED-ON MATERIAL COLLECTED FROM THE WASTE WATER TUB (SIDE OF THE TUB), LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33105	GREY FLUFFY SPRAYED-ON MATERIAL COLLECTED FROM THE WASTE WATER TUB (UNDERSIDE OF THE TUB), LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

\CILITY: WORLD TRADE CENTER
.OCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33106	WHITE CEMENTITIOUS SURFACE LEVELING MATERIAL COLLECTED FROM THE CINDER BLOCK WALL, LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33107	WHITE CEMENTITIOUS SURFACE LEVELING MATERIAL COLLECTED FROM THE CINDER BLOCK WALL, LOCATED ABOUT 50' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33108	WHITE CEMENTITIOUS SURFACE LEVELING MATERIAL COLLECTED FROM THE CINDER BLOCK WALL, LOCATED 55' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33109	GREY JOINT TAPE MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33110	GREY JOINT TAPE MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33111	GREY JOINT TAPE MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33112	WHITE JOINT FILLER MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33113	WHITE JOINT FILLER MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33114	WHITE JOINT FILLER MATERIAL ON SEAMS OF WALLBOARD COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33115	BLACK CABLE WRAP MATERIAL COLLECTED FROM THE MEDIUM GAUGE WIRES LOCATED ABOUT 85' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33116	PIPE FITTING INSULATION DEBRIS MATERIAL COLLECTED FROM AN ELBOW LOCATED 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33117	BLACK DUCTING FLEX DAMPER MATERIAL COLLECTED FROM ABOUT 90' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33118	GREY DUCT SEAMS CAULKING MATERIAL COLLECTED FROM ABOUT 90' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/21/92
WTC-33119	4" BLACK WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE COLUMN LOCATED ABOUT 60' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33120	4" BLACK WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE WALL LOCATED ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33121	4" BLACK WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE WALL LOCATED ABOUT 85' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33122	4" BROWN WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE WALL LOCATED ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33123	4" BROWN WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE WALL LOCATED ABOUT 25' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33124	4" BROWN WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE WALL LOCATED ABOUT 40' FEET EAST OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33125	TAN COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALLS LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33126	TAN COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALLS LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: BAKER'S WOMEN'S SHOES

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33127	TAN COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALLS LOCATED ABOUT 40' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33128	ORANGE COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALL LOCATED ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33129	ORANGE COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALL LOCATED ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33130	ORANGE COLORED WALLPAPER COVERING MATERIAL COLLECTED FROM THE SHEETROCK WALL LOCATED ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33131	WHITE CEMENTITIOUS MOLDING & SEAMS SEALING MATERIAL COLLECTED FROM WHERE THE WASTE WATER TUB AND THE GALVANIZED WASTE WATER LINE PIPE CONNECT.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33132	RUSTED GALVANIZED PIPE MATERIAL COLLECTED FROM THE WASTE WATER LINE LOCATED ADJACENT TO THE WASTE WATER TUB.	NON ASBESTOS SAMPLE DATE: 02/21/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33133	2' X 4' WHITE CEILING TILE (WITH LARGE PERFORATIONS) MATERIAL COLLECTED ABOUT 20' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/21/92
WTC-33134	2' X 4' WHITE CEILING TILE (WITH LARGE PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 15' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33135	2' X 4' WHITE CEILING TILE (WITH LARGE PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 5' FEET EAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33136	2' X 4' WHITE CEILING TILE (WITH LARGE PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 5' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33137	2' X 4' WHITE CEILING TILE (WITH LARGE PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 15' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33138	2' X 4' WHITE CEILING TILE (WITH SMALL PERFORATION) MATERIAL COLLECTED FROM ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33139	2' X 4' WHITE CEILING TILE (WITH SMALL PERFORATION) MATERIAL COLLECTED FROM THE DRESSING ROOM, ABOUT 85' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33140	2' X 4' WHITE CEILING TILE (WITH SMALL PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33141	2' X 4' WHITE CEILING TILE (WITH SMALL PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33142	2' X 4' WHITE CEILING TILE (WITH SMALL PERFORATIONS) MATERIAL COLLECTED FROM ABOUT 45' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

ACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33143	BEIGE COLORED CARPET MASTIC MATERIAL (APPLIED OVER CONCRETE) COLLECTED FROM ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33144	BEIGE COLORED CARPET MASTIC MATERIAL (APPLIED OVER CONCRETE) COLLECTED FROM ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33145	BEIGE COLORED CARPET MASTIC MATERIAL (APPLIED OVER CONCRETE) COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33146	BEIGE COLORED CARPET MASTIC MATERIAL (APPLIED OVER CONCRETE) COLLECTED FROM ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33147	BEIGE COLORED CARPET MASTIC MATERIAL (APPLIED OVER CONCRETE) COLLECTED FROM ABOUT 15' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33148	WHITE CEMENTITITOUS FLOOR LEVELING COMPOUND,SURFACING MATERIAL COLLECTED FROM ABOUT 15' FEET OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33149	WHITE CEMENTITIOUS FLOOR LEVELING COMPOUND, SURFACING MATERIAL COLLECTED FROM ABOUT 5' FEET NORTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33150	WHITE CEMETITIOUS FLOOR LEVELING COMPOUND, SURFACING MATERIAL COLLECTED FROM ABOUT 10' FEET NORTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33151	PAINTED ORANGE WALLPAPER MATERIAL COLLECTED FROM THE DRYWALL LOCATED AT ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33152	PAINTED ORANGE WALLPAPER MATERIAL COLLECTED FROM THE DRYWALL LOCATED AT ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33153	PAINTED ORANGE WALLPAPER MATERIAL COLLECTED FROM THE DRYWALL LOCATED AT ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33154	CARPET MOLDING MATERIAL (SECURING THE EDGE OF THE CARPET) COLLECTED FROM ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33155	CARPET MOLDING MATERIAL (SECURING THE EDGE OF THE CARPET) COLLECTED FROM ABOUT 10' FEET NORTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33156	CARPET MOLDING MATERIAL (SECURING THE EDGE OF THE CARPET) COLLECTED FROM ABOUT 15' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33157	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 30' FEET SOUTH OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33158	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33159	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33160	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33161	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 35' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33162	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 15' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33163	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 20' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33164	4' X 8' SHEET GYPSUM WALLBOARD MATERIAL COLLECTED FROM ABOUT 25' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33165	WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE DRYWALL LOCATED ABOUT 50' FEET SOUTHEAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33166	WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE DRYWALL LOCATED ABOUT 30' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33167	WALLBOARD MOLDING MATERIAL COLLECTED FROM THE BASE OF THE DRYWALL LOCATED ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33168	JOINT TAPE MATERIAL COLLECTED FROM THE DRYWALL LOCATED ABOUT 30' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33169	JOINT TAPE MATERIAL COLLECTED FROM THE DRYWALL LOCATED ABOUT 5' FEET EAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33170	JOINT TAPE MATERIAL COLLECTED FROM THE DRYWALL LOCATED ABOUT 20' FEET EAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33171	WHITE JOINT FILLER MATERIAL COLLECTED FROM THE DRYWALL LOCATED ABOUT 30' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33172	WHITE JOINT FILLER MATERIAL COLLECTED FROM THE DRYWALL LOCATED AT ABOUT 5' FEET EAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

CILITY: WORLD TRADE CENTER
.OCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33173	WHITE JOINT FILLER MATERIAL COLLECTED FROM THE DRYWALL LOCATED ABOUT 20' FEET EAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33174	GREY WALL INSULATION MATERIAL ENCLOSING THE HVAC ROOM, COLLECTED FROM INSIDE THE HVAC ROOM (INNER LAYER).	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33175	GREY WALL INSULATION MATERIAL ENCLOSING THE HVAC ROOM, COLLECTED FROM EAST OF THE HVAC ROOM. (OUTER LAYER)	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33176	GREY WALL INSULATION MATERIAL ENCLOSING THE HVAC ROOM, COLLECTED FROM THE NORTH WALL OF THE HVAC ROOM (OUTER LAYER).	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33177	BLACK FLEX DUCT DAMPER MATERIAL COLLECTED JUST NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33179	WHITE SEMI-CEMENTITIOUS MOLDED PIPE INSULATION MATERIAL COLLECTED FROM THE HOT WATER SUPPLY LINE LOCATED OUTSIDE THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33180	WHITE SEMI-CEMENTITIOUS MOLDED PIPE INSULATION, MATERIAL COLLECTED FROM THE COLD WATER LINE LOCATED OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33181	WHITE SEMI-CEMENTITIOUS MOLDED PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE HOT WATER SUPPLY PIPE LOCATED JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33182	WHITE, SEMI-CEMENTITIOUS MOLDED PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE HOT WATER RETURN PIPE LOCATED JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33183	WHITE, SEMI-CEMENTITIOUS MOLDED PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE COLD WATER PIPE LOCATED JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33184	WHITE, SEMI-CEMENTITIOUS MOLDED PIPE FITTING INSULATION MATERIAL COLLECTED FROM THE COLD WATER PIPE LOCATED JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33185	WHITE, PIPE THREADING MATERIAL COLLECTED FROM THE ELBOW OF A PIPE LOCATED JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33186	HVAC FILTER MATERIAL COLLECTED FROM THE HVAC INTAKE LOCATED IN THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33187	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 65' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/24/92
WTC-33188	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM ABOUT 75' FEET EAST OF THE ENTRANCE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/24/92
WTC-33189	12" X 12" WHITE FLOOR TILE MATERIAL COLLECTED FROM THE ROOM LOCATED ABOUT 15' FEET SOUTH OF THE HVAC ROOM.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/24/92
WTC-33190	FLOOR TILE MASTIC MATERIAL FOR 12" WHITE FLOOR TILE COLLECTED FROM ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33191	FLOOR TILE MASTIC MATERIAL FOR 12" WHITE FLOOR TILE COLLECTED FROM ABOUT 75 FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33192	FLOOR TILE MASTIC MATERIAL FOR 12" WHITE FLOOR TILE COLLECTED FROM A ROOM LOCATED ABOUT 15' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33193	WHITE, TROWELED-ON FIREPROOFING MATERIAL COLLECTED FROM THE UNDERSIDE OF THE BEAM LOCATED ABOUT 15' FEET NORTHEAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

CILITY: WORLD TRADE CENTER
JCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33194	WHITE, TROWELED-ON FIREPROOFING MATERIAL COLLECTED FROM THE UNDERSIDE OF THE BEAM LOCATED ABOUT 15' FEET NORTHEAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33195	WHITE, TROWELED-ON FIREPROOFING MATERIAL COLLECTED FROM THE UNDERSIDE OF THE BEAM LOCATED ABOUT 15' FEET NORTHEAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33196	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE SIDE OF THE BEAM LOCATED ABOUT 15' FEET NORTHEAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33197	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 10' FEET NORTHEAST OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33198	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED IN THE ROOM AT ABOUT 30' FEET SOUTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33199	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 75' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33200	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 70' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33201	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 35' FEET SOUTHEAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33202	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 45' FEET SOUTHEAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33203	GREY SPRAYED-ON FIREPROOFING MATERIAL COLLECTED FROM THE BEAM LOCATED ABOUT 10' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 632
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: CONCOURSE
AREA DESCRIPTION: LERNERS STORE

BUILDING:
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-33204	FALLOUT MATERIAL COLLECTED FROM THE GREY SPRAYED-ON FIREPROOFING FROM THE TOP OF THE CEILING TILE LOCATED ABOUT 45' FEET SOUTHEAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33205	PIPE SEAM CAULKING MATERIAL COLLECTED FROM THE GALVANIZED PIPE OF THE WASTE LINE,LOCATED AT ABOUT 20' FEET NORTH OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33206	HVAC BELT MATERIAL COLLECTED FROM JUST OUTSIDE OF THE HVAC ROOM.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33207	BROWN WALL MOLDING MATERIAL COLLECTED FROM THE COLUMNS LOCATED ABOUT 65' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33208	BROWN WALL MOLDING MATERIAL COLLECTED FROM THE COLUMNS LOCATED AT ABOUT 75' FEET SOUTHEAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92
WTC-33209	BROWN WALL MOLDING MATERIAL COLLECTED FROM THE COLUMNS LOCATED AT ABOUT 35' FEET EAST OF THE ENTRANCE.	NON ASBESTOS SAMPLE DATE: 02/24/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 677
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: TOP OF ELEVATOR CAR
AREA DESCRIPTION: SKYLOBBY ELEVATOR

BUILDING: 1
FLOOR: 78

SAMPLE NUMBER	LOCATION	RESULT
WTC-33354	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 12 LOCATED AT 1WTC 78TH FLOOR SKYLOBBY ELEVATOR SHAFT.	10% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/10/92
WTC-33355	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 12 LOCATED AT 1WTC 78TH FLOOR SKYLOBBY ELEVATOR SHAFT.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/10/92
WTC-33356	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 14 LOCATED AT 1WTC 78TH FLOOR SKYLOBBY ELEVATOR SHAFT.	NON ASBESTOS SAMPLE DATE: 03/10/92
WTC-33357	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 21 LOCATED AT 1WTC 78TH FLOOR SKYLOBBY ELEVATOR SHAFT.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/10/92
WTC-33358	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF CAR # 21 LOCATED AT 1WTC 78TH FLOOR SKYLOBBY ELEVATOR SHAFT.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/10/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 677
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION: ELEVATOR CAR # 21
AREA DESCRIPTION: SKYLOBBY ELEVATOR

BUILDING: 1
FLOOR: 78

SAMPLE NUMBER	LOCATION	RESULT
WTC-33377	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE INSIDE OF CAR # 21.	NON ASBESTOS SAMPLE DATE: 03/12/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 677
SURVEY # 003

CILITY: WORLD TRADE CENTER
/CATION: B-2 LEVEL / ELECTRICAL SHOP
AREA DESCRIPTION: ELEVATOR PIT # 20 + 21

BUILDING: 1
FLOOR: B-2 LEVEL

SAMPLE NUMBER	LOCATION	RESULT
WTC-33576	WHITE FLUFFY MATERIAL COLLECTED FROM THE PULLEY LOCATED ON CAR # 20.	NON ASBESTOS SAMPLE DATE: 03/16/92
WTC-33577	WHITE FLUFFY MATERIAL COLLECTED FROM THE MACHINERY LOCATED ADJACENT TO CAR # 21.	NON ASBESTOS SAMPLE DATE: 03/16/92
WTC-33578	BLACK GRANULAR MATERIAL COLLECTED FROM THE GROUND IN FRONT OF CAR # 20 & 21.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/16/92
WTC-33579	WHITE FLUFFY MATERIAL COLLECTED FROM THE LEDGE OF CAR # 20.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/16/92
WTC-33580	WHITE FLUFFY MATERIAL COLLECTED FROM THE LEDGE OF CAR # 21.	NON ASBESTOS SAMPLE DATE: 03/16/92

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 679
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: ON TOP OF THE ELEVATOR CAR # 3 & 4
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 44

SAMPLE NUMBER	LOCATION	RESULT
WTC-33054	FLUFFY WHITE FIREPROOFING FALLOUT MATERIAL COLLECTED FROM DEBRIS LOCATED ON TOP OF THE CAR # 3.	35% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/18/92
WTC-33055	FLUFFY WHITE FIREPROOFING FALLOUT MATERIAL COLLECTED FROM DEBRIS LOCATED ON TOP OF CAR # 4.	20% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/18/92

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 679
SURVEY # 001

'ILITY: WORLD TRADE CENTER
.ATION: TOP OF THE ELEVATOR CARS # 1, 8 & 11
AREA DESCRIPTION: SKYLOBBY ELEVATORS

BUILDING: 1
FLOOR: 44

SAMPLE NUMBER	LOCATION	RESULT
WTC-33216	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # 1. (IDENTICAL TO SPRAY-ON FIREPROOFING).	35% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/92
WTC-33218	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE TOP OF THE ELEVATOR CAR # 11 (IDENTICAL TO SPRAY-ON FIREPROOFING).	30% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/25/92

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 30
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: OLD SHEARSON LEHMAN
AREA DESCRIPTION: STORAGE AREA, 268 LEVEL

BUILDING: 2
FLOOR: LEVEL B-4

SAMPLE NUMBER	LOCATION	RESULT
WTC-28746	12"x12" FLOOR TILE SAMPLE COLLECTED FROM OLD SHEARSON LEHMAN STORAGE AREA WITHIN RECTANGLE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/14/91
WTC-28747	BLACK MASTIC ADHESIVE SAMPLE COLLECTED FROM OLD SHEARSON LEHMAN STORAGE AREA WITHIN RECTANGLE.	NON ASBESTOS SAMPLE DATE: 02/14/91
WTC-28748	12"X12" FLOOR TILE SAMPLE COLLECTED FROM OLD SHEARSON LEHMAN STORAGE AREA OUTSIDE RECTANGLE.	5% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/14/91
WTC-28772	BLACK MASTIC ADHHESIVE SAMPLE COLLECTED FROM OLD SHEARSON LEHMAN STORAGE AREA OUTSIDE RECTANGLE.	NON ASBESTOS SAMPLE DATE: 02/14/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 32
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: 1ST BOSTON
AREA DESCRIPTION:

BUILDING:
FLOOR: LEVEL B-3

SAMPLE NUMBER	LOCATION	RESULT
WTC-28773	12"X12" YELLOW FLOOR TILE SAMPLE TAKEN IN CORRIDOR OF 1ST BOSTON ON LEVEL B-3.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 02/14/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 33
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: RANDOM VARIOUS LOCATIONS FROM THE FLOOR
AREA DESCRIPTION: WEST SIDE OFFICE AREA

BUILDING: 2
FLOOR: 27

SAMPLE NUMBER	LOCATION	RESULT
WTC-28127	YELLOW 12"X12" FLOOR TILE COLLECTED AT INTERSECTION OF COLUMNS 411 AND 353.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 66
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 2
FLOOR: LOBBY

SAMPLE NUMBER	LOCATION	RESULT
WTC-28855	DARK GRAYISH THERMO INSULATION MATERIAL COLLECTED FROM A PIPE COUPLING JUST ABOVE CEILING OPENING.	NON ASBESTOS SAMPLE DATE: 02/21/91
WTC-28856	LIGHT GRAYISH SPRAYED ON SURFACING MATERIAL COLLECTED FROM A BEAM JUST ABOVE CEILING OPENING IN ELEVATOR LOBBY.	NON ASBESTOS SAMPLE DATE: 02/21/91

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: NORTHEAST QUADRANT
AREA DESCRIPTION: LOBBY CEILING, (MEZZANINE)

BUILDING: 2
FLOOR: LOBBY

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1000	WHITE CEMENTITIOUS MATERIAL COLLECTED FROM THE FIRST LAYER OF THE UNDER-HANG OF THE MEZZANINE LOCATED AT THE NORTHEAST QUAD.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1001	GREY CEMENTITIOUS MATERIAL COLLECTED FROM THE UNDERHANG OF THE MEZZANINE LOCATED AT THE NORTHEAST QUAD.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1002	TAN CEMENTITIOUS MATERIAL COLLECTED FROM THE SECOND LAYER OF THE UNDER-HANG OF THE MEZZANINE LOCATED AT THE NORTHEAST QUAD.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1003	WHITE FLUFFY MATERIAL COLLECTED FROM THE CEILING LOCATED INSIDE THE MEZZANINE AT THE NORTHEAST QUAD.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1004	WHITE FLUFFY MATERIAL COLLECTED FROM A SUPPORT BEAM RUNNING EAST TO WEST LOCATED INSIDE THE MEZZANINE AT THE NORTHEAST QUAD.	NON ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1005	WHITE FLUFFY MATERIAL COLLECTED FROM A SUPPORT BEAM RUNNING NORTH TO SOUTH LOCATED INSIDE THE MEZZANINE AT THE NORTHEAST QUAD.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 03/22/91
R-WTC-1006	GREY CEMENTITIOUS MATERIAL COLLECTED FROM A SUPPORT BEAM RUNNING EAST TO WEST LOCATED INSIDE THE MEZZANINE AT THE NORTHEAST QUAD.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/22/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 102
SURVEY # 001

CITY: WORLD TRADE CENTER
LOCATION: SOUTHWEST QUADRANT BY FEDERAL EXPRSS
AREA DESCRIPTION: LOBBY CEILING, (MEZZANINE)

BUILDING: 2
FLOOR: LOBBY

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-1007	WHITE FLUFFY MATERIAL COLLECTED FROM THE SOUTHWEST SUPPORT BEAM LOCATED INSIDE THE MEZZANINE AT THE SOUTHWEST QUAD.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1008	CEMENTITIOUS MATERIAL COLLECTED FROM THE SOUTHWEST SUPPORT BEAM LOCATED INSIDE THE MEZZANINE AT THE SOUTHWEST QUAD.	35% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1009	WHITE FLUFFY MATERIAL COLLECTED FROM THE CEILING LOCATED INSIDE THE MEZZANINE AT THE SOUTHWEST QUAD.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1010	WHITE FLUFFY MATERIAL COLLECTED FROM THE SOUTHEAST SUPPORT BEAM LOCATED INSIDE THE MEZZANINE AT THE SOUTHWEST QUAD.	NON ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1011	WHITE FLUFFY MATERIAL COLLECTED FROM THE TOP OF THE SOUTHEAST SUPPORT BEAM LOCATED INSIDE THE MEZZANINIE AT THE SOUTHWEST QUAD.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/23/91
R-WTC-1012	WHITE CEMENTITIOUS MATERIAL COLLECTED FROM THE BOTTOM OF THE SOUTHWEST SUPPORT BEAM LOCATED INSIDE THE MEZZANINE AT THE SOUTHWEST QUAD.	50% CHRYSOTILE ASBESTOS SAMPLE DATE: 03/23/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 110
SURVEY # 009

CILITY: WORLD TRADE CENTER
.OCATION:
AREA DESCRIPTION: SUB-LEVEL ELEVATORS SHAFT/CARS K3-K5

BUILDING: 2
FLOOR: 1-B-6

SAMPLE NUMBER	LOCATION	RESULT
R-2WTC-30000	CEMENTITIOUS MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR #K-5 AT THE TOP OF THE B1 FLOOR.	NON ASBESTOS
R-2WTC-30001	CEMENTITIOUS MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR #K-5 AT THE TOP OF FLOOR B3.	NON ASBESTOS
R-2WTC-30002	CEMENTITIOUS MATERIAL COLLECTED FROM A 13" BEAM LOCATED ON THE NORTH EAST CORNER OF THE ELEVATOR SHAFT FOR CAR #K-5 AT THE TOP OF FLOOR B5.	NON ASBESTOS
R-2WTC-30003	CEMENTITIOUS PATCHING MATERIAL COLLECTED FROM THE WEST WALL LOCATED ON THE CENTER OF THE ELEVATOR SHAFT FOR CAR #K-5 AT THE TOP OF FLOOR B-5.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 117
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: TRADE INN RESTURANT-REAR OF COFFEE HOUSE

BUILDING:
FLOOR: B4

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-3008	GREY TROWLED-ON MATERIAL COLLECTED FROM THE DUCT SEAM LOCATED IN THE CENTER OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3009	GREY TROWLED-ON MATERIAL COLLECTED FROM THE DUCT SEAM LOCATED ON THE NORTH SIDE OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3010	GREY TROWLED-ON MATERIAL COLLECTED FROM THE DUCT SEAM LOCATED ON THE BASE OF THE FAN UNIT IN THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3011	WHITE MOLDED PAD MATERIAL COLLECTED FROM A DUCT LOCATED AT THE NORTH END OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3012	WHITE MOLDED PAD MATERIAL COLLECTED FROM A DUCT LOCATED IN THE CENTER OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3013	WHITE MOLDED PAD MATERIAL COLLECTED FROM A DUCT LOCATED IN THE SOUTH SIDE OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3014	FIBROUS MATERIAL COLLECTED FROM A VIBRATION DAMPER LOCATED IN THE CENTER OF THE BACK HALLWAY.	95% CHRYSOTILE ASBESTOS
R-WTC-3015	PLASTER BOARD MATERIAL COLLECTED FROM THE WEST WALL LOCATED IN THE SOUTH SIDE OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3016	CEMENTITIOUS MATERIAL COLLECTED FROM A PATCH LOCATED ON THE EAST WALL NEXT TO THE MANAGERS OFFICE DOOR.	NON ASBESTOS
R-WTC-3017	PLASTER BOARD MATERIAL COLLECTED FROM THE EAST WALL LOCATED IN THE CENTER OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3018	OUTER COVERING MATERIAL COLLECTED FROM A 4" O.D. PIPE LOCATED NEXT TO THE FAN UNIT IN THE CENTER OF THE BACK HALLWAY.	NON ASBESTOS
R-WTC-3019	CEMENTITIOUS PATCHING MATERIAL COLLECTED FROM THE EAST WALL LOCATED NEXT TO THE DOUBLE ENTRANCE DOORS OF THE HALLWAY.	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 117
SURVEY # 002

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: COFFEE HOUSE - TRADE-INN RESTURANT

BUILDING:
FLOOR: B4

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-3020	MASTIC MATERIAL COLLECTED FROM UNDER A GREY 12" X 12" TILE LOCATED BY THE WEST WALL, SOUTH SIDE	NON ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 117
SURVEY # 003

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: KITCHEN AREA - TRADE-INN REST

BUILDING:
FLOOR: B4

SAMPLE NUMBER	LOCATION	RESULT
R-WTC-3021	WHITE PLASTER MATERIAL COLLECTED FROM THE WEST WALL LOCATED BY THE SOUTH ENTRANCE.	NON ASBESTOS
R-WTC-3022	CEMENTITIOUS MATERIAL COLLECTED FROM A DUCT ENCASEMENT LOCATED IN THE NORTH WEST CORNER.	NON ASBESTOS
R-WTC-3023	WHITE PLASTER MATERIAL COLLECTED FROM THE CEILING LOCATED IN THE SOUTH EAST CORNER BY THE SPRINKLER HEAD.	NON ASBESTOS

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 223
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: NORTHWEST & SOUTHEAST RETURN AIR SHAFT

BUILDING: 2WTC
FLOOR: 75TH

SAMPLE NUMBER	LOCATION	RESULT
WTC-30023	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SAFT ON COLUMN 15' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30024	TROWELED ON PATCH MATERIAL IN NORTHWEST AIR SHAFT ON COLUMN 15' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30025	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SHAFT ON COLUMN 30' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30026	GRAY SPRAY ON FIREPROOFING IN NORTHWEST AIR SHAFT ON COLUMN 30' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30027	TROWELED ON PATCH MATERIAL IN NORTHWEST AIR SHAFT ON COLUMN 30' LEFT OF ENTRANCE	NON ASBESTOS SAMPLE DATE: 06/14/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 389
SURVEY #

CILITY: WORLD TRADE CENTER
CATION: SOUTH TOWER
AREA DESCRIPTION: TRUCK LEVEL

BUILDING: 2
FLOOR: B-1

SAMPLE NUMBER	LOCATION	RESULT
WTC-32495	GRAY WET PLASTER LIKE MATERIAL COLLECTED FROM DUCT INSULATION LOCATED IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC # 2 ENTRANCE.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32496	WHITE BLOCK INSULATION COLLECTED FROM DUCT LOCATED IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC # 2 ENTRANCE.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32497	WHITE BLOCK INSULATION COLLECTED FROM DUCT LOCATED IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC # 2.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32498	WHITE BLOCK INSULATION COLLECTED FROM DUCT LOCATED IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC # 2.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32499	BLACK FLEX DUCT DAMPER INSULATION COLLECTED FROM A DUCT IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC# 2.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32500	BLACK FLEX DUCT DAMPER INSULATION COLLECTED FROM A DUCT IN A DUMPSTER 20 FEET FROM SOUTH TOWER WTC # 2.	NON ASBESTOS SAMPLE DATE: 11/13/91
·C-32501	DEBRIS COLLECTED FROM DUCT INSULATION LAYING ON THE GROUND IN THE AREA SOUTH OF TOWER WTC # 2 ENTRANCE.	NON ASBESTOS SAMPLE DATE: 11/13/91
WTC-32502	DEBRIS COLLECTED FROM DUCT INSULATION LAYING ON THE GROUND IN THE AREA SOUTH OF TOWER WTC # 2 ENTRANCE.	NON ASBESTOS SAMPLE DATE: 11/13/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 441
SURVEY # 001

FACILITY: WORLD TRADE CENTER
LOCATION: VARIOUS LOCATION'S ON FLOOR
AREA DESCRIPTION: MAIN PERIMETER AND CORE

BUILDING: 2
FLOOR: 27

SAMPLE NUMBER	LOCATION	RESULT
WTC-28127	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 411 AND # 353.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28128	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12' X 12" YELLOW FLOOR TILE AT INTERSECTION OF COLUMNS # 411 AND # 353.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28129	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 402 AND # 347.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28130	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12" X 12" YELLOW FLOOR TILE AT INTERSECTION OF COLUMNS # 402 AND # 347.	TRACE CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
TC-28131	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 404 AND # 335.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28132	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12" X 12" YELLOW FLOOR TILE AT INTERSECTION OF COLUMNS # 404 AND # 335.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28133	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 408 AND # 305.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28134	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12" X 12" YELLOW FLOOR TILE AT INTERSECTION OF COLUMNS # 408 AND # 305.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28135	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 244 AND # 305.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28136	BLACK MASTIC MATERIAL TAKEN FROM UNDER FLOOR TILE FROM INTERSECTION OF COLUMNS # 244 AND # 305.	NON ASBESTOS SAMPLE DATE: 01/07/91

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 441
SURVEY # 001

CILITY: WORLD TRADE CENTER
.OCATION: VARIOUS LOCATION'S ON FLOOR
AREA DESCRIPTION: MAIN PERIMETER AND CORE

BUILDING: 2
FLOOR: 27

SAMPLE NUMBER	LOCATION	RESULT
WTC-28137	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 221 AND # 150.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28138	BLACK MASTIC MATERIAL TAKEN FROM UNDER FLOOR TILE FROM INTERSECTION COLUMN # 221 AND # 150.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28139	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN AT INTERSECTION OF COLUMNS # 208 AND # 145.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28140	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12' X 12" YELLOW FLOOR TILE FROM INTERSECTION OF COLUMNS # 208 AND # 145.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28141	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 205 AND # 131.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
.TC-28142	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12" X 12" YELLOW FLOOR TILE FROM INTERSECTION OF COLUMNS # 205 AND # 131.	NON ASBESTOS SAMPLE DATE: 01/07/91
WTC-28143	YELLOW 12" X 12" FLOOR TILE MATERIAL TAKEN FROM INTERSECTION OF COLUMNS # 110 AND # 452.	15% CHRYSOTILE ASBESTOS SAMPLE DATE: 01/07/91
WTC-28144	BLACK MASTIC MATERIAL TAKEN FROM UNDER 12" X 12" YELLOW FLOOR TILE AT INTERSECTION OF COLUMNS # 110 AND # 452.	NON ASBESTOS SAMPLE DATE: 01/07/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 444
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: ESCALATOR

BUILDING: 2WTC
FLOOR: CONCOURSE

SAMPLE NUMBER	LOCATION	RESULT
WTC-29950	PLASTER, SOUTH SIDE OF ESCALATOR, 18' WEST OF EXIT DOWN.	NON ASBESTOS SAMPLE DATE: 06/12/91
WTC-29951	PLASTER, WEST SIDE (UNDER SIDE) OF ESCALATOR CENTER.	NON ASBESTOS SAMPLE DATE: 06/12/91
WTC-29952	PLASTER, NORTH SIDE OF ESCALATOR, 18' WEST OF ENTRANCE UP.	NON ASBESTOS SAMPLE DATE: 06/12/91

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 445
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION: RETURN AIR SHAFT NORTHWEST & SOUTHEAST

BUILDING: 2WTC
FLOOR: 75

SAMPLE NUMBER	LOCATION	RESULT
WTC-30023	NORTHWEST AIR SHAFT GRAY SPRAY-ON FIREPROOFING ON COLUMN 15' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30024	NORTHWEST AIR SHAFT TROWELED ON PATCH MATERIAL ON COLUMN 15' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30025	NORTHWEST AIR SHAFT GRAY SPRAY-ON FIREPROOFING ON COLUMN 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30026	NORTHWEST AIR SHAFT GRAY SPRAY-ON FIREPROOFING ON COLUMN 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91
WTC-30027	NORTHWEST AIR SHAFT TROWELED ON PATCH MATERIAL COLUMN 30' LEFT OF ENTRANCE.	NON ASBESTOS SAMPLE DATE: 06/14/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 467
SURVEY #

FACILITY: WORLD TRADE CENTER
LOCATION: KITCHEN EXHAUST DUCT, SOUTHEAST QUADRANT
AREA DESCRIPTION: 99TH FLOOR

BUILDING: 2
FLOOR: 99

SAMPLE NUMBER	LOCATION	RESULT
WTC-32813	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT SOUTH SIDE, TOP OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32814	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT SOUTH SIDE, BOTTOM OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32815	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT SOUTH SIDE, EAST SIDE OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32816	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT SOUTH SIDE, WEST SIDE OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32817	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT PATCHING MATERIAL AT SOUTH SIDE.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32818	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT CENTER OF EXHAUST, TOP OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32819	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT CENTER OF EXHAUST, BOTTOM OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32820	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT CENTER OF EXHAUST, EAST SIDE OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32821	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT CENTER OF EXHAUST, WEST SIDE OF DUCT.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32822	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT PATCHING MATERIAL AT CENTER OF EXHAUST.	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32823	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT NORTH SIDE OF EXHAUST, BOTTOM OF DUCT (IN CLOSET).	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32824	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT EAST SIDE OF DUCT (IN THE CLOSET).	NON ASBESTOS SAMPLE DATE: 12/13/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 467
SURVEY #

ACILITY: WORLD TRADE CENTER
OCATION: KITCHEN EXHAUST DUCT, SOUTHEAST QUADRANT
AREA DESCRIPTION: 99TH FLOOR

BUILDING: 2
FLOOR: 99

SAMPLE NUMBER	LOCATION	RESULT
WTC-32825	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT NORTH SIDE OF DUCT (IN THE CLOSET).	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32826	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT INSULATION AT WEST SIDE OF DUCT (IN THE CLOSET).	NON ASBESTOS SAMPLE DATE: 12/13/91
WTC-32827	2 WTC 99TH FLOOR KITCHEN EXHAUST DUCT PATCHING MATERIAL AT NORTH SIDE (IN THE CLOSET).	NON ASBESTOS SAMPLE DATE: 12/13/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 468
SURVEY #

CILITY: WORLD TRADE CENTER
CATION: 15TH FLOOR
AREA DESCRIPTION: OFFICE AREA

BUILDING: 2
FLOOR:

SAMPLE NUMBER	LOCATION	RESULT
WTC-32522	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED AT THE SOUTHWEST CORNER.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91
WTC-32523	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED IN THE SOUTHEAST QUADRANT, ADJACENT TO WATER FOUNTAIN.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91
WTC-32524	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED IN THE NORTHEAST QUADRANT.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91
WTC-32525	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED IN THE NORTHWEST AREA INSIDE ROOM, ADJACENT TO WATER FOUNTAIN.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91
WTC-32526	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED CLOSE TO ENTRANCE DOOR, BY EXIT-B. NORTH SIDE.	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91
WTC-32527	BEIGE FLOOR TILE MATERIAL COLLECTED FROM A 1' X 1' TILE, LOCATED IN THE WEST SIDE (1ST OPEN ROOM, SAME SIDE TO EXIT-C).	1-3% CHRYSOTILE ASBESTOS SAMPLE DATE: 11/18/91

DRAFT COPY ISSUED 05/15/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 588
SURVEY # 001

CILITY: WORLD TRADE CENTER
CATION: PIT OF ELEVATOR # 1 & 2
AREA DESCRIPTION:

BUILDING: 2
FLOOR: B-2

SAMPLE NUMBER	LOCATION	RESULT
WTC-33056	CEMENTITIOUS FALLOUT MATERIAL COLLECTED FROM THE FLOOR IN THE PIT OF ELEVATOR # 1 & 2.	NON ASBESTOS SAMPLE DATE: 02/18/92
WTC-33057	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE FLOOR IN THE PIT OF THE ELEVATOR # 1 & 2.	NON ASBESTOS SAMPLE DATE: 02/18/92

DRAFT COPY ISSUED 05/18/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 679
SURVEY # 001

:ILITY: WORLD TRADE CENTER
.CATION: PIT OF ELEVATOR CAR # 1 & 2
AREA DESCRIPTION:

BUILDING: 2
FLOOR: B-2 LEVEL

SAMPLE NUMBER	LOCATION	RESULT
WTC-33056	CEMENTITIOUS FALLOUT MATERIAL COLLECTED FROM THE FLOOR IN THE PIT OF ELEVATOR # 1 & 2.	NON ASBESTOS SAMPLE DATE: 02/18/92
WTC-33057	FLUFFY FALLOUT MATERIAL COLLECTED FROM THE FLOOR IN THE PIT OF THE ELEVATOR # 1 & 2.	NON ASBESTOS SAMPLE DATE: 02/18/92

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 027

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-65

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25141	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE S/E CORNER OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 54TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25142	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM AN 18" BEAM LOCATED ON THE WEST WALL OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 50TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25143	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" COLUMN LOCATED ON THE S/E CORNER OF THE ELEVATOR SHAFT FOR CAR # 67, TOP OF 47TH FLOOR	5% CHRYSOTILE ASBESTOS
R-1WTC-25144	FLUFFY FALLOUT MATERIAL COLLECTED FROM TOP OF CAR # 67	5% CHRYSOTILE ASBESTOS

DRAFT COPY ISSUED 05/14/92

PORT AUTHORITY OF NY & NJ
ASBESTOS MANAGEMENT DIVISION
SAMPLE LOCATIONS

REPORT # 0
SURVEY # 028

FACILITY: WORLD TRADE CENTER
LOCATION:
AREA DESCRIPTION:

BUILDING: 1
FLOOR: 43-74

SAMPLE NUMBER	LOCATION	RESULT
R-1WTC-25160	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 69, TOP OF 74TH FLOOR	NON ASBESTOS
R-1WTC-25161	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 69, TOP OF 73RD FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25162	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE WEST WALL OF ELEVATOR SHAFT,FOR CAR # 69, TOP OF 70TH FLOOR	NON ASBESTOS
R-1WTC-25163	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT,FOR CAR # 69, TOP OF 68TH FLOOR	NON ASBESTOS
R-1WTC-25164	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 69, TOP OF 64TH FLOOR	NON ASBESTOS
R-1WTC-25165	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 69, TOP OF 60TH FLOOR	NON ASBESTOS
R-1WTC-25166	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 12" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 69, TOP OF 55TH FLOOR	NON ASBESTOS
R-1WTC-25167	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 16" BEAM LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT, FOR CAR # 69, TOP OF 50TH FLOOR	<1% CHRYSOTILE ASBESTOS
R-1WTC-25168	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 69, TOP OF 45TH FLOOR	<1% CHRYSOTILE ASBESTOS
R-1WTC-25169	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 19" COLUMN LOCATED ON THE S/W CORNER OF ELEVATOR SHAFT FOR CAR # 70, TOP OF 73RD FLOOR	2% CHRYSOTILE ASBESTOS
R-1WTC-25170	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 18" COLUMN LOCATED ON THE SOUTH SIDE OF ELEVATOR SHAFT FOR CAR # 70, TOP OF 69TH FLOOR	NON ASBESTOS
R-1WTC-25171	FLUFFY SPRAYED ON INSULATION MATERIAL COLLECTED FROM A 14" BEAM LOCATED ON THE EAST WALL OF ELEVATOR SHAFT, FOR CAR # 70, TOP OF 65TH FLOOR	2% CHRYSOTILE ASBESTOS

NOTE: The symbol "<" means: Less than. "TRACE" means a barely perceivable amount of asbestos that is less than the USEPA limit for asbestos.